

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Activity: 0520089</b>		<b>Type:</b> Building / Residential / New Building / Single Family		
<b>Parcel:</b> PARUNKN0000000	<b>Applied:</b> 12/31/2005	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>	
<b>Site Address:</b> 1718 MASTER PLAN		<b># Units:</b> 1.00	<b>Sq Ft:</b>	2,388
<b>Location:</b>				
<b>Description:</b> MP 1718 2 STORY 6 ROOM SFR				
<b>Contractor:</b> KIMBALL HILL HOMES				
<b>Occupancy:</b>	<b>Insp Area:</b>	<b>Activity Code:</b>		
<b>Valuation:</b> \$127,226.01	<b>Fees Req:</b> \$648.87	<b>Fees Col:</b>	<b>Bal Due:</b> \$648.87	

<b>Activity: 0520090</b>		<b>Type:</b> Building / Residential / New Building / Single Family		
<b>Parcel:</b> PARUNKN0000000	<b>Applied:</b> 12/31/2005	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>	
<b>Site Address:</b> 1653 MASTER PLAN		<b># Units:</b> 1.00	<b>Sq Ft:</b>	2,107
<b>Location:</b>				
<b>Description:</b> MP 1653 2 STORY 6 ROOM SFR				
<b>Contractor:</b> KIMBALL HILL HOMES				
<b>Occupancy:</b>	<b>Insp Area:</b>	<b>Activity Code:</b>		
<b>Valuation:</b> \$109,848.40	<b>Fees Req:</b> \$458.50	<b>Fees Col:</b>	<b>Bal Due:</b> \$458.50	

<b>Activity: 0520091</b>		<b>Type:</b> Building / Residential / New Building / Single Family		
<b>Parcel:</b> PARUNKN0000000	<b>Applied:</b> 12/31/2005	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>	
<b>Site Address:</b> 2200 MASTER PLAN		<b># Units:</b> 1.00	<b>Sq Ft:</b>	2,815
<b>Location:</b>				
<b>Description:</b> MP 2200 2 STORY 8 ROOM SFR				
<b>Contractor:</b> KIMBALL HILL HOMES				
<b>Occupancy:</b>	<b>Insp Area:</b>	<b>Activity Code:</b>		
<b>Valuation:</b> \$153,982.27	<b>Fees Req:</b> \$589.09	<b>Fees Col:</b>	<b>Bal Due:</b> \$589.09	

<b>Activity: 0520092</b>		<b>Type:</b> Building / Residential / New Building / Single Family		
<b>Parcel:</b> PARUNKN0000000	<b>Applied:</b> 12/31/2005	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>	
<b>Site Address:</b> 1709 MASTER PLAN		<b># Units:</b> 1.00	<b>Sq Ft:</b>	2,125
<b>Location:</b>				
<b>Description:</b> MP 1709 2 STORY 7 ROOM SFR				
<b>Contractor:</b> KIMBALL HILL HOMES				
<b>Occupancy:</b>	<b>Insp Area:</b>	<b>Activity Code:</b>		
<b>Valuation:</b> \$111,860.08	<b>Fees Req:</b> \$549.44	<b>Fees Col:</b>	<b>Bal Due:</b> \$549.44	

<b>Activity: COM-0813161</b>		<b>Type:</b> Building / Commercial / Housing Dept Permit / Apts 5+		
<b>Parcel:</b> 01003110190000	<b>Applied:</b> 10/01/2008	<b>Issued:</b> 12/31/2008	<b>Finalized:</b>	
<b>Site Address:</b> 2575 33RD ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>	6,039
<b>Location:</b>				
<b>Description:</b> 08-003058 ---Repairs per violations list. Repair existing stucco, replace glass at windows, reroof/overlay, Replace ground mounted HVAC, landscaping and fence repairs. Minor plumbing and electrical. Water heater c/o, gas. PG & E & SMUD SAFETY INSPECTION. Drywall repair.				
<b>Contractor:</b> QUALITY HOME CONSTRUCTION				
<b>Occupancy:</b> R2.1	<b>Insp Area:</b> 3	<b>Activity Code:</b> C4 HOUSING CASES		

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

Valuation: \$145,000.00	Fees Req: \$2,006.59	Fees Col: \$2,006.59	Bal Due: \$0.00
-------------------------	----------------------	----------------------	-----------------

<b>Activity: COM-0816042</b>		<b>Type:</b> Building / Ticket Permit Program / Remodel / Industrial	
Parcel: 00701230500000	Applied: 12/02/2008	Issued: 12/30/2008	Finalized:
Site Address: 3230 J ST		# Units: 0.00	Sq Ft: 30
Location:			
Description: INSTALL NEW HYDROGEN FUEL CABINET FOR "DC" POWERED BATTERY BACKUP TO EXISTING AT&T TELECOMMUNICATION FACILITY			
Contractor: MAXXIMUM LOGISTICS INC			
Occupancy: NA	Insp Area: 1	Activity Code: E10 ELEC EQUIPMENT INSTALL	
Valuation: \$38,000.00	Fees Req: \$1,665.92	Fees Col: \$1,665.92	Bal Due: \$0.00

<b>Activity: COM-0816369</b>		<b>Type:</b> Building / Commercial / Repair-Maintenance / Retail Store	
Parcel: 01300910190000	Applied: 12/08/2008	Issued: 12/29/2008	Finalized:
Site Address: 2830 FRANKLIN BLVD		# Units: 0.00	Sq Ft: 0
Location:			
Description: INSTALL NEW 499 GALLON PROPANE TANK WITH DISPENSER FOR RETAIL SALES			
Contractor: AMERIGAS PROPANE L P			
Occupancy: NA	Insp Area: 3	Activity Code: E6 TANKS	
Valuation: \$2,800.00	Fees Req: \$816.87	Fees Col: \$816.87	Bal Due: \$0.00

<b>Activity: COM-0816682</b>		<b>Type:</b> Building / Facilities Permit Program / Fire Equipment / Office	
Parcel: 00601530150000	Applied: 12/16/2008	Issued: 12/29/2008	Finalized:
Site Address: 770 L ST		# Units: 0.00	Sq Ft: 1,446
Location:			
Description: FPP PERMIT FOR FIRE ALARM FOR SUITE 850, RELACE PRE-ACTION SYSTEM AND CONNECT TO MAIN FIRE ALARM SYSTEM FOR MONITORING.			
Contractor: SIMPLEX GRINNELL L P			
Occupancy: B	Insp Area: 1	Activity Code: Z12 FIRE ALARM/SMOKE DET	
Valuation: \$10,877.86	Fees Req: \$0.00	Fees Col: \$0.00	Bal Due: \$0.00

<b>Activity: COM-0816937</b>		<b>Type:</b> Building / Commercial / Remodel / Office	
Parcel: 00400100310000	Applied: 12/23/2008	Issued: 12/30/2008	Finalized:
Site Address: 3301 C ST		# Units: 0.00	Sq Ft: 1,034
Location:			
Description: RELOCATE INTERIOR WALLS, LIGHTS, SWITCHES FOR NEW FLOOR PLAN OF A 1034 SQ FT OFFICE SPACE			
Contractor: CHAMPAS CONSTRUCTION COMPANY INC			
Occupancy: B	Insp Area: 1	Activity Code: I2 INTERIOR REM-TI/COM	
Valuation: \$23,876.00	Fees Req: \$1,139.33	Fees Col: \$1,139.33	Bal Due: \$0.00

<b>Activity: COM-0817092</b>		<b>Type:</b> Building / Commercial / Minor / Apts 5+	
Parcel: 04100140160000	Applied: 12/29/2008	Issued: 12/29/2008	Finalized: 12/30/2008
Site Address: 6800 WOODBINE AVE		# Units: 0.00	Sq Ft:
Location:			
Description: CHANGE OUT GAS 75 GAL WATER HEATER			
Contractor: PREFERRED PLUMBING			

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> P6 WATER HEATER	
<b>Valuation:</b> \$2,566.00	<b>Fees Req:</b> \$88.03	<b>Fees Col:</b> \$88.03	<b>Bal Due:</b> \$0.00

<b>Activity:</b> COM-0817095	<b>Type:</b> Building / Commercial / Remodel / Office		
<b>Parcel:</b> 00101120360000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>
<b>Site Address:</b> 1103 N B ST		<b># Units:</b> 0.00	<b>Sq Ft:</b> 100
<b>Location:</b>			
<b>Description:</b> INSTALLATION OF TWO NEW BRANCH CIRCUITS IN EXISTING ELECTRICAL PANEL			
<b>Contractor:</b> G P DEVELOPMENT			
<b>Occupancy:</b> B	<b>Insp Area:</b> 1	<b>Activity Code:</b> I2 INTERIOR REM-TI/COM	
<b>Valuation:</b> \$350.00	<b>Fees Req:</b> \$114.46	<b>Fees Col:</b> \$114.46	<b>Bal Due:</b> \$0.00

<b>Activity:</b> COM-0817098	<b>Type:</b> Building / Commercial / Minor / Apts 5+		
<b>Parcel:</b> 00901350060000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>
<b>Site Address:</b> 1122 T ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> C/O ROOF MOUNTED PACKAGE UNITS # 3 AND # 8 LIKE FOR LIKE			
<b>Contractor:</b> BREEZE MECHANICAL			
<b>Occupancy:</b> R1	<b>Insp Area:</b> 1	<b>Activity Code:</b> M1 HEATING/AIR CONDITION	
<b>Valuation:</b> \$8,044.64	<b>Fees Req:</b> \$335.50	<b>Fees Col:</b> \$335.50	<b>Bal Due:</b> \$0.00

<b>Activity:</b> COM-0817112	<b>Type:</b> Building / Commercial / Housing Dept Permit / Apts 3-4		
<b>Parcel:</b> 00702640140000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>
<b>Site Address:</b> 2531 P ST 1		<b># Units:</b> 0.00	<b>Sq Ft:</b> 1,000
<b>Location:</b>			
<b>Description:</b> 08-094245 --REPAIR OR REPLACE PLUMBING FIXTURES TUB/SHOWER VALVES & HANDLES; BATHROOM LAV WATER VALVES & HANDLES. UNDERFLOOR WIRING*** REMOVE ALL UNAPPROVED SUBSTANDARD WIRING FROM UNDERFLOOR AREA. REPAIR DAMAGED WALL FINISHES AT KITCHEN SINK AREA. BASEMENT FOUNDATION AND FRAMING ARE IN GOOD WORKING CONDITION PER ENGINEERS REPORT.			
<b>Contractor:</b> D DESIGN BUILD			
<b>Occupancy:</b> R2.1	<b>Insp Area:</b> 1	<b>Activity Code:</b> C4 HOUSING CASES	
<b>Valuation:</b> \$2,300.00	<b>Fees Req:</b> \$315.26	<b>Fees Col:</b> \$315.26	<b>Bal Due:</b> \$0.00

<b>Activity:</b> COM-0817132	<b>Type:</b> Building / Commercial / Minor / Apts 3-4		
<b>Parcel:</b> 01800210140000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 2221 15TH AVE		<b># Units:</b> 4.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> ***QUAD FEE*** REPAIR VANDALIZED WATER, GAS AND ELECTRICS, DRYROT IN 1ST FLOOR BATH, REPLACE WALL HEATERS, CHANGEOUT WET LOCATION RECEPTACLES TO GFCI. MINOR ROOF REPAIRS. QUAD FEE, WORK STARTED WITHOUT A PERMIT. STOP WORK NOTICE POSTED.			
<b>Contractor:</b>			
<b>Occupancy:</b> R2.1	<b>Insp Area:</b> 3	<b>Activity Code:</b> C1 GENERAL REPAIR/FIX-IT	
<b>Valuation:</b> \$7,999.00	<b>Fees Req:</b> \$815.44	<b>Fees Col:</b> \$815.44	<b>Bal Due:</b> \$0.00

<b>Activity:</b> COM-0817134	<b>Type:</b> Building / Commercial / Fire Equipment / Churches		
<b>Parcel:</b> 04800120050000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Site Address:</b> 2251 MEADOWVIEW RD	<b># Units:</b> 0.00	<b>Sq Ft:</b> 16
<b>Location:</b>		
<b>Description:</b> UL300 UPGRADE - HOOD & DUCT SUPPRESSION		
<b>Contractor:</b> SENTINEL FIRE EQUIPMENT COMPANY		
<b>Occupancy:</b> A2	<b>Insp Area:</b> 2	<b>Activity Code:</b> P11 FIRE HOOD SYSTEM
<b>Valuation:</b> \$3,500.00	<b>Fees Req:</b> \$344.81	<b>Fees Col:</b> \$344.81 <b>Bal Due:</b> \$0.00

<b>Activity:</b> COM-0817136	<b>Type:</b> Building / Commercial / Fire Equipment / Other Non-Housekeeping Shelter		
<b>Parcel:</b> 26501930090000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 1550 JULIESSE AVE	<b># Units:</b> 0.00	<b>Sq Ft:</b> 10	
<b>Location:</b>			
<b>Description:</b> UL300 UPGRADE - HOOD & DUCT SUPPRESSION			
<b>Contractor:</b> SENTINEL FIRE EQUIPMENT COMPANY			
<b>Occupancy:</b> R1	<b>Insp Area:</b> 4	<b>Activity Code:</b> P11 FIRE HOOD SYSTEM	
<b>Valuation:</b> \$3,500.00	<b>Fees Req:</b> \$344.58	<b>Fees Col:</b> \$344.58	<b>Bal Due:</b> \$0.00

<b>Activity:</b> COM-0817139	<b>Type:</b> Building / Commercial / Fire Equipment / Retail Store		
<b>Parcel:</b> 00800830010000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 5640 H ST	<b># Units:</b> 0.00	<b>Sq Ft:</b> 24.50	
<b>Location:</b>			
<b>Description:</b> UL300 UPGRADE - HOOD & DUCT SUPPRESSION			
<b>Contractor:</b> SENTINEL FIRE EQUIPMENT COMPANY			
<b>Occupancy:</b> M	<b>Insp Area:</b> 1	<b>Activity Code:</b> P11 FIRE HOOD SYSTEM	
<b>Valuation:</b> \$3,250.00	<b>Fees Req:</b> \$345.03	<b>Fees Col:</b> \$345.03	<b>Bal Due:</b> \$0.00

<b>Activity:</b> COM-0817147	<b>Type:</b> Building / Commercial / Housing Dept Permit / Apts 3-4		
<b>Parcel:</b> 26501510320000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 1637 KATHLEEN AVE	<b># Units:</b> 0.00	<b>Sq Ft:</b> 2,352	
<b>Location:</b>			
<b>Description:</b> 08-101077 --Fire damage repair. REMOVE ALL UNPERMITTED ADDITIONS. REPLACE ALL FIRE DAMAGED ELECTRICAL WIRING, PLUMBING FIXTURES, FIRE DAMAGED WATER LINES AND DRAIN, WASTE AND VENT LINES TO CURRENT STANDARDS. REPLACE OR REPAIR THE FIRE DAMAGED HEATING UNITS AND DUCTING. Water heater replacement. Tear-off, resheet, install 30 yr dim lam comp., 30 sq's, 1 story. Install cabinet countertops.			
<b>Contractor:</b> STORY DESIGN AND CONSTRUCTION INC			
<b>Occupancy:</b> R2.1	<b>Insp Area:</b> 4	<b>Activity Code:</b> C3 FIRE REPAIR	
<b>Valuation:</b> \$180,000.00	<b>Fees Req:</b> \$2,510.45	<b>Fees Col:</b> \$2,510.45	<b>Bal Due:</b> \$0.00

<b>Activity:</b> COM-0817163	<b>Type:</b> Building / Commercial / Housing-Minor / Apts 3-4		
<b>Parcel:</b> 02600710100000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 5640 53RD ST	<b># Units:</b> 1.00	<b>Sq Ft:</b>	
<b>Location:</b>			
<b>Description:</b> PERMIT FOR REPAIRS PER HOUSING VIOLATIONS LIST. ROOF REMOVE AND REPLACE. PLUMBING REPAIRS. ELECTRICAL REPAIRS AND REPLACE MAIN PANEL WITH 200 AMP SYSTEM. BUILDING REPAIR WINDOWS, TRIM AND STUCCO, REPLACE WATER HEATER.			
<b>Contractor:</b> COLOR PROS			
<b>Occupancy:</b> R2.1	<b>Insp Area:</b> 3	<b>Activity Code:</b> C4 HOUSING CASES	

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

Valuation: \$10,000.00	Fees Req: \$608.10	Fees Col: \$608.10	Bal Due: \$0.00
------------------------	--------------------	--------------------	-----------------

<b>Activity: COM-0817165</b>		<b>Type:</b> Building / Commercial / Minor / Apts 5+	
Parcel: 26603810220000	Applied: 12/30/2008	Issued: 12/30/2008	Finalized: 12/31/2008
Site Address: 2516 ALBATROSS WAY		# Units: 0.00	Sq Ft:
Location:			
Description: SMUD SAFETY INSPECTION			
Contractor:			
Occupancy: R3	Insp Area: 4	Activity Code: E11 SAFETY INSPECTION	
Valuation: \$0.00	Fees Req: \$83.00	Fees Col: \$83.00	Bal Due: \$0.00

<b>Activity: COM-0817170</b>		<b>Type:</b> Building / Commercial / Remodel / Office	
Parcel: 01000730080000	Applied: 12/30/2008	Issued: 12/30/2008	Finalized:
Site Address: 1936 STOCKTON BLVD		# Units: 0.00	Sq Ft: 0
Location:			
Description: ADD DUCTING TO EXISTING HVAC SYSTEM			
Contractor:			
Occupancy: NA	Insp Area: 3	Activity Code: M4 DUCT WORK	
Valuation: \$800.00	Fees Req: \$114.32	Fees Col: \$114.32	Bal Due: \$0.00

<b>Activity: COM-0817176</b>		<b>Type:</b> Building / Commercial / Minor / Industrial	
Parcel: 26602710100000	Applied: 12/30/2008	Issued: 12/30/2008	Finalized:
Site Address: 1604 AUBURN BLVD		# Units: 0.00	Sq Ft:
Location:			
Description: HEATPUMP CHANGEOUT. ENERGY DOCUMENTS DUE AT FINAL.			
Contractor: ALLYEAR			
Occupancy: F1	Insp Area: 4	Activity Code: M1 HEATING/AIR CONDITION	
Valuation: \$7,000.00	Fees Req: \$205.80	Fees Col: \$205.80	Bal Due: \$0.00

<b>Activity: COM-0817178</b>		<b>Type:</b> Building / Commercial / Remodel / Apts 5+	
Parcel: 00201760150000	Applied: 12/30/2008	Issued: 01/02/2009	Finalized:
Site Address: 1715 H ST		# Units: 0.00	Sq Ft: 0
Location:			
Description: Replace windows in units 3-6, Replace old meters & service w/new 400 amp service, replace 2 water heaters, add dedicated circuits for bathrooms, install 2 mini-split HVAC system in each units, install exhaust fan in each unit (6), and replace stairs & railings.			
Contractor:			
Occupancy: R2.2	Insp Area: 1	Activity Code: C1 GENERAL REPAIR/FIX-IT	
Valuation: \$65,000.00	Fees Req: \$1,166.42	Fees Col: \$1,166.42	Bal Due: \$0.00

<b>Activity: COM-0817197</b>		<b>Type:</b> Building / Commercial / Repair-Maintenance / Retail Store	
Parcel: 01002410160000	Applied: 12/31/2008	Issued: 12/31/2008	Finalized:
Site Address: 2721 BROADWAY		# Units: 0.00	Sq Ft: 0
Location:			
Description: REPLACEMENT OF 40' OF SEWER LINE			

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

**Contractor:** ROONEY'S PLUMBING CO

**Occupancy:** A3

**Insp Area:** 1

**Activity Code:** C1 GENERAL REPAIR/FIX-IT

**Valuation:** \$1,250.00

**Fees Req:** \$126.98

**Fees Col:** \$126.98

**Bal Due:** \$0.00

**Activity:** COM-0817212

**Type:** Building / Commercial / Minor / Retail Store

**Parcel:** 00801320050000

**Applied:** 12/31/2008

**Issued:** 01/02/2009

**Finalized:**

**Site Address:** 3754 J ST

**# Units:** 0.00

**Sq Ft:**

**Location:**

**Description:** CHANGE OUT 40 GALLON GAS WATER HEATER

**Contractor:** BONNEY PLUMBING & ROOTER SERVICE

**Occupancy:** M

**Insp Area:** 1

**Activity Code:** P6 WATER HEATER

**Valuation:** \$1,990.00

**Fees Req:** \$85.80

**Fees Col:** \$85.80

**Bal Due:** \$0.00

**Activity:** COM-0900024

**Type:** Building / Commercial / Repair-Maintenance / Retail Store

**Parcel:** 04802500250000

**Applied:** 01/02/2009

**Issued:** 01/02/2009

**Finalized:**

**Site Address:** 1441 MEADOWVIEW RD

**# Units:** 0.00

**Sq Ft:** 1,050

**Location:**

**Description:** INSTALL MOP SINK AND REPLACE 10 GAL ELECTRIC WATER HEATER SUITE #108

**Contractor:** FONG KEVIN

**Occupancy:** M

**Insp Area:** 2

**Activity Code:** C1 GENERAL REPAIR/FIX-IT

**Valuation:** \$2,500.00

**Fees Req:** \$280.16

**Fees Col:** \$280.16

**Bal Due:** \$0.00

**Activity:** COM-0900028

**Type:** Building / Commercial / Minor / Apts 3-4

**Parcel:** 00301720140000

**Applied:** 01/02/2009

**Issued:** 01/02/2009

**Finalized:**

**Site Address:** 1831 H ST

**# Units:** 0.00

**Sq Ft:**

**Location:**

**Description:** REPLACE 50' OF 4" CAST IRON TO 4" ABS

**Contractor:** J W HARRIS PLUMBING & ROOTER

**Occupancy:** R3

**Insp Area:** 1

**Activity Code:** P12 WTR & SWR SERVICE

**Valuation:** \$400.00

**Fees Req:** \$84.16

**Fees Col:** \$84.16

**Bal Due:** \$0.00

**Activity:** RES-0811835

**Type:** Building / Residential / Housing-Minor / Single Family

**Parcel:** 02000150260000

**Applied:** 09/02/2008

**Issued:** 09/02/2008

**Finalized:**

**Site Address:** 3737 32ND ST

**# Units:** 0.00

**Sq Ft:**

**Location:**

**Description:** SMUD SAFETY INSPECTION. CONVERT GARAGE TO ORIGINAL STATE. OK PER GREG JOHNSON TO REOPEN PERMIT FOR FINAL INSPECTION 12/29/08

**Contractor:**

**Occupancy:** R3

**Insp Area:** 3

**Activity Code:** E11 SAFETY INSPECTION

**Valuation:** \$999.00

**Fees Req:** \$233.50

**Fees Col:** \$233.50

**Bal Due:** \$0.00

**Activity:** RES-0811835

**Type:** Building / Residential / Housing-Minor / Single Family

**Parcel:** 02000150260000

**Applied:** 09/02/2008

**Issued:** 09/02/2008

**Finalized:**

**Site Address:** 3737 32ND ST

**# Units:** 0.00

**Sq Ft:**

**Location:**



**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Site Address:</b> 2836 DEL PASO BLVD	<b># Units:</b> 1.00	<b>Sq Ft:</b>	
<b>Location:</b>			
<b>Description:</b> ***QUAD FEE*** TEAR OFF RESHEATH AND REROOF 1-STORY SFD. 18 SQ. WITH 30 YR D.C. IN PROGRESS INSPECTION REQUIRED, BUT SKIPPED. NEW CUT-INHVAC, RECEPTACLE CHANGEOUTS. QUAD FEE, WORK STARTED WITHOUT A PERMIT. STOP WORK NOTICE POSTED.			
<b>Contractor:</b>			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> R1 REROOF	
<b>Valuation:</b> \$19,000.00	<b>Fees Req:</b> \$1,432.22	<b>Fees Col:</b> \$1,432.22	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0816823	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 29501000120000	<b>Applied:</b> 12/19/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b> 01/02/2009
<b>Site Address:</b> 611 ELMHURST CIR	<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>			
<b>Description:</b> HVAC CHANGE-OUT. SPLIT SYSTEM.			
<b>Contractor:</b> GARICK AIR CONDITIONING SERVICE			
<b>Occupancy:</b> R1	<b>Insp Area:</b> 1	<b>Activity Code:</b> M1 HEATING/AIR CONDITION	
<b>Valuation:</b> \$12,831.00	<b>Fees Req:</b> \$220.13	<b>Fees Col:</b> \$220.13	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0816840	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 29502800150000	<b>Applied:</b> 12/19/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>
<b>Site Address:</b> 116 HARTNELL PL	<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>			
<b>Description:</b> HVAC CHANGE-OUT. SPLIT SYSTEM.			
<b>Contractor:</b> BERKAN & CLARK HEATING & AIR			
<b>Occupancy:</b> R1	<b>Insp Area:</b> 1	<b>Activity Code:</b> M1 HEATING/AIR CONDITION	
<b>Valuation:</b> \$7,441.00	<b>Fees Req:</b> \$207.98	<b>Fees Col:</b> \$207.98	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0816843	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 01202530190000	<b>Applied:</b> 12/19/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>
<b>Site Address:</b> 3161 16TH ST	<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>			
<b>Description:</b> HVAC CUT-IN. SPLIT SYSTEM.			
<b>Contractor:</b> BERKAN & CLARK HEATING & AIR			
<b>Occupancy:</b> R1	<b>Insp Area:</b> 2	<b>Activity Code:</b> M1 HEATING/AIR CONDITION	
<b>Valuation:</b> \$11,560.00	<b>Fees Req:</b> \$217.62	<b>Fees Col:</b> \$217.62	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0816848	<b>Type:</b> Building / Residential / Housing-Minor / Single Family		
<b>Parcel:</b> 27701310120000	<b>Applied:</b> 12/19/2008	<b>Issued:</b> 12/19/2008	<b>Finalized:</b>
<b>Site Address:</b> 2258 EMPRESS ST	<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>			
<b>Description:</b> 06-018989 --Repairs per violations list. Roof repair, repair leaking p-trap. Provide room heaters. Identify all breakers. Stair case treads.			
<b>Contractor:</b>			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> C4 HOUSING CASES	
<b>Valuation:</b> \$2,900.00	<b>Fees Req:</b> \$315.26	<b>Fees Col:</b> \$315.26	<b>Bal Due:</b> \$0.00



**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Activity: RES-0816848</b>		<b>Type:</b> Building / Residential / Housing-Minor / Single Family	
<b>Parcel:</b> 27701310120000	<b>Applied:</b> 12/19/2008	<b>Issued:</b> 12/19/2008	<b>Finalized:</b>
<b>Site Address:</b> 2258 EMPRESS ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> 06-018989 --Repairs per violations list. Roof repair, repair leaking p-trap. Provide room heaters. Identify all breakers. Stair case treads.			
<b>Contractor:</b>			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> C4 HOUSING CASES	
<b>Valuation:</b> \$2,900.00	<b>Fees Req:</b> \$315.26	<b>Fees Col:</b> \$315.26	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0816848</b>		<b>Type:</b> Building / Residential / Housing-Minor / Single Family	
<b>Parcel:</b> 27701310120000	<b>Applied:</b> 12/19/2008	<b>Issued:</b> 12/19/2008	<b>Finalized:</b>
<b>Site Address:</b> 2258 EMPRESS ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> 06-018989 --Repairs per violations list. Roof repair, repair leaking p-trap. Provide room heaters. Identify all breakers. Stair case treads.			
<b>Contractor:</b>			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> C4 HOUSING CASES	
<b>Valuation:</b> \$2,900.00	<b>Fees Req:</b> \$315.26	<b>Fees Col:</b> \$315.26	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0816872</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 02904230040000	<b>Applied:</b> 12/22/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 7028 13TH ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> REROOF. TEAR-OFF, RESHEET. 30 YEAR COMP.			
<b>Contractor:</b> CAL - VINTAGEROOFING CO INC			
<b>Occupancy:</b> R1	<b>Insp Area:</b> 2	<b>Activity Code:</b> R1 REROOF	
<b>Valuation:</b> \$16,000.00	<b>Fees Req:</b> \$229.00	<b>Fees Col:</b> \$229.00	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0816922</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 02702280100000	<b>Applied:</b> 12/23/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 5853 68TH ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> HVAC CHANGE-OUT. GROUND MOUNT.			
<b>Contractor:</b> NEW - CENTURY AIR SYSTEMS			
<b>Occupancy:</b> R1	<b>Insp Area:</b> 3	<b>Activity Code:</b> M1 HEATING/AIRCONDITION	
<b>Valuation:</b> \$11,680.00	<b>Fees Req:</b> \$217.67	<b>Fees Col:</b> \$217.67	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0816970</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 27702110130000	<b>Applied:</b> 12/23/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>
<b>Site Address:</b> 1840 JAMESTOWN DR		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> HVAC C/O ROOF MOUNT. PROVIDE ALL DOCUMENTS FOR FINAL INSPECTION. SMOKE DETECTORS REQUIRED			
<b>Contractor:</b> BERKAN & CLARK HEATING & AIR			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> M2 HEATPUMP	
<b>Valuation:</b> \$8,365.00	<b>Fees Req:</b> \$210.35	<b>Fees Col:</b> \$210.35	<b>Bal Due:</b> \$0.00

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Activity: RES-0816971</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 01200230060000	<b>Applied:</b> 12/23/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>
<b>Site Address:</b> 2720 13TH ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> PG&E METER MOVE			
<b>Contractor:</b> ALLSTATEPLUMBING HEATING & COOLING			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> P5 GAS TEST/LINE REPAIR	
<b>Valuation:</b> \$999.00	<b>Fees Req:</b> \$83.40	<b>Fees Col:</b> \$83.40	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0816972</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 01501820160000	<b>Applied:</b> 12/23/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b> 12/30/2008
<b>Site Address:</b> 4942 10TH AVE		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> PG&E METER MOVE			
<b>Contractor:</b> ALLSTATEPLUMBING HEATING & COOLING			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> P5 GAS TEST/LINE REPAIR	
<b>Valuation:</b> \$999.00	<b>Fees Req:</b> \$83.40	<b>Fees Col:</b> \$83.40	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0816982</b>		<b>Type:</b> Building / Residential / Minor / Duplex	
<b>Parcel:</b> 00501820110000	<b>Applied:</b> 12/24/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b> 12/31/2008
<b>Site Address:</b> 523 MESSINA DR		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> SEWER LINE REPLACEMENT			
<b>Contractor:</b> ROONEY'S PLUMBING CO			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> P2 SEWER SERVICE	
<b>Valuation:</b> \$1,170.00	<b>Fees Req:</b> \$85.47	<b>Fees Col:</b> \$85.47	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0816984</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 04802410110000	<b>Applied:</b> 12/24/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>
<b>Site Address:</b> 2145 ONEIL WAY		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> REROOF, 1 STORY SFR 16 SQUARES, TEAR-OFF, APPLY 30 YR DIM COMP			
<b>Contractor:</b> ROOFING COMPANY THE			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> R1 REROOF	
<b>Valuation:</b> \$5,000.00	<b>Fees Req:</b> \$201.50	<b>Fees Col:</b> \$201.50	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0816997</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 01202240200000	<b>Applied:</b> 12/26/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b> 12/31/2008
<b>Site Address:</b> 1817 BIDWELL WAY		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> T/O RESHEET 1 STORY 10 SQ'S 30 YR COMP. IN PROGRESS INSPECTION REQUIRED.			
<b>Contractor:</b> HOLMES & SON CONTRACTING			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> R1 REROOF	
<b>Valuation:</b> \$5,000.00	<b>Fees Req:</b> \$107.00	<b>Fees Col:</b> \$107.00	<b>Bal Due:</b> \$0.00

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Activity: RES-0817005</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 00300940170000	<b>Applied:</b> 12/26/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>	
<b>Site Address:</b> 2521 D ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> TRENCHLESS SEWER LINE REPLACEMENT				
<b>Contractor:</b> ACE PLUMBING HEATING & AIR				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> P12 WTR & SWR SERVICE		
<b>Valuation:</b> \$5,700.00	<b>Fees Req:</b> \$95.28	<b>Fees Col:</b> \$95.28	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0817019</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 00703720420000	<b>Applied:</b> 12/26/2008	<b>Issued:</b> 12/31/2008	<b>Finalized:</b>	
<b>Site Address:</b> 1617 36TH ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> BATHROOM REMODEL INCLUDING MOVING TOILET INTO WHAT IS CURRENTLY A CLOSET, SO MOVING WASTE LINE AND SUPPLY LINE. WILL DO AT SAME TIME AS WHOLE HOUSE RE PLUMBING.				
<b>Contractor:</b>				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> I1 INTERIOR REM-RES		
<b>Valuation:</b> \$15,000.00	<b>Fees Req:</b> \$459.36	<b>Fees Col:</b> \$459.36	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0817026</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 07801440130000	<b>Applied:</b> 12/26/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>	
<b>Site Address:</b> 2921 CHIPLAY ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> HVAC C/O SPLIT SYSTEM. PROVIDE ALL DOCUMENTS FOR FINAL INSPECTION. SMOKE DETECTORS REQUIRED.				
<b>Contractor:</b> BELL BROTHER'S HEATING AND AIR INC				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> M1 HEATING/AIR CONDITION		
<b>Valuation:</b> \$6,100.00	<b>Fees Req:</b> \$205.44	<b>Fees Col:</b> \$205.44	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0817080</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 03005300740000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>	
<b>Site Address:</b> 6784 LANGSTON WAY		<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> reroof, t/o, resheet, install 30 sq's of 30 yr. dim lam comp and replace gutters				
<b>Contractor:</b>				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> R1 REROOF		
<b>Valuation:</b> \$7,500.00	<b>Fees Req:</b> \$208.75	<b>Fees Col:</b> \$208.75	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0817081</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 00500630220000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>	
<b>Site Address:</b> 5243 MINERVA AVE		<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> REROOF, T/O, INSTALL 20 SQ'S 30 YR CLASS "A" DIM LAM COMP ROOF AND BUR ON LOW PITCH AREA.				
<b>Contractor:</b> LAKEHILLS ROOFING COMPANY				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> R1 REROOF		
<b>Valuation:</b> \$6,685.00	<b>Fees Req:</b> \$206.34	<b>Fees Col:</b> \$206.34	<b>Bal Due:</b> \$0.00	

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Activity: RES-0817082</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 01201610130000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>	
<b>Site Address:</b> 728 4TH AVE		<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> REPLACE 35' SEWER LINE				
<b>Contractor:</b> ROONEY'S PLUMBING CO				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> P2 SEWER SERVICE		
<b>Valuation:</b> \$1,500.00	<b>Fees Req:</b> \$85.60	<b>Fees Col:</b> \$85.60	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0817083</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 03803450100000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>	
<b>Site Address:</b> 10 BLUESTONE CT		<b># Units:</b> 1.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> HVAC SPLIT SYSTEM CHANGEOUT. ENERGY DOCUMENTS DUE AT FINAL. SMOKE DETECTORS REQUIRED.				
<b>Contractor:</b> ACE PLUMBING HEATING & AIR				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> M1 HEATING/AIR CONDITION		
<b>Valuation:</b> \$6,988.00	<b>Fees Req:</b> \$205.80	<b>Fees Col:</b> \$205.80	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0817084</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 25003050040000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>	
<b>Site Address:</b> 69 FAIRBANKS AVE		<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> CHANGE OUT GAS 30 GAL WATER HEATER, REPLACE GASLINE FROM METER AND HOUSE AND TO 2ND STOVE.				
<b>Contractor:</b> PREFERRED PLUMBING				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> P6 WATER HEATER		
<b>Valuation:</b> \$3,560.00	<b>Fees Req:</b> \$90.42	<b>Fees Col:</b> \$90.42	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0817086</b>		<b>Type:</b> Building / Residential / Minor / Half Plex		
<b>Parcel:</b> 03108100750000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>	
<b>Site Address:</b> 775 PORTUGAL WAY		<b># Units:</b> 1.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> TEAR OFF, RESHEATH AND REROOF 1-STORY 1/2 PLEX. 21 SQ. WITH 30 YR D.C. IN PROGRESS INSPECTION REQUIRED.				
<b>Contractor:</b> F X ROOFING CO				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> R1 REROOF		
<b>Valuation:</b> \$6,497.00	<b>Fees Req:</b> \$206.25	<b>Fees Col:</b> \$206.25	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0817087</b>		<b>Type:</b> Building / Residential / New Building / Private Garage		
<b>Parcel:</b> 20104700040000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>	
<b>Site Address:</b> 5511 NORTHBOROUGH DR		<b># Units:</b> 0.00	<b>Sq Ft:</b>	224
<b>Location:</b>				
<b>Description:</b> NEW DETACHED 224 SF DETACHED STORAGE SHED WITH ELECTRICAL				
<b>Contractor:</b>				
<b>Occupancy:</b> U1	<b>Insp Area:</b> 4	<b>Activity Code:</b> B3 STORAGE SHED		
<b>Valuation:</b> \$5,443.20	<b>Fees Req:</b> \$409.25	<b>Fees Col:</b> \$409.25	<b>Bal Due:</b> \$0.00	

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Activity: RES-0817088</b>		<b>Type:</b> Building / Residential / Minor / Half Plex		
<b>Parcel:</b> 03108100760000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>	
<b>Site Address:</b> 7361 SOUZA CIR		<b># Units:</b> 2.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> TEAR OFF, RESHEATH AND REROOF 1-STORY HALFPLEX. 21 SQ. WITH 30 YR D.C. IN PROGRESS INSPECTION REQUIRED.				
<b>Contractor:</b> F X ROOFING CO				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> R1 REROOF		
<b>Valuation:</b> \$6,497.00	<b>Fees Req:</b> \$206.25	<b>Fees Col:</b> \$206.25	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0817090</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 07901040010000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>	
<b>Site Address:</b> 8200 CITADEL WAY		<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> KITCHEN REMODEL UPDATE PLUMBING, ELECTRICAL, ADD GAS LINE FOR STOVE. NEW CABINETS, SHEETROCK, UPDATE ELECTRICAL IN FAMILYROOM, REPLACE WATER LINE FROM CITY TO HOUSE				
<b>Contractor:</b>				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> I1 INTERIOR REM-RES		
<b>Valuation:</b> \$8,500.00	<b>Fees Req:</b> \$414.13	<b>Fees Col:</b> \$414.13	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0817093</b>		<b>Type:</b> Building / Residential / Housing-Minor / Single Family		
<b>Parcel:</b> 26301410210000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>	
<b>Site Address:</b> 2711 OAKMONT ST		<b># Units:</b> 1.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> PERMIT FOR REPAIR OF HOUSING VIOLATION LIST. REPAIRS TO PLUMBING, ELECTRICAL, WINDOW IN GARAGE LIKE FOR LIKE OR STUCCO...OK PER DESIGN & REVIEW, HOUSE WINDOWS ALSO OK PER DESIGN AND REVIEW. ROOF WAS PERMITTED 7/15/04 PERMIT # 0411359.				
<b>Contractor:</b>				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> C4 HOUSING CASES		
<b>Valuation:</b> \$999.99	<b>Fees Req:</b> \$593.14	<b>Fees Col:</b> \$593.14	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0817094</b>		<b>Type:</b> Building / Residential / Housing-Minor / Single Family		
<b>Parcel:</b> 01402730050000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>	
<b>Site Address:</b> 4232 12TH AVE		<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> 06-002643---Kitchen and bathroom remodel, new water heater and electrical added. Install 30yr dim lam comp, 15 sq's, 1 story. Install new grided windows.				
<b>Contractor:</b>				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> C4 HOUSING CASES		
<b>Valuation:</b> \$999.00	<b>Fees Req:</b> \$233.90	<b>Fees Col:</b> \$233.90	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0817096</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 01201030100000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finalized:</b>	
<b>Site Address:</b> 2792 RIVERSIDE BLVD		<b># Units:</b> 1.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> ***QUAD FEE*** KITCHEN REMODEL WITH ANCILLARY PLUMBING AND ELECTRICAL. QUAD FEE, WORK STARTED WITHOUT A PERMIT. STOP WORK NOTICE POSTED.				

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Contractor:</b>			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> I1 INTERIOR REM-RES	
<b>Valuation:</b> \$3,999.00	<b>Fees Req:</b> \$271.32	<b>Fees Col:</b> \$271.32	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817097		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 01201610290000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finaled:</b> 01/02/2009
<b>Site Address:</b> 617 SWANSTON DR		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> TRENCHLESS REPLACEMENT OF SEWER LINE			
<b>Contractor:</b> ROTO - ROOTER PLUMBERS			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> P2 SEWER SERVICE	
<b>Valuation:</b> \$9,637.72	<b>Fees Req:</b> \$104.86	<b>Fees Col:</b> \$104.86	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817099		<b>Type:</b> Building / Residential / Repair-Maintenance / Single Family	
<b>Parcel:</b> 01201610170000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finaled:</b>
<b>Site Address:</b> 780 4TH AVE		<b># Units:</b> 1.00	<b>Sq Ft:</b> 0
<b>Location:</b>			
<b>Description:</b> REMOVE AND REPLACE REAR STAIRWITH SPIRAL STEEL STAIR.			
<b>Contractor:</b> SIERRA STAIRCO INC			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> C1 GENERAL REPAIR/FIX-IT	
<b>Valuation:</b> \$5,000.00	<b>Fees Req:</b> \$363.66	<b>Fees Col:</b> \$363.66	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817100		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 11801710020000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finaled:</b>
<b>Site Address:</b> 4841 SCARBOROUGH WAY		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> TEAR OFF, INSTALLATION OF 27 SQ'S 30 YR DIM LAM COMP			
<b>Contractor:</b> CISCO'S ROOFING			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> R1 REROOF	
<b>Valuation:</b> \$5,500.00	<b>Fees Req:</b> \$203.75	<b>Fees Col:</b> \$203.75	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817101		<b>Type:</b> Building / Residential / Minor / Duplex	
<b>Parcel:</b> 03601530100000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finaled:</b> 12/30/2008
<b>Site Address:</b> 6717 27TH ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> C/O TWO 100 AMP ELECTRICAL PANELS FOR DUPLEX 6717/6721 27TH ST			
<b>Contractor:</b> SAM'S ELECTRIC			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> E2 ELEC SERVICE CHANGE	
<b>Valuation:</b> \$2,000.00	<b>Fees Req:</b> \$85.80	<b>Fees Col:</b> \$85.80	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817102		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 02302460110000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finaled:</b>
<b>Site Address:</b> 5503 62ND ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

**Description:** REROOF T/O INSTALL 14 SQRS 30 YR DIM COMP - INPROGRESS INSPECTION REQUIRED

**Contractor:**

**Occupancy:** R3

**Insp Area:** 3

**Activity Code:** R1 REROOF

**Valuation:** \$2,500.00

**Fees Req:** \$195.50

**Fees Col:** \$195.50

**Bal Due:** \$0.00

**Activity:** RES-0817103

**Type:** Building / Residential / Minor / Single Family

**Parcel:** 008017110100000

**Applied:** 12/29/2008

**Issued:** 12/29/2008

**Finalized:**

**Site Address:** 5281 K ST

**# Units:** 0.00

**Sq Ft:**

**Location:**

**Description:** REMODEL BATHROOM, REPAIR DRYROT IN OTHER BATHROOM, REWIRE HOUSE (WHERE UNGROUNDED CIRCUITS)REPAIR HVAC

**Contractor:** DYERCONSTRUCTION INC

**Occupancy:** R3

**Insp Area:** 1

**Activity Code:** I1 INTERIOR REM-RES

**Valuation:** \$15,000.00

**Fees Req:** \$460.86

**Fees Col:** \$460.86

**Bal Due:** \$0.00

**Activity:** RES-0817104

**Type:** Building / Residential / Minor / Single Family

**Parcel:** 01200350020000

**Applied:** 12/29/2008

**Issued:** 12/29/2008

**Finalized:**

**Site Address:** 2704 17TH ST

**# Units:** 1.00

**Sq Ft:**

**Location:**

**Description:** TEAR OFF,RESHEATH AND REROOF 1-STORY SFD. 18 SQ. WITH 30 YR D.C. IN PROGRESS INSPECTION REQUIRED.

**Contractor:** CERTIFIED ROOFING COMPANY

**Occupancy:** R3

**Insp Area:** 2

**Activity Code:** R1 REROOF

**Valuation:** \$6,600.00

**Fees Req:** \$206.30

**Fees Col:** \$206.30

**Bal Due:** \$0.00

**Activity:** RES-0817106

**Type:** Building / Residential / Minor / Single Family

**Parcel:** 00800910240000

**Applied:** 12/29/2008

**Issued:** 12/29/2008

**Finalized:**

**Site Address:** 961 MISSION WAY

**# Units:** 0.00

**Sq Ft:**

**Location:**

**Description:** INSTALLATION OF PEDESTAL MAIN SERVICE FOR IRRIGATION TIMER AND COMMON LIGHTING

**Contractor:** DYERCONSTRUCTION INC

**Occupancy:** U1

**Insp Area:** 1

**Activity Code:** E10 ELEC EQUIPMENT INSTALL

**Valuation:** \$1,000.00

**Fees Req:** \$83.40

**Fees Col:** \$83.40

**Bal Due:** \$0.00

**Activity:** RES-0817107

**Type:** Building / Residential / Minor / Single Family

**Parcel:** 26200540100000

**Applied:** 12/29/2008

**Issued:** 12/30/2008

**Finalized:**

**Site Address:** 612 POTOMAC AVE

**# Units:** 1.00

**Sq Ft:**

**Location:**

**Description:** PEST REPAIR, DRYWALL, MINOR ELEC., PLUMBING.

**Contractor:**

**Occupancy:** R3

**Insp Area:** 4

**Activity Code:** C6 TERMITE/DRY ROT REPAIR

**Valuation:** \$2,800.00

**Fees Req:** \$246.26

**Fees Col:** \$246.26

**Bal Due:** \$0.00

**Activity:** RES-0817108

**Type:** Building / Residential / Housing-Minor / Single Family

**Parcel:** 01502410260000

**Applied:** 12/29/2008

**Issued:** 12/29/2008

**Finalized:**

**Site Address:** 4825 12TH AVE

**# Units:** 1.00

**Sq Ft:**

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Location:</b>			
<b>Description:</b> PERMIT ISSUED TO COMPLETE WORK ON PRIOR PERMIT TO REPAIRSON THE HOUSING VIOLATION LIST			
<b>Contractor:</b>			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> C4 HOUSING CASES	
<b>Valuation:</b> \$999.99	<b>Fees Req:</b> \$269.14	<b>Fees Col:</b> \$269.14	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817109		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 11709200530000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/30/2008	<b>Finald:</b>
<b>Site Address:</b> 8591 BRENTWICK WAY		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> W/H CHANGE OUT GAS			
<b>Contractor:</b> LOZANO MIKE JOHN			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> P6 WATER HEATER	
<b>Valuation:</b> \$695.00	<b>Fees Req:</b> \$83.28	<b>Fees Col:</b> \$83.28	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817110		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 02103510350000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/30/2008	<b>Finald:</b> 01/05/2009
<b>Site Address:</b> 7667 20TH AVE		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> WATER HEATER CHANGE OUT GAS			
<b>Contractor:</b> LOZANO MIKE JOHN			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> P6 WATER HEATER	
<b>Valuation:</b> \$805.00	<b>Fees Req:</b> \$83.32	<b>Fees Col:</b> \$83.32	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817111		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 03502210190000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finald:</b> 12/30/2008
<b>Site Address:</b> 6745 PENDLETON ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> SMUD SAFETY INSPECTION ONLY - NO WORK			
<b>Contractor:</b>			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> E11 SAFETY INSPECTION	
<b>Valuation:</b> \$0.00	<b>Fees Req:</b> \$83.00	<b>Fees Col:</b> \$83.00	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817113		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 11709901090000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finald:</b> 12/31/2008
<b>Site Address:</b> 3 FERNCLIFF CT		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> REPAIR 100 AMP MAIN ELECTRICAL PANEL REPLACE BURNT BUSS BARS AND MAIN BREAKER			
<b>Contractor:</b> A AND A ELECTRIC			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> E1 SERVICE REPAIR	
<b>Valuation:</b> \$650.00	<b>Fees Req:</b> \$83.26	<b>Fees Col:</b> \$83.26	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817114		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 25003210100000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/29/2008	<b>Finald:</b>



**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Site Address:</b> 220 SILVER EAGLE RD	<b># Units:</b> 1.00	<b>Sq Ft:</b>	
<b>Location:</b>			
<b>Description:</b> ***QUAD FEE*** BATH REMODEL, QUAD FEE, WORK STARTED WITHOUT A PERMIT. STOP WORK NOTICE POSTED. NON-QUAD FEE WORK: REPLACE VANDALIZED WATER HEATER, REROOF, LAY-OVER 18 SQ WITH 30 YR DIMENSIONAL COMP. OPEN WATER HEATER PERMIT RES-0815388 UNDER RISSE MECHANICAL TO BE VOIDED AFTER ISSUANCE.			
<b>Contractor:</b>			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> I1 INTERIOR REM-RES	
<b>Valuation:</b> \$10,400.00	<b>Fees Req:</b> \$563.04	<b>Fees Col:</b> \$563.04	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817129	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 22507740130000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b> 12/31/2008
<b>Site Address:</b> 2896 CANDIDO DR	<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>			
<b>Description:</b> REPLUMP GAS LINE TO KITCHEN STOVE			
<b>Contractor:</b> PLUMBING THERAPIST THE			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> P5 GAS TEST/LINE REPAIR	
<b>Valuation:</b> \$1,450.00	<b>Fees Req:</b> \$85.58	<b>Fees Col:</b> \$85.58	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817133	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 02900610050000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 6936 S LAND PARK DR	<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>			
<b>Description:</b> TEAR OFF / REROOF W/ 30YR COMP. (IN PROGRESS INSPECTION)			
<b>Contractor:</b> EXCELLENCE IN ROOFING			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> R1 REROOF	
<b>Valuation:</b> \$7,000.00	<b>Fees Req:</b> \$206.50	<b>Fees Col:</b> \$206.50	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817135	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 03111500530000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/31/2008	<b>Finalized:</b>
<b>Site Address:</b> 673 HONEY WAY	<b># Units:</b> 1.00	<b>Sq Ft:</b>	
<b>Location:</b>			
<b>Description:</b> TEAR OFF, RESHEATH AND REROOF 1-STORY SFD. 33 SQ. WITH 30 YR D.C. IN PROGRESS INSPECTION REQUIRED.			
<b>Contractor:</b> ROOFING COMPANY THE			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> R1 REROOF	
<b>Valuation:</b> \$9,000.00	<b>Fees Req:</b> \$211.50	<b>Fees Col:</b> \$211.50	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817137	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 27402900070000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b> 12/31/2008
<b>Site Address:</b> 3063 SWALLOWS NEST DR	<b># Units:</b> 1.00	<b>Sq Ft:</b>	
<b>Location:</b>			
<b>Description:</b> HVAC PACKAGE SYSTEM CHANGEOUT ROOF-MOUNT. ENERGY DOCUMENTS DUE AT FINAL. SMOKE DETECTORS REQUIRED.			
<b>Contractor:</b> ULTIMATE HEATING & AIR			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> M1 HEATING/AIR CONDITION	
<b>Valuation:</b> \$3,200.00	<b>Fees Req:</b> \$198.28	<b>Fees Col:</b> \$198.28	<b>Bal Due:</b> \$0.00

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Activity: RES-0817138</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 22602100710000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/31/2008	<b>Finalized:</b>
<b>Site Address:</b> 829 N HILL WAY		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> WATER HEATER CHANGE OUT (GAS)			
<b>Contractor:</b> HARRIS PLUMBING			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> P6 WATER HEATER	
<b>Valuation:</b> \$800.00	<b>Fees Req:</b> \$83.32	<b>Fees Col:</b> \$83.32	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0817140</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 07903410310000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 8301 LA RIVIERA DR		<b># Units:</b> 1.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> HVAC SPLIT SYSTEM CHANGEOUT. ENERGY DOCUMENTS DUE AT FINAL. SMOKE DETECTORS REQUIRED.			
<b>Contractor:</b> AARONS COOLING & HEATING			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> M1 HEATING/AIRCONDITION	
<b>Valuation:</b> \$4,900.00	<b>Fees Req:</b> \$200.96	<b>Fees Col:</b> \$200.96	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0817141</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 01300860030000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 2616 ROCHON WAY		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> HVAC CHANGE OUT PACKAGE UNIT GROUND MOUNT			
<b>Contractor:</b> PARK MECHANICAL INC			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> M1 HEATING/AIRCONDITION	
<b>Valuation:</b> \$7,976.00	<b>Fees Req:</b> \$208.19	<b>Fees Col:</b> \$208.19	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0817142</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 02702910080000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 5938 ORTEGA ST		<b># Units:</b> 1.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> HVAC PACKAGE SYSTEM CHANGEOUT ROOF-MOUNT. ENERGY DOCUMENTS DUE AT FINAL. SMOKE DETECTORS REQUIRED.			
<b>Contractor:</b> AARONS COOLING & HEATING			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> M1 HEATING/AIRCONDITION	
<b>Valuation:</b> \$5,800.00	<b>Fees Req:</b> \$203.32	<b>Fees Col:</b> \$203.32	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0817143</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 01202920180000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 1461 8TH AVE		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> HVAC CHANGE OUT SPLIT SYSTEM			
<b>Contractor:</b> WERNER & SONS			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> M1 HEATING/AIRCONDITION	
<b>Valuation:</b> \$5,878.00	<b>Fees Req:</b> \$203.35	<b>Fees Col:</b> \$203.35	<b>Bal Due:</b> \$0.00

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Activity: RES-0817145</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 02901140060000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b> 01/02/2009
<b>Site Address:</b> 1176 MONTE VISTA WAY		<b># Units:</b> 1.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> TRENCHLESS SEWER REPLACEMENT			
<b>Contractor:</b> BONNEY PLUMBING & ROOTER SERVICE			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> P2 SEWER SERVICE	
<b>Valuation:</b> \$6,000.00	<b>Fees Req:</b> \$95.40	<b>Fees Col:</b> \$95.40	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0817148</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 26303240100000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b> 12/31/2008
<b>Site Address:</b> 125 BARTON WAY		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> SMUD SAFETY INSPECTION (NO WORK)			
<b>Contractor:</b>			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> E11 SAFETY INSPECTION	
<b>Valuation:</b> \$100.00	<b>Fees Req:</b> \$83.00	<b>Fees Col:</b> \$83.00	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0817149</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 01001030180000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b> 01/02/2009
<b>Site Address:</b> 2025 22ND ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> SPLIT SYSTEM HVAC CHANGE OUT - SMOKE DETECTORS ARE REQUIRED - COMPLIANCE DOCUMENTS ARE DUE AT FINAL.			
<b>Contractor:</b> AIR SOLUTIONS INC			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> M1 HEATING/AIRCONDITION	
<b>Valuation:</b> \$13,200.00	<b>Fees Req:</b> \$222.28	<b>Fees Col:</b> \$222.28	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0817151</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 01202030150000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 1140 MARIAN WAY		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> RELOCATE WATER & SEWER LINES			
<b>Contractor:</b> GEREMIA POOLS INC			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> P12 WTR & SWR SERVICE	
<b>Valuation:</b> \$2,000.00	<b>Fees Req:</b> \$85.80	<b>Fees Col:</b> \$85.80	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0817152</b>		<b>Type:</b> Building / Residential / Housing-Minor / Single Family	
<b>Parcel:</b> 02002140330000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 3625 21ST AVE		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> 06-002290 ---Re-roof overlayment. dryrot repair. Plumbing and electrical repairs. OWNER SHALL OBTAIN A PERMIT FOR NEW WATER LINE AND NEW FRENCH DOOR ADDED TO LEFT SIDE OF DWELLING.			
<b>Contractor:</b> RODECO BUILDERS			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> C4 HOUSING CASES	

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

Valuation: \$20,000.00	Fees Req: \$665.04	Fees Col: \$665.04	Bal Due: \$0.00
------------------------	--------------------	--------------------	-----------------

<b>Activity: RES-0817153</b>		<b>Type:</b> Building / Residential / Addition / Other Struct (non-bldg)	
Parcel: 20107200010000	Applied: 12/30/2008	Issued: 12/30/2008	Finalized:
Site Address: 5594 DUNLAY DR		# Units: 0.00	Sq Ft: 0
Location:			
Description: INSTALL 6.3 KW DC PHOTOVOLTAIC SYSTEM ON ROOF			
Contractor: VALLEY SOLAR INC			
Occupancy: R3	Insp Area: 4	Activity Code: E10 ELEC EQUIPMENT INSTALL	
Valuation: \$40,000.00	Fees Req: \$0.00	Fees Col: \$0.00	Bal Due: \$0.00

<b>Activity: RES-0817154</b>		<b>Type:</b> Building / Residential / Addition / Other Struct (non-bldg)	
Parcel: 03104800180000	Applied: 12/30/2008	Issued: 12/30/2008	Finalized:
Site Address: 7663 GREENHAVEN DR		# Units: 0.00	Sq Ft: 0
Location:			
Description: ADD A 2.8 KW PHOTOVOLTAIC SYSTEM ON ROOF.			
Contractor: VALLEY SOLAR INC			
Occupancy: R3	Insp Area: 2	Activity Code: E10 ELEC EQUIPMENT INSTALL	
Valuation: \$15,000.00	Fees Req: \$0.00	Fees Col: \$0.00	Bal Due: \$0.00

<b>Activity: RES-0817156</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
Parcel: 25001910340000	Applied: 12/30/2008	Issued: 12/30/2008	Finalized:
Site Address: 337 FORD RD		# Units: 0.00	Sq Ft:
Location:			
Description: REROOF W/ 30YR COMP.(IN PROGRESS INSPECTION)			
Contractor:			
Occupancy: R3	Insp Area: 4	Activity Code: R1 REROOF	
Valuation: \$5,000.00	Fees Req: \$199.50	Fees Col: \$199.50	Bal Due: \$0.00

<b>Activity: RES-0817157</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
Parcel: 01200720110000	Applied: 12/30/2008	Issued: 12/30/2008	Finalized:
Site Address: 2788 LAND PARK DR		# Units: 0.00	Sq Ft:
Location:			
Description: install approximately 50' of 4" ABS sewer pipe, new two way cast iron cleanout at house, 4" ABS one way cleanout at city tap. Replace effected PVC water line approx.45'			
Contractor: RUSSELL PLUMBING AND ROOTER SERVICE			
Occupancy: R3	Insp Area: 2	Activity Code: P2 SEWER SERVICE	
Valuation: \$6,000.00	Fees Req: \$95.40	Fees Col: \$95.40	Bal Due: \$0.00

<b>Activity: RES-0817158</b>		<b>Type:</b> Building / Residential / Repair-Maintenance / Single Family	
Parcel: 23703420030000	Applied: 12/30/2008	Issued: 12/30/2008	Finalized:
Site Address: 4480 BOLLENBACHER AVE		# Units: 0.00	Sq Ft: 0
Location:			
Description: REINFORCE 40' OF FOUNDATION WALL ON SOUTH SIDE OF HOUSE			
Contractor: A K ENTERPRISES			

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> C1 GENERAL REPAIR/FIX-IT	
<b>Valuation:</b> \$2,500.00	<b>Fees Req:</b> \$233.22	<b>Fees Col:</b> \$233.22	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817159	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 02502410230000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 2433 39TH AVE		<b># Units:</b> 1.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> HVAC PACKAGESYSTEM CHANGEOUT GROUND-MOUNT. ENERGY DOCUMENTS DUE AT FINAL. SMOKE DETECTORS REQUIRED.			
<b>Contractor:</b> ENERGY CONSERVATIONCONTRACTORS			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> M1 HEATING/AIR CONDITION	
<b>Valuation:</b> \$2,200.00	<b>Fees Req:</b> \$195.88	<b>Fees Col:</b> \$195.88	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817160	<b>Type:</b> Building / Residential / Minor / Duplex		
<b>Parcel:</b> 00801640060000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 5140 J ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> REPLACE HVAC SYSTEM LIKE FOR LIKE IN UNIT 5142 J STREET.			
<b>Contractor:</b> CENTRAL AIR'S ONE HOUR HEATING & AIR CONDITIONING			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> M1 HEATING/AIR CONDITION	
<b>Valuation:</b> \$7,766.00	<b>Fees Req:</b> \$208.11	<b>Fees Col:</b> \$208.11	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817161	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 07801430080000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 2776 WISSEMAN DR		<b># Units:</b> 1.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> HVAC SPLIT SYSTEM CHANGEOUT. ENERGY DOCUMENTS DUE AT FINAL. SMOKE DETECTORS REQUIRED.			
<b>Contractor:</b> SERVICE CHAMPIONS			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> M1 HEATING/AIR CONDITION	
<b>Valuation:</b> \$7,999.00	<b>Fees Req:</b> \$208.20	<b>Fees Col:</b> \$208.20	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817164	<b>Type:</b> Building / Residential / Housing-Minor / Single Family		
<b>Parcel:</b> 02301850110000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b> 01/02/2009
<b>Site Address:</b> 7418 25TH AVE		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> 08-015721 ---In continuation to expired permit res-0813619. Complete repairs from violations list and call for final.			
<b>Contractor:</b> U C S UNIVERSAL CONTRACTING SERVICES			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> C4 HOUSING CASES	
<b>Valuation:</b> \$999.00	<b>Fees Req:</b> \$233.90	<b>Fees Col:</b> \$233.90	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817166	<b>Type:</b> Building / Residential / Housing-Minor / Single Family		
<b>Parcel:</b> 01302920280000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 3650 6TH AVE		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> 06-009238 --Repair all dryrot damage on exterior, siding. Kitchen remodel, repair all faulty plumbing fixtures. Installation of wall furnace. Complete electrical re-wire throughout house. Water heater change out.			

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Contractor:</b>			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> C4 HOUSING CASES	
<b>Valuation:</b> \$10,000.00	<b>Fees Req:</b> \$711.00	<b>Fees Col:</b> \$711.00	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817167		<b>Type:</b> Building / Residential / Minor / Half Plex	
<b>Parcel:</b> 22509300190000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 2980 MENDEL WAY		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> ROOF REPAIR OF A PORTION OF THE ROOF OVER ONE OF THE HALF-PLEX UNITS 15 SQ'S INVOLVED			
<b>Contractor:</b> REST ASSURED ROOFING			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> R1 REROOF	
<b>Valuation:</b> \$5,088.00	<b>Fees Req:</b> \$203.55	<b>Fees Col:</b> \$203.55	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817169		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 04904500010000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b> 12/31/2008
<b>Site Address:</b> 23 SENTIDO CT		<b># Units:</b> 1.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> SMUD SAFETY, ONE TIME INSPECTION, NO REPAIRS. PROVIDE ACCESS.			
<b>Contractor:</b> FRAGO JEFF			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> E11 SAFETY INSPECTION	
<b>Valuation:</b> \$99.00	<b>Fees Req:</b> \$83.04	<b>Fees Col:</b> \$83.04	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817171		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 02403240110000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b> 12/31/2008
<b>Site Address:</b> 6525 FORDHAM WAY		<b># Units:</b> 1.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> CHANGE OUT GAS WATER HEATER TO TANKLESS.			
<b>Contractor:</b> BOYD PLUMBING INC			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> P6 WATER HEATER	
<b>Valuation:</b> \$1,622.00	<b>Fees Req:</b> \$85.65	<b>Fees Col:</b> \$85.65	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817172		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 00501530240000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 5601 MODDISON AVE		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> UPDATE SERVICE PANEL TO 200AMP			
<b>Contractor:</b>			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> E2 ELEC SERVICE CHANGE	
<b>Valuation:</b> \$800.00	<b>Fees Req:</b> \$83.00	<b>Fees Col:</b> \$83.00	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817173		<b>Type:</b> Building / Residential / Housing Dept Permit / Single Family	
<b>Parcel:</b> 01303320010000	<b>Applied:</b> 12/30/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 3200 9TH AVE		<b># Units:</b> 0.00	<b>Sq Ft:</b> 1,200
<b>Location:</b>			

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

**Description:** 08-017118 --New roof, restructure roof at rear with trusses. Install 30 yr. dim lam comp. New siding and windows. Dryrot repair and termite damage. A complete rewire. Interior remodel. New floor joist at northwest corner of house. New HVAC, split system.

**Contractor:** B C CONSTRUCTION

**Occupancy:** R3

**Insp Area:** 3

**Activity Code:** C4 HOUSING CASES

**Valuation:** \$30,000.00

**Fees Req:** \$925.40

**Fees Col:** \$925.40

**Bal Due:** \$0.00

**Activity:** RES-0817174

**Type:** Building / Residential / Minor / Single Family

**Parcel:** 26202320160000

**Applied:** 12/30/2008

**Issued:** 12/30/2008

**Finalized:** 01/02/2009

**Site Address:** 901 W EL CAMINO AVE

**# Units:** 0.00

**Sq Ft:**

**Location:**

**Description:** REPAIR ELECTRICAL CIRCUIT (EXPOSED ROMEX) ADD BATTERY OPERATED SMOKE DETECTORS

**Contractor:** PLATINUM ELECTRIC

**Occupancy:** R3

**Insp Area:** 4

**Activity Code:** E1 SERVICE REPAIR

**Valuation:** \$384.00

**Fees Req:** \$83.15

**Fees Col:** \$83.15

**Bal Due:** \$0.00

**Activity:** RES-0817175

**Type:** Building / Residential / Housing-Minor / Single Family

**Parcel:** 01302510200000

**Applied:** 12/30/2008

**Issued:** 12/30/2008

**Finalized:**

**Site Address:** 3048 37TH ST

**# Units:** 1.00

**Sq Ft:**

**Location:**

**Description:** PERMIT ISSUED FOR REPAIRS FROM THE HOUSING VIOLATIONS LIST. MINOR PLUMBING, BUILDING. GAS VENTS.

**Contractor:** KATZART

**Occupancy:** R3

**Insp Area:** 3

**Activity Code:** C4 HOUSING CASES

**Valuation:** \$2,000.00

**Fees Req:** \$314.06

**Fees Col:** \$314.06

**Bal Due:** \$0.00

**Activity:** RES-0817179

**Type:** Building / Residential / Minor / Single Family

**Parcel:** 00301540060000

**Applied:** 12/30/2008

**Issued:** 12/30/2008

**Finalized:**

**Site Address:** 2816 E ST

**# Units:** 0.00

**Sq Ft:**

**Location:**

**Description:** REMOVE WOOD PANELING, KITCHEN AND BATHROOM CABINETS, SINKS, ELECTRICAL TO UPDATE LATER, ACOUSTIC CEILINGS TILES, INSULATION FROM INTERIOR OF HOUSE AND ACCESSORY STRUCTURE FOR FUTURE REMODEL.

**Contractor:**

**Occupancy:** R3

**Insp Area:** 1

**Activity Code:** I6 INTERIOR DEMOLITION

**Valuation:** \$1,000.00

**Fees Req:** \$119.14

**Fees Col:** \$119.14

**Bal Due:** \$0.00

**Activity:** RES-0817180

**Type:** Building / Residential / Remodel / Half Plex

**Parcel:** 04001540250000

**Applied:** 12/30/2008

**Issued:** 12/30/2008

**Finalized:**

**Site Address:** 7795 OTHEL WAY

**# Units:** 0.00

**Sq Ft:** 203

**Location:**

**Description:** CONVERTING OF FAMILYROOM INTO A 3RD BEDROOM & ADDING OF FURRED OUT CEILING IN HALL. INSTALLATION OF LIGHTS IN NEWLY RECREATING CEILING AND INSTALLATION OF AFCI.

**Contractor:**

**Occupancy:** R3

**Insp Area:** 3

**Activity Code:** I1 INTERIOR REM-RES

**Valuation:** \$1,700.00

**Fees Req:** \$239.74

**Fees Col:** \$239.74

**Bal Due:** \$0.00

**Activity:** RES-0817191

**Type:** Building / Residential / Minor / Single Family

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Parcel:</b> 22601610490000	<b>Applied:</b> 12/31/2008	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 646 PINEDALE AVE		<b># Units:</b> 1.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> HVAC PACKAGE SYSTEM CHANGEOUT ROOF-MOUNT. ENERGY DOCUMENTS DUE AT FINAL. SMOKE DETECTORS REQUIRED.			
<b>Contractor:</b> COOK RAY O COMPANY			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> M1 HEATING/AIRCONDITION	
<b>Valuation:</b> \$4,500.00	<b>Fees Req:</b> \$201.30	<b>Fees Col:</b> \$201.30	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817192	<b>Type:</b> Building / Residential / Housing-Demo / Single Family		
<b>Parcel:</b> 03801010030000	<b>Applied:</b> 12/31/2008	<b>Issued:</b> 12/31/2008	<b>Finalized:</b>
<b>Site Address:</b> 6161 63RD ST		<b># Units:</b> 0.00	<b>Sq Ft:</b> 1,400
<b>Location:</b>			
<b>Description:</b> 08-015225--Demo of single family residence.			
<b>Contractor:</b> MAPA INDUSTRIES INC			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> C4 HOUSING CASES	
<b>Valuation:</b> \$7,000.00	<b>Fees Req:</b> \$353.00	<b>Fees Col:</b> \$353.00	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817194	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 00501620180000	<b>Applied:</b> 12/31/2008	<b>Issued:</b> 12/31/2008	<b>Finalized:</b>
<b>Site Address:</b> 5800 CALLISTER AVE		<b># Units:</b> 1.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> 125 AMP ELECTRICAL SERVICE CHANGE			
<b>Contractor:</b> SAXELBY ELECTRIC			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> E2 ELEC SERVICE CHANGE	
<b>Valuation:</b> \$3,700.00	<b>Fees Req:</b> \$90.48	<b>Fees Col:</b> \$90.48	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817195	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 26201640110000	<b>Applied:</b> 12/31/2008	<b>Issued:</b> 12/31/2008	<b>Finalized:</b>
<b>Site Address:</b> 2740 BRIDGEOFORD DR		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> REPLACE MAIN BREAKER			
<b>Contractor:</b>			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> E10 ELEC EQUIPMENT INSTALL	
<b>Valuation:</b> \$200.00	<b>Fees Req:</b> \$83.00	<b>Fees Col:</b> \$83.00	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0817198	<b>Type:</b> Building / Residential / Repair-Maintenance / Single Family		
<b>Parcel:</b> 00901340160000	<b>Applied:</b> 12/31/2008	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 1025 V ST		<b># Units:</b> 1.00	<b>Sq Ft:</b> 0
<b>Location:</b>			
<b>Description:</b> HAND DIG AND REPLACE SEWER. REPLUMB WASTE UNDER BUILDING. ****VERIFY NO SIDING WORK IN PROGRESS****			
<b>Contractor:</b> TRENCHLESS COMPANY THE			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> P2 SEWER SERVICE	
<b>Valuation:</b> \$11,484.00	<b>Fees Req:</b> \$395.79	<b>Fees Col:</b> \$395.79	<b>Bal Due:</b> \$0.00



**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Activity: RES-0817202</b>		<b>Type:</b> Building / Residential / Housing-Demo / Private Garage		
<b>Parcel:</b> 01303510200000	<b>Applied:</b> 12/31/2008	<b>Issued:</b> 12/31/2008	<b>Finalized:</b>	
<b>Site Address:</b> 3741 9TH AVE		<b># Units:</b> 0.00	<b>Sq Ft:</b>	240
<b>Location:</b>				
<b>Description:</b> 07-050465 --Demo garage.				
<b>Contractor:</b> QUALITY HOME CONSTRUCTION				
<b>Occupancy:</b> U1	<b>Insp Area:</b> 3	<b>Activity Code:</b> C4 HOUSING CASES		
<b>Valuation:</b> \$999.00	<b>Fees Req:</b> \$341.40	<b>Fees Col:</b> \$341.40	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0817204</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 26302910120000	<b>Applied:</b> 12/31/2008	<b>Issued:</b> 12/31/2008	<b>Finalized:</b>	
<b>Site Address:</b> 205 OLMSTEAD DR		<b># Units:</b> 1.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> SEWER REPAIRS				
<b>Contractor:</b>				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> P2 SEWER SERVICE		
<b>Valuation:</b> \$1,999.00	<b>Fees Req:</b> \$85.00	<b>Fees Col:</b> \$85.00	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0817205</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 02102320090000	<b>Applied:</b> 12/31/2008	<b>Issued:</b> 12/31/2008	<b>Finalized:</b>	
<b>Site Address:</b> 4421 60TH ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> C/O 30 FOOT SEWER LINE				
<b>Contractor:</b> ROY'S PLUMBING				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> P12 WTR & SWR SERVICE		
<b>Valuation:</b> \$2,000.00	<b>Fees Req:</b> \$85.80	<b>Fees Col:</b> \$85.80	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0817208</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 29501300370000	<b>Applied:</b> 12/31/2008	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>	
<b>Site Address:</b> 1004 DUNBARTON CIR		<b># Units:</b> 1.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> ELECTRIC WATER HEATER CHANGE OUT				
<b>Contractor:</b> BONNEY PLUMBING & ROOTER SERVICE				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> P6 WATER HEATER		
<b>Valuation:</b> \$1,900.00	<b>Fees Req:</b> \$85.76	<b>Fees Col:</b> \$85.76	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0817210</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 03003950010000	<b>Applied:</b> 12/31/2008	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>	
<b>Site Address:</b> 6796 POCKET RD		<b># Units:</b> 1.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> HEAT PUMP CHANGEOUT. ENERGY DOCUMENTS DUE AT FINAL. SMOKE DETECTORS REQUIRED.				
<b>Contractor:</b> BELL BROTHER'S HEATING AND AIR INC				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> M1 HEATING/AIR CONDITION		
<b>Valuation:</b> \$9,653.00	<b>Fees Req:</b> \$212.86	<b>Fees Col:</b> \$212.86	<b>Bal Due:</b> \$0.00	

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Activity: RES-0817211</b>		<b>Type: Building / Residential / Housing-Minor / Single Family</b>	
<b>Parcel:</b> 00702210010000	<b>Applied:</b> 12/31/2008	<b>Issued:</b> 12/31/2008	<b>Finalized:</b>
<b>Site Address:</b> 1301 32ND ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> 08-100570 --REVERT BASEMENT BACK TO ORIGINAL STATE,A BASEMENT/STORAGE. REVERT ACCESSORY STORAGE STRUCTURE BACK TO A STORAGE UNIT.			
<b>Contractor:</b> M J RENOVATOR			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> C4 HOUSING CASES	
<b>Valuation:</b> \$1,800.00	<b>Fees Req:</b> \$271.86	<b>Fees Col:</b> \$271.86	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0817213</b>		<b>Type: Building / Residential / Minor / Single Family</b>	
<b>Parcel:</b> 03503010060000	<b>Applied:</b> 12/31/2008	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 1631 59TH AVE		<b># Units:</b> 1.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> HVAC SPLIT SYSTEM FURNACE CHANGEOUT. ENERGY DOCUMENTS DUE AT FINAL. SMOKE DETECTORS REQUIRED.			
<b>Contractor:</b> BELL BROTHER'S HEATING AND AIR INC			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> M1 HEATING/AIR CONDITION	
<b>Valuation:</b> \$3,350.00	<b>Fees Req:</b> \$198.34	<b>Fees Col:</b> \$198.34	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0817214</b>		<b>Type: Building / Residential / Minor / Single Family</b>	
<b>Parcel:</b> 02902660080000	<b>Applied:</b> 12/31/2008	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 1030 FOXHALL WAY		<b># Units:</b> 1.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> WATER HEATER CHANGE OUT			
<b>Contractor:</b> BONNEY PLUMBING & ROOTER SERVICE			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> P6 WATER HEATER	
<b>Valuation:</b> \$1,800.00	<b>Fees Req:</b> \$85.72	<b>Fees Col:</b> \$85.72	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0817215</b>		<b>Type: Building / Residential / Minor / Single Family</b>	
<b>Parcel:</b> 04701230050000	<b>Applied:</b> 12/31/2008	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 2040 NEWPORT AVE		<b># Units:</b> 1.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> TEAR OFF,RESHEATH AND REROOF 1-STORY SFD. 25 SQ. WITH 30 YR D.C. IN PROGRESS INSPECTION REQUIRED.			
<b>Contractor:</b> WORK FORCE UNLIMITED			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> R1 REROOF	
<b>Valuation:</b> \$8,000.00	<b>Fees Req:</b> \$209.00	<b>Fees Col:</b> \$209.00	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0817216</b>		<b>Type: Building / Residential / Minor / Single Family</b>	
<b>Parcel:</b> 02901620020000	<b>Applied:</b> 12/31/2008	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 1053 WOODSHIRE WAY		<b># Units:</b> 1.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> HVAC CHANGE OUT SPLIT SYSTEM			
<b>Contractor:</b> A & P HEATING AND COOLING INC			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> M1 HEATING/AIR CONDITION	
<b>Valuation:</b> \$12,027.00	<b>Fees Req:</b> \$219.81	<b>Fees Col:</b> \$219.81	<b>Bal Due:</b> \$0.00

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Activity: RES-0817218</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 29505000370000	<b>Applied:</b> 12/31/2008	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>	
<b>Site Address:</b> 1926 UNIVERSITY PARK DR		<b># Units:</b> 1.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> HVAC CHANGE OUT - SPLIT SYSTEM				
<b>Contractor:</b> A & P HEATING AND COOLING INC				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> M1 HEATING/AIR CONDITION		
<b>Valuation:</b> \$10,557.00	<b>Fees Req:</b> \$215.22	<b>Fees Col:</b> \$215.22	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0817221</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 00501730160000	<b>Applied:</b> 12/31/2008	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>	
<b>Site Address:</b> 290 MESSINA DR		<b># Units:</b> 1.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> TRENCHLESS SEWER LINE REPLACEMENT.				
<b>Contractor:</b> TRENCHLESS COMPANY THE				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> P2 SEWER SERVICE		
<b>Valuation:</b> \$6,117.00	<b>Fees Req:</b> \$97.45	<b>Fees Col:</b> \$97.45	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0817223</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 00400640020000	<b>Applied:</b> 12/31/2008	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>	
<b>Site Address:</b> 82 PRIMROSE WAY		<b># Units:</b> 1.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> TRENCHLESS SEWER REPLACEMENT				
<b>Contractor:</b> TRENCHLESS COMPANY THE				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> P2 SEWER SERVICE		
<b>Valuation:</b> \$4,701.00	<b>Fees Req:</b> \$92.88	<b>Fees Col:</b> \$92.88	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0817227</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 01202720010000	<b>Applied:</b> 12/31/2008	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>	
<b>Site Address:</b> 632 6TH AVE		<b># Units:</b> 1.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> TRENCHLESS SEWER REPLACEMENT				
<b>Contractor:</b> TRENCHLESS COMPANY THE				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> P2 SEWER SERVICE		
<b>Valuation:</b> \$2,774.00	<b>Fees Req:</b> \$88.11	<b>Fees Col:</b> \$88.11	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0900001</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 03101310010000	<b>Applied:</b> 01/01/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>	
<b>Site Address:</b> 1210 GILCREST AVE		<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> PARTIAL SEWER REPAIR				
<b>Contractor:</b> ACE PLUMBING HEATING & AIR				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> P2 SEWER SERVICE		
<b>Valuation:</b> \$2,150.00	<b>Fees Req:</b> \$87.86	<b>Fees Col:</b> \$87.86	<b>Bal Due:</b> \$0.00	

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Activity: RES-0900002</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 01502810090000	<b>Applied:</b> 01/01/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>	
<b>Site Address:</b> 5978 RAYMOND WAY		<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> T/O 1 STORY 19 SQ'S 30 YR COMP.IN PROGRESS INSPECTION REQUIRED				
<b>Contractor:</b> ZIMMERMAN RE - ROOFING INC				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> R1 REROOF		
<b>Valuation:</b> \$5,740.00	<b>Fees Req:</b> \$203.87	<b>Fees Col:</b> \$203.87	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0900003</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 03107700190000	<b>Applied:</b> 01/01/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>	
<b>Site Address:</b> 575 CORK RIVER WAY		<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> HVAC C/O SPLIT SYSTEM GROUND MOUNT.PROVIDE ALL DOCUMENTS FOR FINAL INSPECTION. SMOKE DETECTORS REQUIRED.				
<b>Contractor:</b> HUFT HEATING AND AIR CONDITIONING				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> M1 HEATING/AIRCONDITION		
<b>Valuation:</b> \$9,082.00	<b>Fees Req:</b> \$212.63	<b>Fees Col:</b> \$212.63	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0900004</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 01103300270000	<b>Applied:</b> 01/01/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>	
<b>Site Address:</b> 5309 BROADWAY		<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> FURNANCE AND COIL CHANGEOUT ONLY GROUND MONUT.PROVIDE ALL DOCUMENTS FOR FINAL INSPECTION. SMOKE DETECTORS REQUIRED				
<b>Contractor:</b> HUFT HEATING AND AIR CONDITIONING				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> M3 FURNACE		
<b>Valuation:</b> \$3,800.00	<b>Fees Req:</b> \$198.52	<b>Fees Col:</b> \$198.52	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0900006</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 22508510230000	<b>Applied:</b> 01/01/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>	
<b>Site Address:</b> 3150 AZEVEDO DR		<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> HVAC C/O HEATPUMP GROUND MOUNT.PROVIDE ALL DOCUMENTS FOR FINAL INSPECTION. SMOKE DETECTORS REQUIRED.				
<b>Contractor:</b> SECO HEATING AIR CONDITIONING AND REFRIGERATION INC				
<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> M1 HEATING/AIRCONDITION		
<b>Valuation:</b> \$5,500.00	<b>Fees Req:</b> \$203.20	<b>Fees Col:</b> \$203.20	<b>Bal Due:</b> \$0.00	

<b>Activity: RES-0900007</b>		<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 01500540360000	<b>Applied:</b> 01/01/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>	
<b>Site Address:</b> 5349 8TH AVE		<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>				
<b>Description:</b> REPLACE SEWER LINE				
<b>Contractor:</b> EXPRESS PLUMBING AFFORDABLE TRENCHLESS COMPANY				

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> P12 WTR & SWR SERVICE	
<b>Valuation:</b> \$2,200.00	<b>Fees Req:</b> \$87.88	<b>Fees Col:</b> \$87.88	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0900008	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 01502240030000	<b>Applied:</b> 01/01/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 6012 12TH AVE		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> TRENCHLESS SEWER REPLACEMENT			
<b>Contractor:</b> EXPRESS PLUMBING AFFORDABLE TRENCHLESS COMPANY			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> P12 WTR & SWR SERVICE	
<b>Valuation:</b> \$3,500.00	<b>Fees Req:</b> \$90.40	<b>Fees Col:</b> \$90.40	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0900009	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 11705760390000	<b>Applied:</b> 01/01/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 8428 SUNBLAZE WAY		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> HVAC C/O HEATPUMP SPLIT SYSTEM. PROVIDE ALL DOCUMENTS FOR FINAL INSPECTION. SMOKE DETECTORS REQUIRED.			
<b>Contractor:</b> A TO Z HEATING AND AIR INC			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> M1 HEATING/AIRCONDITION	
<b>Valuation:</b> \$8,000.00	<b>Fees Req:</b> \$208.20	<b>Fees Col:</b> \$208.20	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0900010	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 01300920040000	<b>Applied:</b> 01/01/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 2901 27TH ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> HVAC C/O ROOF MOUNT. PROVIDE ALL DOCUMENTS FOR FINAL INSPECTION. SMOKE DETECTORS REQUIRED.			
<b>Contractor:</b> ACE PLUMBING HEATING & AIR			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> M1 HEATING/AIRCONDITION	
<b>Valuation:</b> \$3,380.00	<b>Fees Req:</b> \$198.35	<b>Fees Col:</b> \$198.35	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0900011	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 03103800010000	<b>Applied:</b> 01/01/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 7145 POCKET RD		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> HVAC C/O HEATPUMP SPLIT SYSTEM. PROVIDE ALL DOCUMENTS FOR FINAL INSPECTION. SMOKE DETECTORS REQUIRED.			
<b>Contractor:</b> VALLEY HEATING & AIR CONDITIONING & HOME IMPROVEMENTS INC			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> M1 HEATING/AIRCONDITION	
<b>Valuation:</b> \$7,700.00	<b>Fees Req:</b> \$208.08	<b>Fees Col:</b> \$208.08	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0900012	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 22507320330000	<b>Applied:</b> 01/01/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 166 SAGINAW CIR		<b># Units:</b> 0.00	<b>Sq Ft:</b>

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Location:</b>			
<b>Description:</b> HVAC C/O SPLIT SYSTEM GROUND MOUNT. PROVIDE ALL DOCUMENTS FOR FINAL INSPECTION. SMOKE DETECTORS REQUIRED.			
<b>Contractor:</b> ONE HOUR HEATING AND AIR CONDITIONING			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> M1 HEATING/AIR CONDITION	
<b>Valuation:</b> \$7,457.00	<b>Fees Req:</b> \$207.98	<b>Fees Col:</b> \$207.98	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0900014	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 00300830100000	<b>Applied:</b> 01/01/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 231 22ND ST	<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>			
<b>Description:</b> Inclusions: Install new 6x6x48 gutter above panels New riser and weather head New 100 amp service/sub panel to be installed next to existing 200 amp panel Install new 6x6x48 gutter below panels to intercept existing circuits New grounding electrode and grounding electrode conductor Repair existing pvc conduit going to attic			
<b>Contractor:</b>			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> E2 ELEC SERVICE CHANGE	
<b>Valuation:</b> \$1,400.00	<b>Fees Req:</b> \$86.00	<b>Fees Col:</b> \$86.00	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0900015	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 01303220130000	<b>Applied:</b> 01/01/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 3511 E CURTIS DR	<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>			
<b>Description:</b> T/O 2 STORY 13 SQ'S C TREATED SHAKES. IN PROGRESS INSPECTION REQUIRED			
<b>Contractor:</b> HAAS DEBBIE ROOFING			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> R1 REROOF	
<b>Valuation:</b> \$3,300.00	<b>Fees Req:</b> \$198.82	<b>Fees Col:</b> \$198.82	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0900016	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 02300610340000	<b>Applied:</b> 01/02/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 9 SUBURBAN CT	<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>			
<b>Description:</b> C/O GAS WATER HEATER			
<b>Contractor:</b> DOMCO PLUMBING INC			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> P6 WATER HEATER	
<b>Valuation:</b> \$600.00	<b>Fees Req:</b> \$84.24	<b>Fees Col:</b> \$84.24	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0900018	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 01203720100000	<b>Applied:</b> 01/02/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 1610 10TH AVE	<b># Units:</b> 0.00	<b>Sq Ft:</b>	
<b>Location:</b>			
<b>Description:</b> HVAC C/O SPLIT SYSTEM. PROVIDE ALL DOCUMENTS FOR FINAL INSPECTION. SMOKE DETECTORS REQUIRED.			
<b>Contractor:</b> GARICK AIR CONDITIONING SERVICE			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> M1 HEATING/AIR CONDITION	
<b>Valuation:</b> \$10,125.00	<b>Fees Req:</b> \$215.05	<b>Fees Col:</b> \$215.05	<b>Bal Due:</b> \$0.00

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Activity: RES-0900021</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 00402830290000	<b>Applied:</b> 01/02/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 551 38TH ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> NEW HVAC SPLIT SYSTEM PROVIDE ALL DOCUMENTS FOR FINAL INSPECTION. SMOKE DETECTORS REQUIRED			
<b>Contractor:</b> NORTHERNAIR MECHANICAL			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> M1 HEATING/AIRCONDITION	
<b>Valuation:</b> \$6,021.00	<b>Fees Req:</b> \$207.01	<b>Fees Col:</b> \$207.01	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0900025</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 00701840100000	<b>Applied:</b> 01/02/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 1272 32ND ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> REPLACE WATER SERVICE			
<b>Contractor:</b> GAVRILOVPHILLIP CONSTRUCTION INC			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> P12 WTR & SWR SERVICE	
<b>Valuation:</b> \$500.00	<b>Fees Req:</b> \$84.20	<b>Fees Col:</b> \$84.20	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0900026</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 01600310190000	<b>Applied:</b> 01/02/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 1161 LANCASTER WAY		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> HVAC C/O PACKAGE SYSTEM ROOF MOUNT. PROVIDE ALL DOCUMENTS FOR FINAL INSPECTION. SMOKE DETECTORS REQUIRED.			
<b>Contractor:</b> MC DONALD PLUMBING HEATING & AIR CONDITIONING INC			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> M1 HEATING/AIRCONDITION	
<b>Valuation:</b> \$9,818.00	<b>Fees Req:</b> \$213.93	<b>Fees Col:</b> \$213.93	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0900030</b>		<b>Type:</b> Building / Residential / Housing-Minor / Single Family	
<b>Parcel:</b> 11902700590000	<b>Applied:</b> 01/02/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 107 DECATHLON CIR		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> 08-003294 --SMUD SAFETY INSPECTION. HVAC unit vandalized, CHANGE OUT. REPAIRS PER VIOLATIONS LIST. WATER DAMAGE REPAIR.			
<b>Contractor:</b> MAXIMUM HOME BUILDERS			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> C4 HOUSING CASES	
<b>Valuation:</b> \$7,500.00	<b>Fees Req:</b> \$653.41	<b>Fees Col:</b> \$653.41	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0900031</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 03003810070000	<b>Applied:</b> 01/02/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 6724 TRUDY WAY		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> TRENCHLESS SEWER REPLACEMENT			
<b>Contractor:</b> ACE PLUMBING HEATING & AIR			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> P12 WTR & SWR SERVICE	
<b>Valuation:</b> \$6,200.00	<b>Fees Req:</b> \$98.48	<b>Fees Col:</b> \$98.48	<b>Bal Due:</b> \$0.00

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Activity: RES-0900032</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 01200630120000	<b>Applied:</b> 01/02/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 2780 13TH ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> REPLACE KITCHEN AND BATHROOM PLUGS TO GFCI RECEPTECLES			
<b>Contractor:</b> A R P ELECTRIC AND LIGHTING CO A PARTNERSHIP			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> E10 ELEC EQUIPMENT INSTALL	
<b>Valuation:</b> \$100.00	<b>Fees Req:</b> \$84.04	<b>Fees Col:</b> \$84.04	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0900033</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 26202830230000	<b>Applied:</b> 01/02/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 2859 CARBERRY WAY		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> REPLACE STOLEN BREAKERS IN SERVICE PANELS			
<b>Contractor:</b> PARKER ENTERPRISES			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> E1 SERVICE REPAIR	
<b>Valuation:</b> \$1,600.00	<b>Fees Req:</b> \$86.64	<b>Fees Col:</b> \$86.64	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0900034</b>		<b>Type:</b> Building / Residential / Minor / Duplex	
<b>Parcel:</b> 00701460110000	<b>Applied:</b> 01/02/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 2009 N ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> ELECTRICAL SERVICE CHANGE 200 AMP			
<b>Contractor:</b> J & J ELECTRIC			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 1	<b>Activity Code:</b> E10 ELEC EQUIPMENT INSTALL	
<b>Valuation:</b> \$100.00	<b>Fees Req:</b> \$84.04	<b>Fees Col:</b> \$84.04	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0900035</b>		<b>Type:</b> Building / Residential / Housing Dept Permit / Single Family	
<b>Parcel:</b> 01400930120000	<b>Applied:</b> 01/02/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 3874 3RD AVE		<b># Units:</b> 0.00	<b>Sq Ft:</b> 870
<b>Location:</b>			
<b>Description:</b> 08-093801 ---Incontinuation to expired permit # res-0814656. To complete repairs per violations list. Kitchen remodel, finish plumbing and electrical.			
<b>Contractor:</b> GROW HADLEY			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> C4 HOUSING CASES	
<b>Valuation:</b> \$15,000.00	<b>Fees Req:</b> \$605.86	<b>Fees Col:</b> \$605.86	<b>Bal Due:</b> \$0.00

<b>Activity: RES-0900036</b>		<b>Type:</b> Building / Residential / Minor / Single Family	
<b>Parcel:</b> 02701610230000	<b>Applied:</b> 01/02/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 8005 34TH AVE		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> INSTALL NEW 100 AMP BREAKER			
<b>Contractor:</b> O'BRIEN KEN			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> E1 SERVICE REPAIR	



**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

Valuation: \$350.00	Fees Req: \$84.14	Fees Col: \$84.14	Bal Due: \$0.00
---------------------	-------------------	-------------------	-----------------

<b>Activity: RES-0900037</b>		<b>Type: Building / Residential / Minor / Single Family</b>	
Parcel: 22519800640000	Applied: 01/02/2009	Issued: 01/02/2009	Finalized: 01/05/2009
Site Address: 24 JACKDAW CT		# Units: 0.00	Sq Ft:
Location:			
Description: SMUD SAFETY INSPECTION ONLY- NO WORK			
Contractor:			
Occupancy: R3	Insp Area: 4	Activity Code: E11 SAFETY INSPECTION	
Valuation: \$0.00	Fees Req: \$84.00	Fees Col: \$84.00	Bal Due: \$0.00

<b>Activity: RES-0900039</b>		<b>Type: Building / Residential / Minor / Single Family</b>	
Parcel: 22506540030000	Applied: 01/02/2009	Issued: 01/02/2009	Finalized:
Site Address: 1083 MILLET WAY		# Units: 0.00	Sq Ft:
Location:			
Description: CHANGE OUT GAS WATER HEATER			
Contractor:			
Occupancy: R3	Insp Area: 4	Activity Code: G3 HOT WATER HEATER	
Valuation: \$1,200.00	Fees Req: \$86.00	Fees Col: \$86.00	Bal Due: \$0.00

<b>Activity: RES-0900040</b>		<b>Type: Building / Residential / Remodel / Single Family</b>	
Parcel: 00803340040000	Applied: 01/02/2009	Issued: 01/02/2009	Finalized:
Site Address: 1408 48TH ST		# Units: 0.00	Sq Ft: 0
Location:			
Description: INSTALL DIVIDING WALL IN EXISTING BEDROOM TO CREATE TWO BEDROOMS AND INSTALL TWO NEW WINDOWS TO PROVIDE EGRESS			
Contractor: PAGE LARRY CONSTRUCTION			
Occupancy: R3	Insp Area: 1	Activity Code: I1 INTERIOR REM-RES	
Valuation: \$3,500.00	Fees Req: \$285.22	Fees Col: \$285.22	Bal Due: \$0.00

<b>Activity: RES-0900041</b>		<b>Type: Building / Residential / Housing-Minor / Duplex</b>	
Parcel: 03005400110000	Applied: 01/02/2009	Issued: 01/02/2009	Finalized:
Site Address: 66 HAVENWOOD CIR		# Units: 0.00	Sq Ft:
Location:			
Description: H040037889--Incontinuation to expired permit # res-0815957. Replacement of approx. 200 sf of roof.			
Contractor:			
Occupancy: R3	Insp Area: 2	Activity Code: C4 HOUSING CASES	
Valuation: \$1,100.00	Fees Req: \$272.14	Fees Col: \$272.14	Bal Due: \$0.00

<b>Activity: RES-0900043</b>		<b>Type: Building / Residential / Minor / Single Family</b>	
Parcel: 03101440030000	Applied: 01/02/2009	Issued: 01/02/2009	Finalized:
Site Address: 20 ROSE MEAD CIR		# Units: 0.00	Sq Ft:
Location:			
Description: HVAC C/O SPLIT SYSTEM. PROVIDE ALL DOCUMENTS FOR FINAL INSPECTION. SMOKE DETECTORS REQUIRED.			
Contractor: ALLEY & COMPANY INC			

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> M1 HEATING/AIRCONDITION	
<b>Valuation:</b> \$5,000.00	<b>Fees Req:</b> \$202.00	<b>Fees Col:</b> \$202.00	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0900045	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 01302320170000	<b>Applied:</b> 01/02/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 2733 6TH AVE		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> HVAC C/O PACKAGE SYSTEM ROOF MOUNT. PROVIDE ALL DOCUMENTS FOR FINAL INSPECTION. SMOKE DETECTORS REQUIRED.			
<b>Contractor:</b> ALLEY & COMPANY INC			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 3	<b>Activity Code:</b> M1 HEATING/AIRCONDITION	
<b>Valuation:</b> \$5,000.00	<b>Fees Req:</b> \$202.00	<b>Fees Col:</b> \$202.00	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0900046	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 01602630100000	<b>Applied:</b> 01/02/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 1294 NOONAN DR		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> HVAC C/O SPLIT SYSTEM. PROVIDE ALL DOCUMENTS FOR FINAL INSPECTION. SMOKE DETECTORS REQUIRED.			
<b>Contractor:</b> ALLEY & COMPANY INC			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 2	<b>Activity Code:</b> M1 HEATING/AIRCONDITION	
<b>Valuation:</b> \$5,466.00	<b>Fees Req:</b> \$204.19	<b>Fees Col:</b> \$204.19	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0900047	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 26201820110000	<b>Applied:</b> 01/02/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 302 HAGGIN AVE		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> C/O WALL FUNANCE, HOT WATER TAKER TANK, PROVIDE ALL DOCUMENTS FOR FINAL INSPECTION. SMOKE DETECTORS REQUIRED.			
<b>Contractor:</b> ALLEY & COMPANY INC			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> M3 FURNACE	
<b>Valuation:</b> \$5,925.00	<b>Fees Req:</b> \$96.37	<b>Fees Col:</b> \$96.37	<b>Bal Due:</b> \$0.00

<b>Activity:</b> RES-0900048	<b>Type:</b> Building / Residential / Minor / Single Family		
<b>Parcel:</b> 27403740030000	<b>Applied:</b> 01/02/2009	<b>Issued:</b> 01/02/2009	<b>Finalized:</b>
<b>Site Address:</b> 1526 WATERWHEELDR		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> C/O CONDENSER & AIR HANDLER LIKE FOR LIKE. PROVIDE ALL DOCUMENTS FOR FINAL INSPECTION. SMOKE DETECTORS REQUIRED.			
<b>Contractor:</b> ALLEY & COMPANY INC			
<b>Occupancy:</b> R3	<b>Insp Area:</b> 4	<b>Activity Code:</b> M1 HEATING/AIRCONDITION	
<b>Valuation:</b> \$9,385.00	<b>Fees Req:</b> \$213.75	<b>Fees Col:</b> \$213.75	<b>Bal Due:</b> \$0.00

<b>Activity:</b> SIG-0813122	<b>Type:</b> Building / Sign / 1-5 / NA		
<b>Parcel:</b> 00602740130000	<b>Applied:</b> 10/01/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 1001 R ST		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

**Description:** 1 sign, d/f, illuminated attached blade / projecting sign located over a public right-a-way, copy; Fox & Goose Restaurant & Pub; Public House  
Requires special inspection and Revocable encroachment permit.

**Contractor:** PACIFICNEON

<b>Occupancy:</b>	<b>Insp Area:</b> 1	<b>Activity Code:</b>	
<b>Valuation:</b> \$969.50	<b>Fees Req:</b> \$929.79	<b>Fees Col:</b> \$929.79	<b>Bal Due:</b> \$0.00

**Activity:** SIG-0816458

**Type:** Building / Sign / 1-5 / NA

**Parcel:** 29503900060000

**Applied:** 12/10/2008

**Issued:** 12/30/2008

**Finalized:**

**Site Address:** 9 PARK CENTER DR

**# Units:** 0.00

**Sq Ft:**

**Location:**

**Description:** 1 sign, d/f, illuminated detached monument at existing location, 22.1 sq ft, copy; Bank of America & logo

**Contractor:**

<b>Occupancy:</b>	<b>Insp Area:</b> 1	<b>Activity Code:</b>	
<b>Valuation:</b> \$884.00	<b>Fees Req:</b> \$899.75	<b>Fees Col:</b> \$899.75	<b>Bal Due:</b> \$0.00

**Activity:** SIG-0816463

**Type:** Building / Sign / 1-5 / NA

**Parcel:** 27400600240000

**Applied:** 12/10/2008

**Issued:** 12/30/2008

**Finalized:**

**Site Address:** 1590 W EL CAMINO AVE

**# Units:** 0.00

**Sq Ft:**

**Location:**

**Description:** 5 signs total: 1 sign, d/f, detached illuminated, monument, reface, copy; Bank of America / logo: 3 signs, s/f, attached illuminated, 40.9 sf copy; Bank of America / logo: 1 sign, s/f, attached illuminated, 28.3 sf copy; Bank of America / logo

**Contractor:** SIGN PRODUCTIONS INC

<b>Occupancy:</b>	<b>Insp Area:</b> 4	<b>Activity Code:</b>	
<b>Valuation:</b> \$6,617.00	<b>Fees Req:</b> \$1,059.17	<b>Fees Col:</b> \$1,059.17	<b>Bal Due:</b> \$0.00

**Activity:** SIG-0816476

**Type:** Building / Sign / 1-5 / NA

**Parcel:** 27500950040000

**Applied:** 12/10/2008

**Issued:** 12/30/2008

**Finalized:**

**Site Address:** 1830 DEL PASO BLVD

**# Units:** 0.00

**Sq Ft:**

**Location:**

**Description:** 3 signs total: 1 sign, d/f, reface existing pole detached illuminated, copy; Bank of America / logo: 2 signs s/f, attached illuminated, copy; Bank of America / logo

**Contractor:** SIGN PRODUCTIONS INC

<b>Occupancy:</b>	<b>Insp Area:</b> 4	<b>Activity Code:</b>	
<b>Valuation:</b> \$5,112.00	<b>Fees Req:</b> \$1,149.04	<b>Fees Col:</b> \$1,149.04	<b>Bal Due:</b> \$0.00

**Activity:** SIG-0816484

**Type:** Building / Sign / 1-5 / NA

**Parcel:** 01301540330000

**Applied:** 12/10/2008

**Issued:** 12/30/2008

**Finalized:**

**Site Address:** 3810 BROADWAY

**# Units:** 0.00

**Sq Ft:**

**Location:**

**Description:** 3 signs: 2 signs, d/f, attached illuminated, 70.6 sf, copy, Bank of America / logo., 1 new awning w/ exterior ATM window, s/f, attached illuminated, 99.5 sf, copy, Bank of America / logo.

**Contractor:** SIGN PRODUCTIONS INC

<b>Occupancy:</b>	<b>Insp Area:</b> 3	<b>Activity Code:</b>	
<b>Valuation:</b> \$8,424.00	<b>Fees Req:</b> \$1,298.93	<b>Fees Col:</b> \$1,298.93	<b>Bal Due:</b> \$0.00

**Activity:** SIG-0816488

**Type:** Building / Sign / 1-5 / NA

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

<b>Parcel:</b> 00701220090000	<b>Applied:</b> 12/10/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 1100 ALHAMBRA BLVD		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> 2 signs: 1 sign, attached illuminated, s/f, 43.7 sf, copy, Bank of America / logo, 1 sign, attached illuminated, s/f, 27.8 sf, copy, Bank of America / logo,			
<b>Contractor:</b> SIGN PRODUCTIONS INC			
<b>Occupancy:</b>	<b>Insp Area:</b> 1	<b>Activity Code:</b>	
<b>Valuation:</b> \$2,502.50	<b>Fees Req:</b> \$999.44	<b>Fees Col:</b> \$999.44	<b>Bal Due:</b> \$0.00

<b>Activity:</b> SIG-0816490	<b>Type:</b> Building / Sign / 1-5 / NA		
<b>Parcel:</b> 00601450250000	<b>Applied:</b> 12/10/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 555 CAPITOL MALL		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> 3 signs: 2 sign, attached illuminated, s/f, wall mount, 69.8 sf, copy, Bank of America / logo, 1 sign, attached illuminated, s/f, 15.3 sf, copy, Bank of America / logo.			
<b>Contractor:</b> SIGN PRODUCTIONS INC			
<b>Occupancy:</b>	<b>Insp Area:</b> 1	<b>Activity Code:</b>	
<b>Valuation:</b> \$5,421.00	<b>Fees Req:</b> \$1,149.17	<b>Fees Col:</b> \$1,149.17	<b>Bal Due:</b> \$0.00

<b>Activity:</b> SIG-0816510	<b>Type:</b> Building / Sign / 1-5 / NA		
<b>Parcel:</b> 00902610100000	<b>Applied:</b> 12/10/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 1515 BROADWAY		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> 3 signs, attached illuminated, s/f, each sign is 50.3 sf, copy, Bank of America / logo			
<b>Contractor:</b> SIGN PRODUCTIONS INC			
<b>Occupancy:</b>	<b>Insp Area:</b> 1	<b>Activity Code:</b>	
<b>Valuation:</b> \$5,281.00	<b>Fees Req:</b> \$1,149.11	<b>Fees Col:</b> \$1,149.11	<b>Bal Due:</b> \$0.00

<b>Activity:</b> SIG-0816515	<b>Type:</b> Building / Sign / 1-5 / NA		
<b>Parcel:</b> 01701210560000	<b>Applied:</b> 12/10/2008	<b>Issued:</b> 12/30/2008	<b>Finalized:</b>
<b>Site Address:</b> 4740 FREEPORT BLVD		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> 3 SIGNS TOTAL: 1 SIGN, S/F Bank of America / logo ATTACHED ILLUMINATED WALL CABINET, 122.2 SF, COPY, Bank of America / logo, 1 SIGN, S/F ATTACHED ILLUMINATED FASCIA SIGN CABINET, 60.6 SF, COPY, Bank of America / logo, 1 SIGN, D/F PYLON SIGN, DETACHED ILLUMINATED, 112.2 SF, COPY,			
<b>Contractor:</b> SIGN PRODUCTIONS INC			
<b>Occupancy:</b>	<b>Insp Area:</b> 2	<b>Activity Code:</b>	
<b>Valuation:</b> \$10,886.00	<b>Fees Req:</b> \$1,118.95	<b>Fees Col:</b> \$1,118.95	<b>Bal Due:</b> \$0.00

<b>Activity:</b> SIG-0817105	<b>Type:</b> Building / Sign / 1-5 / NA		
<b>Parcel:</b> 03109000610000	<b>Applied:</b> 12/29/2008	<b>Issued:</b> 12/31/2008	<b>Finalized:</b>
<b>Site Address:</b> 7465 RUSH RIVER DR		<b># Units:</b> 0.00	<b>Sq Ft:</b>
<b>Location:</b>			
<b>Description:</b> 1 sign, s/f, attached illuminated cabinet sign, copy; Peets Coffee & Tea			
<b>Contractor:</b> WESTERN SIGN COMPANY INC			
<b>Occupancy:</b>	<b>Insp Area:</b> 2	<b>Activity Code:</b>	
<b>Valuation:</b> \$605.50	<b>Fees Req:</b> \$339.64	<b>Fees Col:</b> \$339.64	<b>Bal Due:</b> \$0.00

---

01/05/2009  
09:44:33 AM

**Activity Data Report**  
**City of Sacramento, CA**  
**ISSUED between 12/28/2008 and 01/03/2009**

---

Page 37