08:59:34 AM

Activity Data Report 02/23/2009 Page 1

City of Sacramento, CA ISSUED between 02/15/2009 and 02/21/2009

Activity: 0609191 Type: Building / Commercial / Remodel / Office

Parcel: 00600470110000 Applied: 06/20/2006 Issued: 09/28/2006 Finaled: 02/20/2009

Site Address: 921 11TH ST # Units: 0.00 Sq Ft: 3,200

Location:

Description: REMODEL: INSTALLATION OF DEMISING WALL/HVAC DUCT, CEILING & LIGHTING (3200 SQ FT)

Contractor: JOHN F OTTO

Occupancy: B Insp Area: 1 Activity Code: 12

Valuation: \$172.800.00 Fees Col: \$3,285,12 Bal Due: \$0.00 Fees Req: \$3,285.12

Activity: COM-0813833 Type: Building / Commercial / Fire Equipment / Apts 5+

Parcel: 00600320290000 Applied: 10/15/2008 Issued: 02/20/2009 Finaled:

Site Address: 600 I ST 1001 # Units: 0.00 Sq Ft: 97,000

Location:

Description: REPLACE FIRE ALARM SYSTEM, WIRING, AND FIELD DEVICES THROUGHOUT APT COMPLEX

Contractor:

Occupancy: R1 Insp Area: 1 Activity Code: Z12 FIRE ALARM/SMOKE DET

Valuation: \$417,603.00 Fees Col: \$11,618.84 Fees Req: \$11,618.84 Bal Due: \$0.00

Type: Building / Commercial / Repair-Maintenance / Office Activity: COM-0815039

Parcel: 11701700860000 Applied: 11/10/2008 Issued: 02/19/2009 Finaled:

Site Address: 6600 BRUCEVILLE RD # Units: 0.00 Sq Ft: 0

Location:

Description: PROVIDE POWER TO (2) NEW FLOOR MOUNTED TELECOM RACKS. POWER CONSISTS OF 4 NEW DOUBLE DUPLEX

RECEPTACLES. TWO NEW SLEEVES FOR THROUGH WALL PENETRATIONS SHALL ALSO BE INSTALLED FOR FUTURE

Contractor: KAISER FOUNDATION HEALTH PLAN INC

Activity Code: E10 ELEC EQUIPMENT INSTALL Occupancy: NA Insp Area: 2 Valuation: \$25,000.00 Fees Req: \$1,138.37 Fees Col: \$1,138.37 Bal Due: \$0.00

Type: Building / Facilities Permit Program / Remodel / Office Activity: COM-0816539

Parcel: 00601020070000 Applied: 12/11/2008 Issued: 02/17/2009 Finaled:

Site Address: 925 L ST # Units: 0.00 Sq Ft: 1,416

Location:

Description: FPP permit for suite 325, demolition of ceiling tiles, interior partitions, constructing new partitions with related electrical.

Mechanical to reuse existing. Non-sprinklered building. (Fire inspections Com-0816540)

Contractor: DESCOR BUILDERS

Occupancy: B Insp Area: 1 Activity Code: 12 INTERIOR REM-TI/COM

Valuation: \$49,555.00 Fees Req: \$2,224.23 Fees Col: \$2,224.23 Bal Due: \$0.00

Type: Building / Facilities Permit Program / Fire Equipment / Office Activity: COM-0816540

Parcel: 00601020070000 Applied: 12/11/2008 Issued: 02/17/2009 Finaled:

Site Address: 925 L ST # Units: 0.00 Sq Ft: 0

Location:

Description: FPP PERMIT FOR FIRE ALARM INSPECTIONS BASE PERMIT COM-0816539, NON-SPRINKLERED BUILDING

Contractor:

Activity Data Report 02/23/2009 City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Occupancy: B Insp Area: 1 Activity Code: 12 INTERIOR REM-TI/COM

Valuation: \$0.00 Fees Col: \$0.00 Fees Req: \$0.00 Bal Due: \$0.00

Activity: COM-0900334 Type: Building / Commercial / New Structural / Other Struct (non-bldg)

Parcel: 23802200110000 Applied: 01/09/2009 Issued: 02/19/2009 Finaled:

Site Address: 1855 DIESEL DR # Units: 0.00 Sq Ft: 391

Location:

08:59:34 AM

Description: Install spray booth with fire sprinklers.

Contractor: SIMPLEX GRINNELL LP

Occupancy: H1 Insp Area: 4 Activity Code: 17 PAINT SPRAY BOOTH

Valuation: \$7,500.00 Fees Req: \$1,676.56 Fees Col: \$1,676.56 Bal Due: \$0.00

Activity: COM-0900406 Type: Building / Facilities Permit Program / Tenant Improvement / Office

Parcel: 26502930240000 Applied: 01/12/2009 Issued: 02/17/2009 Finaled:

Site Address: 2400 DEL PASO BLVD # Units: 0.00 Sq Ft: 680

Location:

Description: FPP-REMODEL OF EXISTING OFFICE SPACE, SUITE 255 AND SPRINKLERS (FOR FIRE PERMIT COM-0900410)

Contractor: HEADWATERSCONSTRUCTION INC.

Occupancy: B Activity Code: 12 INTERIOR REM-TI/COM Insp Area: 4

Valuation: \$31,000.00 Fees Req: \$1,729.31 Fees Col: \$0.00 Bal Due: \$1,729.31

Activity: COM-0900410 Type: Building / Facilities Permit Program / Fire Equipment / Office

Parcel: 22500701300000 Applied: 01/13/2009 Issued: 02/17/2009 Finaled: Site Address: 2400 DEL PASORD # Units: 0.00 Sq Ft:

Location:

Description: FPP-REMODEL OF EXISTING T.I.AND SPRINKLERS (FOR BASE PERMIT COM-0900406)

Contractor: HEADWATERSCONSTRUCTION INC.

Occupancy: Insp Area: 4 **Activity Code:**

Valuation: \$0.00 Fees Req: \$210.00 Fees Col: \$0.00 Bal Due: \$210.00

Type: Building / Facilities Permit Program / Tenant Improvement / Retail Store Activity: COM-0900655

Parcel: 00700830030000 Applied: 01/20/2009 Issued: 02/19/2009 Finaled:

Units: 0.00 Site Address: 1050 20TH ST Sq Ft: 2,011

Location:

Description: FPP TENANT IMPROVEMENT FOR RETAIL YOGA EXERCISE STUDIO STE. 110(FOR FIRE INSPECTIONS COM-0900662)

Contractor: CAPITOL PAINTING AND SERVICES

Activity Code: 12 INTERIOR REM-TI/COM Occupancy: B Insp Area: 1

Valuation: \$50,000.00 Fees Req: \$1,098.50 Fees Col: \$0.00 Bal Due: \$1,098.50

Activity: COM-0900662 Type: Building / Facilities Permit Program / Fire Equipment / Retail Store

Parcel: 00700830030000 Applied: 01/20/2009 Issued: 02/19/2009 Finaled:

Site Address: 1050 20TH ST # Units: 0.00 Sq Ft: 2,011

Description: FPP PERMIT FOR FIRE INSPECTIONS ONLY SEE BASE PERMIT COM-0900655

Page 2

02/23/2009 Activity Data Report Page 3

08:59:34 AM

City of Sacramento, CA ISSUED between 02/15/2009 and 02/21/2009

Contractor:

Occupancy: B Insp Area: 1 Activity Code: P9 OVERHEAD FIRE SPRKLR

Valuation: \$0.00 Fees Req: \$0.00 Fees Col: \$0.00 Bal Due: \$0.00

Activity: COM-0900885 Type: Building / Facilities Permit Program / Remodel / Office

Site Address: 300 CAPITOL MALL **# Units:** 0.00 **Sq Ft:** 6,570

Location:

Description: FPP REMODEL SUITE 1125 LIMITED TO INTERIOR MODIFICATION WITH SOME ADDITIONS AND DEMOLITION. (FOR FIRE

INSPECTION SEE COM-0900886)

Contractor: ICON GENERAL CONTRACTORS INC

Occupancy: B Insp Area: 1 Activity Code: 12 INTERIOR REM-TI/COM

Valuation: \$35,000.00 Fees Req: \$748.55 Fees Col: \$0.00 Bal Due: \$748.55

Activity: COM-0900886 Type: Building / Facilities Permit Program / Fire Equipment / Office

Site Address: 300 CAPITOL MALL # Units: 0.00 Sq Ft: 6,570

Location:

Description: FPP PERMIT FOR FIRE ALARM AND FIRE SPRINKLER INPECTIONS SUITE 1125 (RELATED TO COM-0900885)

Contractor:

Occupancy: B Insp Area: 1 Activity Code: 12 INTERIOR REM-TI/COM

Valuation: \$0.00 Fees Req: \$0.00 Fees Col: \$0.00 Bal Due: \$0.00

Activity: COM-0901013 Type: Building / Commercial / Fire Equipment / Retail Store

Parcel: 25000100600000 **Applied**: 01/29/2009 **Issued**: 02/18/2009 **Finaled**:

Site Address: 3773 NORTHGATEBLVD # Units: 0.00 Sq Ft: 0

Location:

Description: Hood system upgrade to UL-300 compliance **Contractor:** SENTINEL FIRE EQUIPMENT COMPANY

Occupancy: B Insp Area: 4 Activity Code: P11 FIRE HOOD SYSTEM

Valuation: \$3,000.00 Fees Req: \$521.00 Fees Col: \$521.00 Bal Due: \$0.00

Activity: COM-0901352 Type: Building / Facilities Permit Program / Remodel / Office

Parcel: 27702860270000 **Applied:** 02/06/2009 **Issued:** 02/17/2009 **Finaled:**

 Site Address:
 1425 RIVER PARK DR 300
 # Units:
 0.00
 Sq Ft:
 7,515

Location:

Description: FPP: INTERIOR OFFICE REMODEL OF 7515 SQ FT FOR THE DEPT. OF JUSTICE, SUITE 300 (NO CITY FIRE REVIEW OR

INSPECTIONS: EXISTING STATETENANT)

Contractor: PARRETTBOB CONSTRUCTION INC

Occupancy: B Insp Area: 4 Activity Code: 12 INTERIOR REM-TI/COM

Valuation: \$188,000.00 Fees Req: \$0.00 Fees Col: \$0.00 Bal Due: \$0.00

Activity: COM-0901437 Type: Building / Commercial / Remodel / Apts 5+

Parcel: 01500410090000 Applied: 02/10/2009 Issued: 02/19/2009 Finaled:

Site Address: 5200 BROADWAY #Units: 0.00 Sq Ft: 0

Location:

08:59:34 AM

Activity Data Report 02/23/2009 Page 4

City of Sacramento, CA ISSUED between 02/15/2009 and 02/21/2009

Description: Bldg. 1 (6 units) - REPLACE hot/cold copper water lines w/PEX piping in all units for "Broadway Senior Apartments"

Contractor: WILLS PLUMBING

Occupancy: R1 Insp Area: 3 Activity Code: P1 WATER SERVICE

Valuation: \$9,499.98 Fees Req: \$753.40 Fees Col: \$753.40 Bal Due: \$0.00

Type: Building / Commercial / Housing-Minor / Apts 5+ Activity: COM-0901518

Parcel: 00702730110000 Applied: 02/12/2009 Issued: 02/19/2009 Finaled: Site Address: 2827 O ST # Units: 0.00 Sq Ft:

Location:

Description: Repair existing stairwell and egress per Historic Preservation conditions of approval, and building code standards.THIS PERMIT

WAS ISSUED BY DSD IN ERROR (PERMIT # COM-0900569) THIS IS AN HDB HOUSING CASE. ALL VIOLATIONS ON THE HOUSING VIOLATIONS LIST MUST BE REPAIRED. THE HOUSING SURCHARGE WILL BE ADDED TO NEW PERMIT. CASE #

08-091348 A NEW PERMIT WILL BE RE-ISSUED

Contractor: BENCKEN DAN RECONSTRUCTION

Occupancy: R3 Insp Area: 1 Activity Code: C4 HOUSING CASES

Valuation: \$22,000.00 Fees Req: \$1,225.12 Fees Col: \$1,225.12 Bal Due: \$0.00

Activity: COM-0901532 Type: Building / Commercial / Repair-Maintenance / Apts 5+

Parcel: 01500410090000 Applied: 02/12/2009 Issued: 02/19/2009 Finaled: Site Address: 5200 BROADWAY # Units: 0.00 Sq Ft: 0

Location:

Description: Bldg. #2 (4 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOTTO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Insp Area: 3 Activity Code: P1 WATER SERVICE Occupancy: R1

Valuation: \$6,333.32 Fees Req: \$359.69 Fees Col: \$359.69 Bal Due: \$0.00

Type: Building / Commercial / Repair-Maintenance / Apts 5+ Activity: COM-0901533

Parcel: 01500410090000 Applied: 02/12/2009 Issued: 02/19/2009 Finaled:

Site Address: 5200 BROADWAY # Units: 0.00 Sq Ft:

Location:

Description: Bldg. #3 (4 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOT TO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Activity Code: P1 WATER SERVICE Occupancy: R1 Insp Area: 3

Valuation: \$6,333.32 Fees Req: \$359.69 Fees Col: \$359.69 Bal Due: \$0.00

Type: Building / Commercial / Repair-Maintenance / Apts 5+ Activity: COM-0901534

Parcel: 01500410090000 Applied: 02/12/2009 Issued: 02/19/2009 Finaled: Site Address: 5200 BROADWAY # Units: 0.00 Sq Ft: 0

Location:

Description: Bldg. #4 (4 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOT TO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Activity Code: P1 WATER SERVICE Occupancy: R1 Insp Area: 3

Valuation: \$6,333.32 Fees Req: \$359.69 Fees Col: \$359.69 Bal Due: \$0.00 08:59:34 AM

Activity Data Report 02/23/2009 Page 5 City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Activity: COM-0901535 Type: Building / Commercial / Repair-Maintenance / Apts 5+

Parcel: 01500410090000 Issued: 02/19/2009 Applied: 02/12/2009 Finaled:

Site Address: 5200 BROADWAY # Units: 0.00 Sq Ft: 0

Location:

Description: Bldg. #5 (6 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOTTO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Activity Code: P1 WATER SERVICE Occupancy: R1 Insp Area: 3

Valuation: \$9,499.98 Fees Col: \$427.44 Fees Req: \$427.44 Bal Due: \$0.00

Type: Building / Commercial / Repair-Maintenance / Apts 5+ Activity: COM-0901536

Issued: 02/19/2009 Parcel: 01500410090000 Applied: 02/12/2009 Finaled:

Site Address: 5200 BROADWAY # Units: 0.00 Sq Ft:

Location:

Description: Bldg. #6 (4 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOT TO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Occupancy: R1 Insp Area: 3 Activity Code: P1 WATER SERVICE

Valuation: \$6,333.32 Fees Req: \$359.69 Fees Col: \$359.69 Bal Due: \$0.00

Activity: COM-0901537 Type: Building / Commercial / Repair-Maintenance / Apts 5+

Applied: 02/12/2009 Issued: 02/19/2009 Parcel: 01500410090000 Finaled: 0

Site Address: 5200 BROADWAY # Units: 0.00 Sq Ft:

Location:

Description: Bldg. #7 (6 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOTTO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Occupancy: R1 Insp Area: 3 Activity Code: P1 WATER SERVICE

Valuation: \$9,499.98 Fees Req: \$427.44 Fees Col: \$427.44 Bal Due: \$0.00

Type: Building / Commercial / Repair-Maintenance / Apts 5+ Activity: COM-0901538

Parcel: 01500410090000 Issued: 02/19/2009 Applied: 02/12/2009 Finaled:

Site Address: 5200 BROADWAY # Units: 0.00 Sq Ft: 0

Location:

Description: Bldg. #8 (4 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOT TO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Occupancy: R1 Insp Area: 3 Activity Code: P1 WATER SERVICE

Applied: 02/12/2009

Valuation: \$6,333.32 Fees Req: \$359.69 Fees Col: \$359.69 Bal Due: \$0.00

Type: Building / Commercial / Repair-Maintenance / Apts 5+ Activity: COM-0901539

Issued: 02/19/2009

Finaled:

Site Address: 5200 BROADWAY # Units: 0.00 Sq Ft: 0

Location:

Description: Bldg. #9 (4 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOTTO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Parcel: 01500410090000

Activity Data Report 02/23/2009 Page 6 City of Sacramento, CA 08:59:34 AM

ISSUED between 02/15/2009 and 02/21/2009

Occupancy: R1 Insp Area: 3 Activity Code: P1 WATER SERVICE

Fees Col: \$359.69 Valuation: \$6,333.32 Fees Req: \$359.69 Bal Due: \$0.00

Type: Building / Commercial / Repair-Maintenance / Apts 5+ Activity: COM-0901540

Parcel: 01500410090000 Applied: 02/12/2009 Issued: 02/19/2009 Finaled:

Site Address: 5200 BROADWAY # Units: 0.00 Sq Ft:

Location:

Description: Bldg. #10 (4 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOTTO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Occupancy: R1 Insp Area: 3 Activity Code: P1 WATER SERVICE

Fees Req: \$359.69 Fees Col: \$359.69 Valuation: \$6,333.32 Bal Due: \$0.00

Activity: COM-0901541 Type: Building / Commercial / Repair-Maintenance / Apts 5+

Parcel: 01500410090000 Applied: 02/12/2009 Issued: 02/19/2009 Finaled:

Site Address: 5200 BROADWAY # Units: 0.00 Sq Ft: 0

Location:

Description: Bldg. #11 (6 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOTTO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Occupancy: R1 Insp Area: 3 Activity Code: P1 WATER SERVICE

Valuation: \$9,499.98 Fees Req: \$427.44 Fees Col: \$427.44 Bal Due: \$0.00

Type: Building / Commercial / Repair-Maintenance / Apts 5+ Activity: COM-0901542

Parcel: 01500410090000 Applied: 02/12/2009 Issued: 02/19/2009 Finaled:

Site Address: 5200 BROADWAY # Units: 0.00 Sq Ft: 0

Location:

Description: Bldg. #12 (4 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOTTO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Occupancy: R1 Insp Area: 3 Activity Code: P1 WATER SERVICE

Valuation: \$6,333.32 Fees Req: \$359.69 Fees Col: \$359.69 Bal Due: \$0.00

Type: Building / Commercial / Repair-Maintenance / Apts 5+ Activity: COM-0901543

Issued: 02/19/2009 Parcel: 01500410090000 Applied: 02/12/2009 Finaled:

Site Address: 5200 BROADWAY # Units: 0.00 Sq Ft:

Location:

Description: Bldg. #13 (4 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOTTO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Activity Code: P1 WATER SERVICE Occupancy: R1 Insp Area: 3

Valuation: \$6,333.32 Fees Req: \$359.69 Fees Col: \$359.69 Bal Due: \$0.00

Activity: COM-0901544 Type: Building / Commercial / Repair-Maintenance / Apts 5+

Parcel: 01500410090000 Applied: 02/12/2009 Issued: 02/19/2009 Finaled:

Site Address: 5200 BROADWAY # Units: 0.00 Sq Ft: 0

Location:

Activity Data Report 02/23/2009

City of Sacramento, CA ISSUED between 02/15/2009 and 02/21/2009

Description: Bldg. #14 (6 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOTTO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Occupancy: R1 Insp Area: 3 Activity Code: P1 WATER SERVICE

Valuation: \$9,499.98 Fees Req: \$427.44 Fees Col: \$427.44 Bal Due: \$0.00

Activity: COM-0901545 Type: Building / Commercial / Repair-Maintenance / Apts 5+

Applied: 02/12/2009 Issued: 02/19/2009 Parcel: 01500410090000 Finaled:

Site Address: 5200 BROADWAY # Units: 0.00 Sq Ft: 0

Location:

Description: Bldg. #15 (4 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOTTO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Occupancy: R1 Insp Area: 3 Activity Code: P1 WATER SERVICE

Valuation: \$6,333.32 Fees Req: \$359.69 Fees Col: \$359.69 Bal Due: \$0.00

Type: Building / Commercial / Repair-Maintenance / Apts 5+ Activity: COM-0901546

Parcel: 01500410090000 Applied: 02/12/2009 Issued: 02/19/2009 Finaled:

Site Address: 5200 BROADWAY # Units: 0.00 Sq Ft:

Location:

Description: Bldg. #16 (4 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOTTO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Insp Area: 3 Activity Code: P1 WATER SERVICE Occupancy: R1

Valuation: \$6,333.32 Fees Req: \$359.69 Fees Col: \$359.69 Bal Due: \$0.00

Activity: COM-0901547 Type: Building / Commercial / Repair-Maintenance / Apts 5+

Parcel: 01500410090000 Applied: 02/12/2009 Issued: 02/19/2009 Finaled:

Site Address: 5200 BROADWAY # Units: 0.00 Sq Ft: 0

Location:

Description: Bldg. #17 (4 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOTTO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Occupancy: R1 Insp Area: 3 Activity Code: P1 WATER SERVICE

Valuation: \$6,333.32 Fees Req: \$359.69 Fees Col: \$359.69 Bal Due: \$0.00

Type: Building / Commercial / Repair-Maintenance / Apts 5+ Activity: COM-0901548

Parcel: 01500410090000 Applied: 02/12/2009 Issued: 02/19/2009 Finaled:

Site Address: 5200 BROADWAY # Units: 0.00 Sq Ft:

Location:

Description: Bldg. #18 (4 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOTTO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Occupancy: R1 Insp Area: 3 Activity Code: P1 WATER SERVICE

Valuation: \$6,333.32 Fees Col: \$359.69 Fees Req: \$359.69 Bal Due: \$0.00

Activity: COM-0901549 Type: Building / Commercial / Repair-Maintenance / Apts 5+

Page 7

Activity Data Report
City of Sacramento, CA
ISSUED between 02/15/2009 and 02/21/2009

Page 8

Site Address: 5200 BROADWAY #Units: 0.00 Sq Ft: 0

Location:

Description: Bldg. #19 (6 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOTTO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Occupancy: R1 Insp Area: 3 Activity Code: P1 WATER SERVICE

Valuation: \$9,499.98 Fees Req: \$427.44 Fees Col: \$427.44 Bal Due: \$0.00

Activity: COM-0901550 Type: Building / Commercial / Repair-Maintenance / Apts 5+

Site Address: 5200 BROADWAY #Units: 0.00 Sq Ft: 0

Location:

Description: Bldg. #20 (4 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOTTO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Occupancy: R1 Insp Area: 3 Activity Code: P1 WATER SERVICE

Valuation: \$6,333.32 Fees Req: \$359.69 Fees Col: \$359.69 Bal Due: \$0.00

Activity: COM-0901551 Type: Building / Commercial / Repair-Maintenance / Apts 5+

Parcel: 01500410090000 **Applied**: 02/12/2009 **Issued**: 02/19/2009 **Finaled**:

Site Address: 5200 BROADWAY # Units: 0.00 Sq Ft: 0

Location:

Description: Bldg. #21 (6 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOTTO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Occupancy: R1 Insp Area: 3 Activity Code: P1 WATER SERVICE

Valuation: \$9,499.98 Fees Req: \$427.44 Fees Col: \$427.44 Bal Due: \$0.00

Activity: COM-0901552 Type: Building / Commercial / Repair-Maintenance / Apts 5+

Site Address: 5200 BROADWAY # Units: 0.00 Sq Ft: 0

Location:

Description: Bldg. #22 (4 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOTTO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Occupancy: R1 Insp Area: 3 Activity Code: P1 WATER SERVICE

Valuation: \$6,333.32 Fees Req: \$359.69 Fees Col: \$359.69 Bal Due: \$0.00

Activity: COM-0901553 Type: Building / Commercial / Repair-Maintenance / Apts 5+

Parcel: 01500410090000 **Applied:** 02/12/2009 **Issued:** 02/19/2009 **Finaled:**

Site Address: 5200 BROADWAY # Units: 0.00 Sq Ft: 0

Location:

Description: Bldg. #23 (6 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOTTO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Occupancy: R1 Insp Area: 3 Activity Code: P1 WATER SERVICE

Activity Data Report
City of Sacramento, CA
ISSUED between 02/15/2009 and 02/21/2009

Page 9

 Valuation:
 \$9,499.98
 Fees Req:
 \$427.44
 Fees Col:
 \$427.44
 Bal Due:
 \$0.00

Activity: COM-0901554 Type: Building / Commercial / Repair-Maintenance / Apts 5+

Parcel: 01500410090000 **Applied**: 02/12/2009 **Issued**: 02/19/2009 **Finaled**:

Site Address: 5200 BROADWAY **# Units:** 0.00 **Sq Ft:** 0

Location:

Description: Bldg. #24 (6 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOTTO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Occupancy: R1 Insp Area: 3 Activity Code: P1 WATER SERVICE

Valuation: \$9,499.98 Fees Req: \$427.44 Fees Col: \$427.44 Bal Due: \$0.00

Activity: COM-0901555 Type: Building / Commercial / Repair-Maintenance / Apts 5+

Site Address: 5200 BROADWAY #Units: 0.00 Sq Ft: 0

Location:

Description: Bldg. #25 (6 units) - REPLACE existing copper hot/cold water lines with PEX piping (NOTTO INCLUDE UNDERGROUND

PLUMBING) (REVIEW COMPLETED UNDER #COM-0901437)

Contractor: WILLS PLUMBING

Occupancy: R1 Insp Area: 3 Activity Code: P1 WATER SERVICE

Valuation: \$9,499.98 Fees Req: \$427.44 Fees Col: \$427.44 Bal Due: \$0.00

Activity: COM-0901557 Type: Building / Commercial / Minor / Apts 3-4

 Parcel: 29501800150000
 Applied: 02/12/2009
 Issued: 02/18/2009
 Finaled: 02/18/2009

 Site Address: 1306 VANDERBILTWAY
 # Units: 3.00
 Sq Ft:

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1306,1312, 1318 VANDERBUILTWY (1)

Contractor: DRAEGER CONSTRUCTION INC

 Occupancy:
 R1
 Insp Area:
 1
 Activity Code:
 C6 TERMITE/DRY ROT REPAIR

 Valuation:
 \$5,280.00
 Fees Req:
 \$264.62
 Fees Col:
 \$264.62
 Bal Due:
 \$0.00

Activity: COM-0901558 Type: Building / Commercial / Minor / Apts 3-4

 Parcel: 29501800050000
 Applied: 02/12/2009
 Issued: 02/18/2009
 Finaled: 02/18/2009

 Site Address: 1324 VANDERBILTWAY
 # Units: 4.00
 Sq Ft:

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1324,1330, 1336,1342 VANDERBUILTWY (2)

Contractor: DRAEGER CONSTRUCTION INC

Occupancy:R1Insp Area:1Activity Code:C6 TERMITE/DRY ROT REPAIRValuation:\$7,040.00Fees Req:\$315.06Fees Col:\$315.06Bal Due:\$0.00

Activity: COM-0901560 Type: Building / Commercial / Minor / Condos

 Parcel: 29501900210000
 Applied: 02/12/2009
 Issued: 02/18/2009
 Finaled:

 Site Address: 1206 VANDERBILTWAY
 # Units: 2.00
 Sq Ft:

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1206,1212,VANDERBUILTWY (6)

Contractor: DRAEGER CONSTRUCTION INC

Activity Data Report
City of Sacramento, CA

Page 10

ISSUED between 02/15/2009 and 02/21/2009

Occupancy:R1Insp Area:1Activity Code:C6 TERMITE/DRY ROT REPAIRValuation:\$3,520.00Fees Req:\$205.21Fees Col:\$205.21Bal Due:\$0.00

Activity: COM-0901561 Type: Building / Commercial / Minor / Condos

 Parcel:
 29501600010000
 Applied:
 02/12/2009
 Issued:
 02/18/2009
 Finaled:

 Site Address:
 1311 VANDERBILTWAY
 # Units:
 5.00
 Sq Ft:

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM, 1311, 1317, 1323, 1329 1335 VANDERBUILTWY (7)

Contractor: DRAEGER CONSTRUCTION INC

 Occupancy:
 R1
 Insp Area:
 1
 Activity Code:
 C6 TERMITE/DRY ROT REPAIR

 Valuation:
 \$8,800.00
 Fees Req:
 \$337.54
 Fees Col:
 \$337.54
 Bal Due:
 \$0.00

Activity: COM-0901563 Type: Building / Commercial / Minor / Condos

 Parcel:
 29501700230000
 Applied:
 02/12/2009
 Issued:
 02/20/2009
 Finaled:

 Site Address:
 1149 VANDERBILTWAY
 # Units:
 6.00
 Sq Ft:

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM ,1149,1155,1161,1167,1173& 1179 VANDERBUILTWY (19)

Contractor: DRAEGER CONSTRUCTION INC

 Occupancy:
 R1
 Insp Area:
 1
 Activity Code:
 C6 TERMITE/DRY ROT REPAIR

 Valuation:
 \$10,560.00
 Fees Req:
 \$380.07
 Fees Col:
 \$380.07
 Bal Due:
 \$0.00

Activity: COM-0901581 Type: Building / Commercial / Minor / Condos

 Parcel: 29501800180000
 Applied: 02/13/2009
 Issued: 02/18/2009
 Finaled:

 Site Address: 1268 VANDERBILTWAY
 # Units: 4.00
 Sq Ft:

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1268,1276,11284,1292 VANDERBUILTWY (3)

Contractor: DRAEGER CONSTRUCTION INC

Occupancy:R1Insp Area:1Activity Code:C6 TERMITE/DRY ROT REPAIRValuation:\$7,040.00Fees Req:\$315.06Fees Col:\$315.06Bal Due:\$0.00

Activity: COM-0901584 Type: Building / Commercial / Minor / Condos

 Parcel:
 29501800010000
 Applied:
 02/13/2009
 Issued:
 02/18/2009
 Finaled:

 Site Address:
 1242 VANDERBILTWAY
 # Units:
 4.00
 Sq Ft:

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1242,1248,1254,1260 VANDERBUILTWY (4)

Contractor: DRAEGER CONSTRUCTION INC

 Occupancy:
 R1
 Insp Area:
 1
 Activity Code:
 C6 TERMITE/DRY ROT REPAIR

 Valuation:
 \$7,040.00
 Fees Req:
 \$315.06
 Fees Col:
 \$315.06
 Bal Due:
 \$0.00

Activity: COM-0901590 Type: Building / Commercial / Minor / Condos

 Parcel:
 29501900230000
 Applied:
 02/13/2009
 Issued:
 02/18/2009
 Finaled:

 Site Address:
 1218 VANDERBILTWAY
 # Units:
 4.00
 Sq Ft:

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1218,1224,1230,1236 VANDERBUILTWY (5)

08:59:34 AM

Activity Data Report 02/23/2009 Page 11 City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Contractor: DRAEGER CONSTRUCTION INC

Activity Code: C6 TERMITE/DRY ROT REPAIR Occupancy: R3 Insp Area: 1 Valuation: \$7,040.00 Fees Req: \$315.06 Fees Col: \$315.06 Bal Due: \$0.00

Type: Building / Commercial / Minor / Condos Activity: COM-0901593

Parcel: 29501600120000 Applied: 02/13/2009 Issued: 02/18/2009 Finaled: Site Address: 1287 VANDERBILTWAY # Units: 4.00 Sq Ft:

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1218,1224,1230,1236 VANDERBUILTWY (8)

Contractor: DRAEGER CONSTRUCTION INC

Occupancy: R1 Insp Area: 1 Activity Code: C6 TERMITE/DRY ROT REPAIR Valuation: \$7,040.00 Fees Req: \$315.06 Fees Col: \$315.06 Bal Due: \$0.00

Type: Building / Commercial / Minor / Condos Activity: COM-0901596

Parcel: 29501600160000 Applied: 02/13/2009 Issued: 02/18/2009 Finaled: Site Address: 1281 VANDERBILTWAY # Units: 3.00 Sq Ft:

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1269,1275,1281 VANDERBUILTWY (9)

Contractor: DRAEGER CONSTRUCTION INC

Occupancy: R3 Insp Area: 1 Activity Code: C6 TERMITE/DRY ROT REPAIR Valuation: \$5,280.00 Fees Req: \$264.62 Fees Col: \$264.62 Bal Due: \$0.00

Activity: COM-0901596 Type: Building / Commercial / Minor / Condos

Parcel: 29501600160000 Applied: 02/13/2009 Issued: 02/18/2009 Finaled: Site Address: 1281 VANDERBILTWAY # Units: 3.00 Sq Ft:

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1269,1275,1281 VANDERBUILTWY (9)

Contractor: DRAEGER CONSTRUCTION INC

Occupancy: R3 Activity Code: C6 TERMITE/DRY ROT REPAIR Insp Area: 1 Valuation: \$5,280.00 Fees Req: \$264.62 Fees Col: \$264.62 Bal Due: \$0.00

Activity: COM-0901597 Type: Building / Commercial / Minor / Condos

Parcel: 29501800050000 Applied: 02/13/2009 Issued: 02/18/2009 Finaled: Site Address: 1324 VANDERBILTWAY # Units: 4.00 Sq Ft:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1245,1251, 11257,1263 VANDERBUILTWY (10)

Contractor: DRAEGER CONSTRUCTION INC

Occupancy: R1 Insp Area: 1 Activity Code: C6 TERMITE/DRY ROT REPAIR Valuation: \$7,040.00 Fees Req: \$315.06 Fees Col: \$315.06 Bal Due: \$0.00

Type: Building / Commercial / Minor / Office Activity: COM-0901649

Parcel: 29500400320000 Applied: 02/17/2009 Issued: 02/17/2009 Finaled:

Site Address: 100 HOWE AVE # Units: 0.00 Sq Ft: 0

Description: REROOF. TEAR-OFF. INSTALL SINGLE PLY TPO.

02/23/2009 Activity Data Report Page 12

08:59:34 AM

City of Sacramento, CA ISSUED between 02/15/2009 and 02/21/2009

Contractor: D 7 ROOFING SERVICES INC

Occupancy: B Insp Area: 1 Activity Code: R1 REROOF

Valuation: \$110,574.00 Fees Req: \$1,536.20 Fees Col: \$1,536.20 Bal Due: \$0.00

Activity: COM-0901662 Type: Building / Commercial / Minor / Apts 5+

Site Address: 901 26TH ST # Units: 0.00 Sq Ft: 0

Location:

Description: DRY-ROTREPAIR ON REAR WALL SIDING. **Contractor:** HOME IMPROVEMENT AND REPAIR

Occupancy: R2.1 Insp Area: 1 Activity Code: Z1 VINYL/WOOD SIDING

Valuation: \$3,500.00 Fees Req: \$105.64 Fees Col: \$105.64 Bal Due: \$0.00

Activity: COM-0901664 Type: Building / Commercial / Minor / Apts 5+

 Parcel:
 02901760020000
 Applied:
 02/17/2009
 Issued:
 02/17/2009
 Finaled:
 02/17/2009

 Site Address:
 5981 LAKE CREST WAY 6
 # Units:
 0.00
 Sq Ft:
 0

Location:

Description: CHANGE MAIN BREAKER

Contractor:

Occupancy:R2.2Insp Area:2Activity Code:E10 ELEC EQUIPMENT INSTALLValuation:\$300.00Fees Req:\$84.12Fees Col:\$84.12Bal Due:\$0.00

Activity: COM-0901666 Type: Building / Commercial / Remodel / Retail Store

Parcel: 00902520100000 Applied: 02/17/2009 Issued: 02/17/2009 Finaled:

Site Address: 2422 13TH ST **# Units:** 0.00 **Sq Ft:** 700

Location:

Description: HVAC Change out, 6 units total. **Contractor:** PIONEER MECHANICAL

Occupancy: A3 Insp Area: 1 Activity Code: I2 INTERIOR REM-TI/COM

Valuation: \$42,150.00 Fees Req: \$1,520.15 Fees Col: \$1,520.15 Bal Due: \$0.00

Activity: COM-0901681 Type: Building / Facilities Permit Program / Remodel / Office

 Parcel: 22500700920000
 Applied: 02/17/2009
 Issued: 02/17/2009
 Finaled:

 Site Address: 4400 E COMMERCE WAY
 # Units: 0.00
 Sq Ft: 0

Location:

Description: FPP PERMIT FOR ADDING TWO 30 AMP 120 VOLT CORD DROPS

Contractor: BARNUM & CELILLO ELECTRIC INC

Occupancy: B Insp Area: 4 Activity Code: 12 INTERIOR REM-TI/COM

Valuation: \$900.00 Fees Req: \$0.00 Fees Col: \$0.00 Bal Due: \$0.00

Activity: COM-0901706 Type: Building / Commercial / Minor / Apts 5+

Parcel: 00201240220000 **Applied**: 02/18/2009 **Issued**: 02/18/2009 **Finaled**:

Site Address: 525 13TH ST 6 **# Units:** 0.00 **Sq Ft:** 0

Location:

Activity Data Report Page 13
City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Description: MOVE SINK. REPLACE TUB DRAIN. KITCHEN OUTLETS. CEILING FAN. MICROWAVE OUTLET.

Contractor:

Occupancy: R1 Insp Area: 1 Activity Code: C1 GENERAL REPAIR/FIX-IT

Valuation: \$5,000.00 Fees Req: \$259.40 Fees Col: \$259.40 Bal Due: \$0.00

Activity: COM-0901733 Type: Building / Commercial / Minor / Industrial

Site Address: 6565 BELLEAU WOOD LN # Units: 0.00 Sq Ft: 200

Location:

Description: T/O TEAR OFF / REROOF WITH TPO kinderworld south bldg.

Contractor: BILL'SROOFING

Occupancy: R2.1 Insp Area: 2 Activity Code: R1 REROOF

Valuation: \$7,499.00 Fees Req: \$315.33 Fees Col: \$315.33 Bal Due: \$0.00

Activity: COM-0901740 Type: Building / Commercial / Minor / Retail Store

 Site Address:
 2800 BROADWAY
 # Units:
 0.00
 Sq Ft:
 0

Location:

Description: REPLACE SEWER. TRENCHLESS. **Contractor:** TRENCHLESS COMPANYTHE

Occupancy: B Insp Area: 3 Activity Code: P2 SEWER SERVICE

Valuation: \$21,625.00 Fees Req: \$134.65 Fees Col: \$134.65 Bal Due: \$0.00

Activity: COM-0901744 Type: Building / Commercial / Minor / Condos

 Site Address:
 1418 COMMONS DR
 # Units:
 3.00
 Sq Ft:
 0

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1418,1420,1422 COMMONS DR (11)

Contractor: DRAEGER CONSTRUCTION INC

Occupancy:R1Insp Area:1Activity Code:C6 TERMITE/DRY ROT REPAIRValuation:\$5,280.00Fees Req:\$264.62Fees Col:\$264.62Bal Due:\$0.00

Activity: COM-0901745 Type: Building / Commercial / Minor / Condos

 Site Address:
 1426 COMMONS DR
 # Units:
 2.00
 Sq Ft:
 0

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1426,1428,COMMONS DR WY (12)

Contractor: DRAEGER CONSTRUCTION INC

Occupancy:R1Insp Area:1Activity Code:C6 TERMITE/DRY ROT REPAIRValuation:\$2,920.00Fees Req:\$167.54Fees Col:\$167.54Bal Due:\$0.00

Activity: COM-0901746 Type: Building / Commercial / Minor / Condos

 Parcel: 29501100030000
 Applied: 02/19/2009
 Issued: 02/20/2009
 Finaled:

 Site Address:
 901 ELMHURST CIR
 # Units:
 2.00
 Sq Ft:
 0

Activity Data Report
City of Sacramento, CA

Page 14

ISSUED between 02/15/2009 and 02/21/2009

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 901,903 ELMHURST CR (13)

Contractor: DRAEGER CONSTRUCTION INC

Occupancy:R1Insp Area:1Activity Code:C6 TERMITE/DRY ROT REPAIRValuation:\$2,920.00Fees Req:\$167.54Fees Col:\$167.54Bal Due:\$0.00

Activity: COM-0901750 Type: Building / Commercial / Minor / Condos

Site Address: 1231 VANDERBILTWAY # Units: 3.00 Sq Ft: 0

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1231, 1233, 1235 VANDERBUILTWY (14)

Contractor: DRAEGER CONSTRUCTION INC

 Occupancy:
 R1
 Insp Area:
 1
 Activity Code:
 C6 TERMITE/DRY ROT REPAIR

 Valuation:
 \$5,280.00
 Fees Req:
 \$264.62
 Fees Col:
 \$264.62
 Bal Due:
 \$0.00

Activity: COM-0901751 Type: Building / Commercial / Repair-Maintenance / Industrial

Site Address: 3001 G ST **# Units:** 0.00 **Sq Ft:** 0

Location:

Description: TRENCHLESS SEWER LINE REPLACEMENT AT BUDGET TRUCK RENTAL AT 627 30TH ST.

Contractor: TRENCHLESS COMPANYTHE

Occupancy: B Insp Area: 1 Activity Code: P2 SEWER SERVICE

Valuation: \$9,922.36 Fees Req: \$392.61 Fees Col: \$392.61 Bal Due: \$0.00

Activity: COM-0901753 Type: Building / Commercial / Minor / Condos

 Parcel: 29500900310000
 Applied: 02/19/2009
 Issued: 02/20/2009
 Finaled:

Site Address: 1219 VANDERBILTWAY #Units: 2.00 Sq Ft: 0

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1219,1221,VANDERBUILTWY (16)

Contractor: DRAEGER CONSTRUCTION INC

Occupancy:R1Insp Area:1Activity Code:C6 TERMITE/DRY ROT REPAIRValuation:\$2,920.00Fees Req:\$167.54Fees Col:\$167.54Bal Due:\$0.00

Activity: COM-0901755 Type: Building / Commercial / Minor / Condos

 Parcel:
 29501700170000
 Applied:
 02/19/2009
 Issued:
 02/20/2009
 Finaled:

 Site Address:
 1215 VANDERBILTWAY
 # Units:
 2.00
 Sq Ft:
 0

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1215,1217,VANDERBUILTWY (17)

Contractor: DRAEGER CONSTRUCTION INC

Occupancy:R1Insp Area:1Activity Code:C6 TERMITE/DRY ROT REPAIRValuation:\$2,920.00Fees Req:\$167.54Fees Col:\$167.54Bal Due:\$0.00

Activity: COM-0901756 Type: Building / Commercial / Minor / Condos

 08:59:34 AM

Activity Data Report 02/23/2009 City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Site Address: 1207 VANDERBILTWAY # Units: 4.00 Sq Ft:

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1207,1209, 1211, 1213 VANDERBUILTWY (18)

Contractor: DRAEGER CONSTRUCTION INC

Occupancy: R1 Insp Area: 1 Activity Code: C6 TERMITE/DRY ROT REPAIR Valuation: \$7,040.00 Fees Col: \$315.06 Fees Req: \$315.06 Bal Due: \$0.00

Activity: COM-0901758 Type: Building / Commercial / Minor / Other Non-Res Bldgs

Parcel: 22502940070000 Applied: 02/19/2009 Issued: 02/19/2009

Site Address: 1200 W EL CAMINO AVE # Units: 0.00

Location:

Description: INSTALL 200AMP PANEL. LAUNDRY ROOM.

Contractor: A R P ELECTRIC AND LIGHTING CO A PARTNERSHIP

Activity Code: E2 ELEC SERVICE CHANGE Occupancy: R1 Insp Area: 4

Valuation: \$1,950.00 Fees Col: \$86.78 Fees Req: \$86.78 Bal Due: \$0.00

Type: Building / Commercial / Minor / Condos Activity: COM-0901760

Parcel: 29501700290000 Applied: 02/19/2009 Issued: 02/20/2009 Finaled: Site Address: 1131 VANDERBILTWAY # Units: 3.00 0

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1131, 1137, 1143 VANDERBUILTWY (20)

Contractor: DRAEGER CONSTRUCTION INC

Insp Area: 1 Activity Code: C6 TERMITE/DRY ROT REPAIR Occupancy: R1 Valuation: \$5,280.00 Fees Req: \$264.62 Fees Col: \$264.62 Bal Due: \$0.00

Activity: COM-0901762 Type: Building / Commercial / Minor / Condos

Parcel: 29501700020000 Applied: 02/19/2009 Issued: 02/20/2009 Site Address: 1185 VANDERBILTWAY # Units: 4.00 Sq Ft: 0

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1185, 1191, 1197, 1203 VANDERBUILTWY (21)

Contractor: DRAEGER CONSTRUCTION INC

Occupancy: R1 Insp Area: 1 Activity Code: C6 TERMITE/DRY ROT REPAIR Valuation: \$7,040.00 Fees Req: \$315.06 Fees Col: \$315.06 Bal Due: \$0.00

Activity: COM-0901764 Type: Building / Commercial / Minor / Condos

Parcel: 29501900180000 Applied: 02/19/2009 Issued: 02/20/2009 Finaled: Site Address: 1170 VANDERBILTWAY # Units: 3.00 Sq Ft: 0

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1170, 1176, 1182 VANDERBUILTWY (22)

Contractor: DRAEGER CONSTRUCTION INC

Activity Code: C6 TERMITE/DRY ROT REPAIR Occupancy: R1 Insp Area: 1 Valuation: \$5,280.00 Fees Req: \$264.62 Fees Col: \$264.62 Bal Due: \$0.00

Type: Building / Commercial / Minor / Condos Activity: COM-0901767

Page 15

0

Sq Ft:

Sq Ft:

Finaled:

Activity Data Report Page 16
City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Site Address: 1146 VANDERBILTWAY # Units: 4.00 Sq Ft: 0

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1146, 1152, 1158, 1164, VANDERBUILTWY (23)

Contractor: DRAEGER CONSTRUCTION INC

Occupancy:R1Insp Area:1Activity Code:C6 TERMITE/DRY ROT REPAIRValuation:\$7,040.00Fees Req:\$315.06Fees Col:\$315.06Bal Due:\$0.00

Activity: COM-0901769 Type: Building / Commercial / Minor / Condos

 Parcel: 29501900100000
 Applied: 02/19/2009
 Issued: 02/20/2009
 Finaled:

Site Address: 1118 VANDERBILTWAY # Units: 4.00 Sq Ft: 0

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1118, 1124, 1130, 1136 VANDERBUILTWY (24)

Contractor: DRAEGER CONSTRUCTION INC

Occupancy:R1Insp Area:1Activity Code:B6 CELL TOWER COMPONENTSValuation:\$7,040.00Fees Req:\$315.06Fees Col:\$315.06Bal Due:\$0.00

Activity: COM-0901782 Type: Building / Commercial / Minor / Condos

 Parcel:
 29501900080000
 Applied:
 02/19/2009
 Issued:
 02/20/2009
 Finaled:

 Site Address:
 1106 VANDERBILTWAY
 # Units:
 2.00
 Sq Ft:
 0

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1106,1112,VANDERBUILTWY (25)

Contractor: DRAEGER CONSTRUCTION INC

Occupancy:R1Insp Area:1Activity Code:C6 TERMITE/DRY ROT REPAIRValuation:\$2,290.00Fees Req:\$167.18Fees Col:\$167.18Bal Due:\$0.00

Activity: COM-0901786 Type: Building / Commercial / Minor / Condos

Site Address: 1095 VANDERBILTWAY # Units: 4.00 Sq Ft: 0

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1095, 1101, 1107, 1113 VANDERBUILTWY (27)

Contractor: DRAEGER CONSTRUCTION INC

Occupancy:R1Insp Area:1Activity Code:C6 TERMITE/DRY ROT REPAIRValuation:\$7,040.00Fees Req:\$315.06Fees Col:\$315.06Bal Due:\$0.00

Activity: COM-0901789 Type: Building / Commercial / Minor / Condos

Site Address: 1071 VANDERBILTWAY # Units: 3.00 Sq Ft: 0

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1071, 1077, 1083 VANDERBUILTWY (28)

Contractor: DRAEGER CONSTRUCTION INC

 Occupancy:
 R1
 Insp Area:
 1
 Activity Code:
 C6 TERMITE/DRY ROT REPAIR

 Valuation:
 \$5,280.00
 Fees Req:
 \$264.62
 Fees Col:
 \$264.62
 Bal Due:
 \$0.00

Activity Data Report Page 17 City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Activity: COM-0901792 Type: Building / Commercial / Minor / Condos

Parcel: 29501700030000 Applied: 02/19/2009 Issued: 02/20/2009 Finaled: Site Address: 1045 VANDERBILTWAY # Units: 3 00 Sq Ft: 0

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1045, 1055, 1065 VANDERBUILTWY (29)

Contractor: DRAEGER CONSTRUCTION INC

Activity Code: C6 TERMITE/DRY ROT REPAIR Occupancy: R1 Insp Area: 1 Valuation: \$5,280.00 Fees Req: \$264.62 Fees Col: \$264.62 Bal Due: \$0.00

Type: Building / Commercial / Minor / Condos Activity: COM-0901795

Issued: 02/20/2009 Parcel: 29501900030000 Applied: 02/19/2009 Finaled:

Site Address: 1026 VANDERBILTWAY # Units: 5.00 Sq Ft: 0

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM, 1026, 1036, 1046, 1056, 1066 VANDERBUILTWY (30)

Contractor: DRAEGER CONSTRUCTION INC

Occupancy: R1 Activity Code: C6 TERMITE/DRY ROT REPAIR Insp Area: 1 Valuation: \$8,800.00 Fees Req: \$338.65 Fees Col: \$338.65 Bal Due: \$0.00

Activity: COM-0901799 Type: Building / Commercial / Minor / Condos

Parcel: 29501900010000 Applied: 02/19/2009 Issued: 02/20/2009 Finaled:

Site Address: 1006 VANDERBILTWAY # Units: 2.00 Sq Ft: 0

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1006,1016, VANDERBUILTWY (31)

Contractor: DRAEGER CONSTRUCTION INC

Activity Code: C6 TERMITE/DRY ROT REPAIR Occupancy: R1 Insp Area: 1 Valuation: \$2.920.00 Fees Req: \$167.54 Fees Col: \$167.54 Bal Due: \$0.00

Activity: COM-0901801 Type: Building / Commercial / Minor / Condos

Parcel: 04902810180002 Applied: 02/19/2009 Issued: 02/20/2009 Finaled:

Site Address: 7448 FRANKLIN BLVD 2 # Units: 4.00 Sq Ft: 0

Location:

Description: HVAC CHANGE-OUT. SPLIT SYSTEM. REFER TO PERMIT NO. RES-0900475. FEES PAID UNDER THAT PERMIT.

Contractor: ASTRO AIR DESIGN INC

Activity Code: M1 HEATING/AIR CONDITION Occupancy: R1 Insp Area: 2

Valuation: \$0.00 Fees Req: \$0.00 Fees Col: \$0.00 Bal Due: \$0.00

Type: Building / Commercial / New Structural / Service Stations Activity: COM-0901808

Parcel: 01500310430000 Applied: 02/19/2009 Issued: 02/19/2009 Finaled:

Site Address: 2901 65TH ST # Units: 0.00 Sq Ft: 27

Location:

Description: NEW EVR INSTALLW/ HORIZONTAL TANK. Contractor: M V P PETROLEUM ENGINEERING INC

Occupancy: M Activity Code: E6 TANKS Insp Area: 3

Valuation: \$8,000.00 Fees Req: \$718.03 Fees Col: \$718.03 Bal Due: \$0.00

Activity Data Report Page 18
City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Activity: COM-0901816 Type: Building / Commercial / Minor / Condos

 Parcel:
 29500900010000
 Applied:
 02/20/2009
 Issued:
 02/20/2009
 Finaled:

 Site Address:
 1005 VANDERBILTWAY
 # Units:
 3.00
 Sq Ft:
 0

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 1005, 1015, 1025 VANDERBUILTWY (32)

Contractor: DRAEGER CONSTRUCTION INC

 Occupancy:
 R1
 Insp Area:
 1
 Activity Code:
 C6 TERMITE/DRY ROT REPAIR

 Valuation:
 \$5,280.00
 Fees Req:
 \$264.62
 Fees Col:
 \$264.62
 Bal Due:
 \$0.00

Activity: COM-0901818 Type: Building / Commercial / Minor / Condos

 Site Address:
 100 ELMHURST CIR
 # Units:
 5.00
 Sq Ft:
 0

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 100,102,104,106,108 ELMHURST CR (33)

Contractor: DRAEGER CONSTRUCTION INC

 Occupancy:
 R1
 Insp Area:
 1
 Activity Code:
 C6 TERMITE/DRY ROT REPAIR

 Valuation:
 \$8,800.00
 Fees Req:
 \$338.65
 Fees Col:
 \$338.65
 Bal Due:
 \$0.00

Activity: COM-0901820 Type: Building / Commercial / Minor / Condos

 Site Address:
 201 ELMHURST CIR
 # Units:
 4.00
 Sq Ft:
 0

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 201,203,205,207 ELMHURST CR (34)

Contractor: DRAEGER CONSTRUCTION INC

Occupancy:R1Insp Area:1Activity Code:B6 CELL TOWER COMPONENTSValuation:\$7,040.00Fees Req:\$315.06Fees Col:\$315.06Bal Due:\$0.00

Activity: COM-0901827 Type: Building / Commercial / Minor / Condos

 Parcel: 29500900150000
 Applied: 02/20/2009
 Issued: 02/20/2009
 Finaled:

 Site Address:
 209 ELMHURST CIR
 # Units:
 3.00
 Sq Ft:
 0

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 209,211,213 ELMHURST CR (35)

Contractor: DRAEGER CONSTRUCTION INC

 Occupancy:
 R1
 Insp Area:
 1
 Activity Code:
 C6 TERMITE/DRY ROT REPAIR

 Valuation:
 \$5,280.00
 Fees Req:
 \$264.62
 Fees Col:
 \$264.62
 Bal Due:
 \$0.00

Activity: COM-0901830 Type: Building / Commercial / Minor / Condos

 Parcel: 29500900180000
 Applied: 02/20/2009
 Issued: 02/20/2009
 Finaled:

Site Address: 209 ELMHURST CIR # Units: 3.00 Sq Ft: 0

Location:

Description: REMOVE AND REPLACE DRY ROTTED T1-11 SIDING AND TRIM 215,217,219 ELMHURST CR (36)

Contractor: DRAEGER CONSTRUCTION INC

Occupancy: R1 Insp Area: 1 Activity Code: C6 TERMITE/DRY ROT REPAIR

Valuation: \$5,280.00 Fees Req: \$264.62 Fees Col: \$264.62 Bal Due: \$0.00

Activity Data Report
City of Sacramento, CA

Page 19

ISSUED between 02/15/2009 and 02/21/2009

Activity: COM-0901848 Type: Building / Commercial / Remodel / Retail Store

Site Address: 1708 BROADWAY #Units: 0.00 Sq Ft: 0

Location:

Description: remove and replace 200 amp overhead service add new sub panel in building

Contractor: ENERGY ELECTRIC

Occupancy: B Insp Area: 1 Activity Code: E2 ELEC SERVICE CHANGE

Valuation: \$1,700.00 Fees Req: \$201.16 Fees Col: \$201.16 Bal Due: \$0.00

Activity: COM-0901869 Type: Building / Commercial / Repair-Maintenance / Retail Store

Site Address: 5288 FRUITRIDGE RD # Units: 0.00 Sq Ft: 0

Location:

Description: STORE FRONT REPAIR CAR DAMAGE. **Contractor:** SUN VALLEY CONSTRUCTION CO

Occupancy: M Insp Area: 3 Activity Code: Z14 STRUCTURALIMPROVMT

Valuation: \$6,000.00 Fees Req: \$495.10 Fees Col: \$495.10 Bal Due: \$0.00

Activity: RES-0811493 Type: Building / Residential / Addition / Single Family

 Site Address:
 5100 H ST
 # Units:
 0.00
 Sq Ft:
 1,088

Location:

Description: ADD 635 SF liv (master bed/bath/closet, laundry rm, expand kitchen) & 30 SF & 73 SF rear patios; REMODEL approx. 350 SF

existing house (hallway, kitchen)

Contractor:

 Occupancy:
 R3
 Insp Area:
 1
 Activity Code:
 A1 ADD SQFT-EXISTING BLDG

 Valuation:
 \$77,176.90
 Fees Req:
 \$2,192.82
 Fees Col:
 \$2,223.69
 Bal Due:
 -\$30.87

Activity: RES-0813928 Type: Building / Residential / Fire-Equipment / Single Family

 Site Address:
 7321 MEADOWGATEDR
 # Units:
 0.00
 Sq Ft:
 1,917

Location:

Description: INSTALL FIRE SPRINKLERS IN EXISTING SFR AS PART OF CONVERSION TO CARE FACILITY (6 or less non-ambulatory

patients)

Contractor: INTERNATIONAL FIRE EQUIP CO

Occupancy: R3 Insp Area: 2 Activity Code: P3 FIRE SPRINKLERS/LINE

 Valuation:
 \$8,051.40
 Fees Req:
 \$1,275.11
 Fees Col:
 \$1,275.11
 Bal Due:
 \$0.00

Activity: RES-0814153 Type: Building / Residential / Housing-Minor / Single Family

 Parcel: 27501010050000
 Applied: 10/22/2008
 Issued: 10/22/2008
 Finaled:

 Site Address: 2381 CANTALIER ST
 # Units: 0.00
 Sq Ft:

Location:

Description: TO COMPLETE WORK FROM PREVIOUS PERMIT(S)RES-0811363 AND RES-08090303, (ALL PREVIOUS CONDITIONS AND

APPROVALS (IF ANY) APPLY.INSTALL HVAC, MINOR PLUMBING, COMPLETE INTERIOR REMODEL.

Contractor: JOHNSON BUILTCONST.

Occupancy: R3 Insp Area: 4 Activity Code: C4 HOUSING CASES

08:59:34 AM

Activity Data Report 02/23/2009 Page 20 City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Valuation: \$15,000.00 Fees Req: \$610.86 Fees Col: \$610.86 Bal Due: \$0.00

Type: Building / Residential / Housing-Minor / Single Family Activity: RES-0815545

Parcel: 27501040180000 Applied: 11/18/2008 Issued: 11/18/2008 Finaled: Site Address: 2352 CAMBRIDGE ST # Units: 0.00 Sq Ft:

Location:

Description: SMUD SAFETY INSP. REPAIR WINDOWS, MINOR PLUMBING ELECTRICAL, REMOVE STOVE FROM GARAGE, CONVERT TO

ACCESSORY STRUCTURE. PR08-01775 -

Contractor:

Activity Code: C4 HOUSING CASES Occupancy: R3 Insp Area: 4

Fees Col: \$271.14 Valuation: \$1,900.00 Fees Req: \$271.14 Bal Due: \$0.00

Type: Building / Residential / Remodel / Single Family Activity: RES-0815708

Parcel: 00804240110000 Applied: 11/20/2008 Issued: 02/20/2009 Finaled:

Site Address: 1552 48TH ST # Units: 0.00 Sq Ft: 900

Location:

Description: REMODEL DINING RM AND KITCHEN, REMOVING WALLS IN DINING RM, ELECTRICAL AND PLUMBING CHANGES, 1 DUCT

CHANGE.

Contractor:

Insp Area: 1 Activity Code: 11 INTERIOR REM-RES Occupancy: R3

Valuation: \$25,000.00 Fees Req: \$934.46 Fees Col: \$934.46 Bal Due: \$0.00

Type: Building / Residential / Housing-Minor / Duplex Activity: RES-0815936

Parcel: 02000220390000 Applied: 11/26/2008 Issued: 11/26/2008 Finaled: 02/19/2009

Site Address: 3430 12TH AVE # Units: 0.00 Sq Ft:

Location:

Description: C/O 2 WALL HEATERS

Contractor: ACE PLUMBING HEATING & AIR

Occupancy: R3 Insp Area: 3 Activity Code: C4 HOUSING CASES

Valuation: \$3,900.00 Fees Req: \$353.38 Fees Col: \$353.38 Bal Due: \$0.00

Type: Building / Residential / Repair-Maintenance / Single Family Activity: RES-0900233

Parcel: 01402220270000 Applied: 01/07/2009 Issued: 02/18/2009 Finaled: Site Address: 4588 9TH AVE # Units: 1.00 Sq Ft:

Location:

Description: PER DESIGN REVIEW APPROVAL WORK SHALL BE DONE ACCORDING TO CONDITIONS OF APPROVAL REPLACE SIDING.

0

PORCH COLUMNS, STONE COVERING AT PORCH AND COLUMN FOOTINGS. NO QUADE FEE.

Contractor:

Occupancy: R3 Insp Area: 3 Activity Code: C1 GENERAL REPAIR/FIX-IT

Valuation: \$10,000.00 Fees Req: \$520.96 Fees Col: \$520.96 Bal Due: \$0.00

Type: Building / Residential / New Building / Duplex Activity: RES-0900543

Parcel: 01401740120000 Applied: 01/15/2009 Issued: 02/20/2009 Finaled:

Site Address: 3957 8TH AVE # Units: 2.00 Sq Ft: 2,862

Location:

Description: NDPLX - COMPLETE WORK STARTED UNDER RES-0618743 - UNIT A 1180SF LIV 210 SF GARAGE UNIT B 1262 LIV AND 210

SF GARAGE

Activity Data Report
City of Sacramento, CA

Page 21

ISSUED between 02/15/2009 and 02/21/2009

Contractor: DAVIS CONSTRUCTION COMPANY

 Occupancy:
 R3
 Insp Area:
 3
 Activity Code:
 C10 COMPLETE WK-PREV PRMT

 Valuation:
 \$0.00
 Fees Req:
 \$1,377.53
 Fees Col:
 \$1,377.53
 Bal Due:
 \$0.00

Activity: RES-0900941 Type: Building / Residential / Addition / Single Family

Site Address: 2600 PATTONWAY **# Units:** 0.00 **Sq Ft:** 299.50

Location:

Description: DEMO 190 SQ FT OF HOUSE TO ADD 489.5 SQ FT ADDITON AT REAR NET CHANGE 299.5 SQ FT MASTER SUITE /LAUDRY

ROOM RAPLACE ELECTRIC MAIN, ROOF OVERLAY OF EXISTING, NEW UPFLOW FURNNACE, NEW WATER MAIN, NEW

TANKLESS W.H. REWIRE INTERIOR, TIE INTO EXISTING PLUMBING

Contractor: FUGINA KEVIN J

 Occupancy:
 R3
 Insp Area:
 2
 Activity Code:
 A1 ADD SQFT-EXISTING BLDG

 Valuation:
 \$45,183.60
 Fees Req:
 \$1,642.98
 Fees Col:
 \$1,642.98
 Bal Due:
 \$0.00

Activity: RES-0900941 Type: Building / Residential / Addition / Single Family

Site Address: 2600 PATTONWAY **# Units:** 0.00 **Sq Ft:** 299.50

Location:

Description: DEMO 190 SQ FT OF HOUSE TO ADD 489.5 SQ FT ADDITION AT REAR NET CHANGE 299.5 SQ FT MASTER SUITE /LAUDRY

ROOM RAPLACE ELECTRIC MAIN, ROOF OVERLAY OF EXISTING, NEW UPFLOW FURNNACE, NEW WATER MAIN, NEW

TANKLESS W.H. REWIRE INTERIOR, TIE INTO EXISTING PLUMBING

Contractor: FUGINA KEVIN J

 Occupancy:
 R3
 Insp Area:
 2
 Activity Code:
 A1 ADD SQFT-EXISTING BLDG

 Valuation:
 \$45,183.60
 Fees Req:
 \$1,642.98
 Fees Col:
 \$1,642.98
 Bal Due:
 \$0.00

Activity: RES-0901311 Type: Building / Residential / Minor / Single Family

 Parcel:
 00802220060000
 Applied:
 02/06/2009
 Issued:
 02/18/2009
 Finaled:

 Site Address:
 5025 L ST
 # Units:
 0.00
 Sq Ft:

Location:

Description: KICHEN, DINING ROOM REMODEL. REMOVE SOME NON-BEARING WALLS.

Contractor:

Occupancy: R1 Insp Area: 1 Activity Code: C1 GENERAL REPAIR/FIX-IT

Valuation: \$11,450.00 Fees Req: \$397.93 Fees Col: \$397.93 Bal Due: \$0.00

Activity: RES-0901455 Type: Building / Residential / Minor / Single Family

 Parcel:
 01702010150000
 Applied:
 02/10/2009
 Issued:
 02/17/2009
 Finaled:

 Site Address:
 1700 OPPER AVE
 # Units:
 0.00
 Sq Ft:

Location:

 $\textbf{Description:} \ \ \textbf{HVACC/OSPLITSYSTEM} \ \ \textbf{GROUND MOUNT.PROVIDE ALL DOCUMENTS FOR FINAL INSPECTION. SMOKE DETECTORS$

REQUIRED.

Contractor: DIAL ONE SERVICE EXPERTS

Occupancy: R3 Insp Area: 2 Activity Code: M1 HEATING/AIR CONDITION

Valuation: \$16,683.00 Fees Req: \$230.67 Fees Col: \$230.67 Bal Due: \$0.00

Activity: RES-0901618 Type: Building / Residential / Minor / Single Family

Activity Data Report 02/23/2009

08:59:34 AM

City of Sacramento, CA ISSUED between 02/15/2009 and 02/21/2009

Site Address: 7708 RIVER GROVE CIR # Units: 0.00 Sq Ft:

Location:

Description: HVAC CHANGE-OUT. SPLIT SYSTEM. Contractor: ALL STAR HOME IMPROVEMENT

Occupancy: R1 Insp Area: 2 Activity Code: M1 HEATING/AIR CONDITION

Valuation: \$10,000.00 Fees Col: \$214.00 Fees Req: \$214.00 Bal Due: \$0.00

Activity: RES-0901626 Type: Building / Residential / Minor / Single Family

Parcel: 11708500200000 Applied: 02/17/2009 Issued: 02/17/2009

Site Address: 6090 WINDBREAKER WAY # Units: 0.00 Sq Ft: O

Location:

Description: INSTALL VINYL SIDING

Contractor: SEARS HOME IMPROVEMENT PRODUCTS INC

Activity Code: Z1 VINYL/WOOD SIDING Occupancy: R1 Insp Area: 2

Valuation: \$27,083.00 Fees Req: \$260.54 Fees Col: \$260.54 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901627

Parcel: 02401920040000 Applied: 02/17/2009 Issued: 02/17/2009

Site Address: 5880 14TH ST # Units: 0.00 Sq Ft: 27

Location:

Description: REROOF. TEAR-OFF. 30 YEAR COMP. Contractor: RIDINGS GEORGE WILLIAM IV

Insp Area: 2 Activity Code: R1 REROOF Occupancy: R1

Valuation: \$6,900.00 Fees Req: \$207.45 Fees Col: \$207.45 Bal Due: \$0.00

Activity: RES-0901628 Type: Building / Residential / Minor / Single Family

Parcel: 26602420560000 Applied: 02/17/2009 Issued: 02/17/2009 Finaled: 02/18/2009 Site Address: 1821 HELENA AVE J # Units: 0.00 Sq Ft: 0

Location:

Description: INSTALL NEW CIRCUIT BREAKER FOR A/C UNIT. Contractor: SUPERIOR ELECTRICAL SERVICE TECHNICIANS INC

Occupancy: R3 Insp Area: 4 Activity Code: E10 ELEC EQUIPMENT INSTALL Valuation: \$500.00 Fees Req: \$84.20 Fees Col: \$84.20 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901629

Parcel: 00700540110000 Applied: 02/17/2009 Issued: 02/20/2009 Finaled:

Site Address: 932 33RD ST # Units: 0.00 Sq Ft: 0

Location:

Description: HVAC CHANGE-OUT. SPLIT SYSTEM.

Contractor: BRONCO HEATING & AIR

Occupancy: R1 Insp Area: 1 Activity Code: M1 HEATING/AIR CONDITION

Valuation: \$6,636.00 Fees Req: \$206.65 Fees Col: \$206.65 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901630

Page 22

Activity Data Report Page 23
City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Site Address: 19 ZEPHYR COVE CIR #Units: 0.00 Sq Ft: 0

Location:

Description: HVAC CHANGE-OUT. SPLIT SYSTEM. **Contractor:** BERKAN & CLARK HEATING & AIR

Occupancy: R1 Insp Area: 2 Activity Code: M1 HEATING/AIR CONDITION

Valuation: \$8,435.00 Fees Req: \$211.37 Fees Col: \$211.37 Bal Due: \$0.00

Activity: RES-0901631 Type: Building / Residential / Minor / Single Family

Site Address: 1520 WOODLAND OAKS WAY # Units: 0.00 Sq Ft: 0

Location:

Description: WATER HEATER. GAS. **Contractor:** DOMCO PLUMBING INC

Occupancy: R1 Insp Area: 4 Activity Code: P6 WATER HEATER

Valuation: \$700.00 Fees Req: \$84.28 Fees Col: \$84.28 Bal Due: \$0.00

Activity: RES-0901632 Type: Building / Residential / Minor / Single Family

 Parcel:
 03000200380000
 Applied:
 02/17/2009
 Issued:
 02/17/2009
 Finaled:
 02/19/2009

 Site Address:
 6621 PARK RIVIERA WAY
 # Units:
 0.00
 Sq Ft:
 0

Location:

Description: SEWER LINE TRENCHLESS. **Contractor:** TRENCHLESS COMPANY THE

Occupancy: R1 Insp Area: 2 Activity Code: P2 SEWER SERVICE

Valuation: \$3,900.00 Fees Req: \$91.56 Fees Col: \$91.56 Bal Due: \$0.00

Activity: RES-0901634 Type: Building / Residential / Minor / Single Family

Site Address: 8630 EVERGLADE DR # Units: 0.00 Sq Ft: 0

Location:

Description: HVAC PACKAGE ROOF MOUNT CHANGE OUT

Contractor: BARNETT HEATING & AIR

Occupancy: R3 Insp Area: 1 Activity Code: M1 HEATING/AIR CONDITION

Valuation: \$4,887.00 Fees Req: \$201.95 Fees Col: \$201.95 Bal Due: \$0.00

Activity: RES-0901635 Type: Building / Residential / Minor / Single Family

 Parcel:
 03107200330000
 Applied:
 02/17/2009
 Issued:
 02/17/2009
 Finaled:
 02/18/2009

 Site Address:
 57 HERITAGEWOOD CIR
 # Units:
 0.00
 Sq Ft:
 0

Location:

Description: REPLACE DUCT WORK. **Contractor:** HOYT MECHANICAL

Occupancy: R1 Insp Area: 2 Activity Code: M1 HEATING/AIR CONDITION

 Valuation:
 \$2,100.00
 Fees Req:
 \$77.84
 Fees Col:
 \$77.84
 Bal Due:
 \$0.00

Activity Data Report Page 24 City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Activity: RES-0901636 Type: Building / Residential / Housing Dept Permit / Private Garage

Parcel: 03502820070000 Issued: 02/17/2009 Applied: 02/17/2009 Finaled:

Site Address: 7000 MIDDLECOFF WAY # Units: 0.00 Sq Ft: 360

Location:

Description: 07-034885 Garage conversion 360sf habitable space; 140sf storage. REPLACE ELECTRICAL OUTLETS, REROOF, 1 STORY

SFR 22 SQUARES TEAR-OFF APPLY 30 YR COMP, REMOVE AND REPLACE WINDOWS, INSTALL SHOWER STALL, REMOVE

AND REPLACE TUB AND SURROUND, INSTALL RAFTERS AND HANG SHEETROCK.

Contractor:

Occupancy: R3 Insp Area: 2 Activity Code: C4 HOUSING CASES

Valuation: \$36,666.00 Fees Req: \$1,001.47 Fees Col: \$1,001.47 Bal Due: \$0.00

Activity: RES-0901637 Type: Building / Residential / Minor / Single Family

Parcel: 03101220040000 Applied: 02/17/2009 Issued: 02/17/2009 Finaled:

Site Address: 1231 WOODFIELD AVE # Units: 0.00 Sq Ft: 0

Location:

Description: REROOF. TEAR-OFF. 40 YEAR COMP. Contractor: CAL - VINTAGE ROOFING CO INC

Occupancy: R1 Insp Area: 2 Activity Code: R1 REROOF

Valuation: \$12.000.00 Fees Req: \$220.00 Fees Col: \$220.00 Bal Due: \$0.00

Activity: RES-0901638 Type: Building / Residential / Housing-Minor / Single Family

Parcel: 22504200770000 Applied: 02/17/2009 Issued: 02/17/2009 Finaled:

Site Address: 1461 BREWERTON DR # Units: 0.00 Sq Ft: 1,600

Location:

Description: PERMIT TO COMPLETE REPAIRS OF HOUSING VIOLATION LIST, PLUS HVAC CHANGE OUT, WINDOW REPACEMENT,

WATER HEATER CHANGE OUT. REPAIR STUCCO AROUND WINDOWS.

Contractor:

Occupancy: R3 Insp Area: 4 Activity Code: C4 HOUSING CASES

Valuation: \$10,000.00 Fees Req: \$712.00 Fees Col: \$712.00 Bal Due: \$0.00

Activity: RES-0901639 Type: Building / Residential / Minor / Single Family

Parcel: 04700430150000 Applied: 02/17/2009 Issued: 02/17/2009 Finaled:

Site Address: 1925 WAKEFIELD WAY # Units: 0.00 Sq Ft: 0

Location:

Description: HVAC CHANGE-OUT. SPLIT SYSTEM.

Contractor: HOYT MECHANICAL

Occupancy: R1 Activity Code: M1 HEATING/AIR CONDITION Insp Area: 2

Valuation: \$4,300.00 Fees Req: \$201.72 Fees Col: \$201.72 Bal Due: \$0.00

Activity: RES-0901640 Type: Building / Residential / Minor / Single Family

Applied: 02/17/2009 Issued: 02/17/2009 Parcel: 22504200070000 Finaled:

Site Address: 1535 WOODRIDGE OAK WAY # Units: 0.00 Sq Ft: 0

Location:

Description: HVAC CHANGE-OUT. SPLIT SYSTEM. Contractor: BERKAN & CLARK HEATING & AIR

Activity Code: M1 HEATING/AIR CONDITION Occupancy: R1 Insp Area: 4

Activity Data Report Page 25

AM City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

 Valuation:
 \$6,586.00
 Fees Req:
 \$206.63
 Fees Col:
 \$206.63
 Bal Due:
 \$0.00

Activity: RES-0901641 Type: Building / Residential / Remodel / Single Family

 Site Address: 4011 73RD ST
 # Units: 1.00
 Sq Ft: 100

Location:

Description: Enlarge 5' interior wall to 7', bearing wall.

Contractor:

Occupancy: R3 Insp Area: 3 Activity Code: I1 INTERIOR REM-RES

Valuation: \$1,000.00 Fees Req: \$168.74 Fees Col: \$168.74 Bal Due: \$0.00

Activity: RES-0901642 Type: Building / Residential / Minor / Single Family

 Site Address:
 3712 DAYTONST
 # Units:
 0.00
 Sq Ft:
 0

Location:

Description: HVAC CHANGE-OUT. ROOF UNIT. **Contractor:** AIR MAX HEATING & COOLING

Occupancy: R1 Insp Area: 4 Activity Code: M1 HEATING/AIR CONDITION

Valuation: \$4,000.00 Fees Req: \$199.60 Fees Col: \$199.60 Bal Due: \$0.00

Activity: RES-0901643 Type: Building / Residential / Minor / Single Family

Site Address: 2500 ENCINAL AVE #Units: 0.00 Sq Ft: 0

Location:

Description: REPLACE DAMAGED SUBPANEL.

Contractor: RESI - COMM ALARMS

Occupancy: R1 Insp Area: 3 Activity Code: E1 SERVICE REPAIR

Valuation: \$860.00 Fees Req: \$84.34 Fees Col: \$84.34 Bal Due: \$0.00

Activity: RES-0901643 Type: Building / Residential / Minor / Single Family

 Site Address:
 2500 ENCINAL AVE
 # Units:
 0.00
 Sq Ft:
 0

Location:

Description: REPLACE DAMAGED SUBPANEL.

Contractor: RESI - COMM ALARMS

Occupancy: R1 Insp Area: 3 Activity Code: E1 SERVICE REPAIR

Valuation: \$860.00 Fees Req: \$84.34 Fees Col: \$84.34 Bal Due: \$0.00

Activity: RES-0901644 Type: Building / Residential / Minor / Single Family

 Parcel: 26500600300000
 Applied: 02/17/2009
 Issued: 02/17/2009
 Finaled:

 Site Address:
 3111 DEL PASO BLVD
 # Units:
 0.00
 Sq Ft:
 0

Location:

Description: HVAC CHANGE-OUT. SPLIT SYSTEM.

Contractor: ONE HOUR HEATING AND AIR CONDITIONING

Occupancy: R1 Insp Area: 4 Activity Code: M1 HEATING/AIR CONDITION

08:59:34 AM

Activity Data Report 02/23/2009 Page 26 City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Valuation: \$7,722.00 Fees Req: \$209.09 Fees Col: \$209.09 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901645

Parcel: 02403820040000 Applied: 02/17/2009 Issued: 02/17/2009 Finaled: 02/19/2009 # Units: 0.00 Sq Ft: 0

Site Address: 6242 OAKRIDGE WAY Location:

Description: SEWER LINE. TRENCHLESS. Contractor: ACE PLUMBING HEATING & AIR

Occupancy: R1 Insp Area: 2 Activity Code: P2 SEWER SERVICE

Valuation: \$4,250.00 Fees Req: \$93.70 Fees Col: \$93.70 Bal Due: \$0.00

Activity: RES-0901646 Type: Building / Residential / Housing-Minor / Single Family

Parcel: 02201320060000 Applied: 02/17/2009 Issued: 02/20/2009 Finaled:

Site Address: 4711 ETHEL WAY # Units: 0.00 Sq Ft: 0

Location:

Description: PERMIT TO COMPLETE REPAIRS OF THE HOUSING VIOLATION LIST. PATIOCOVER, WALL HEATERS, WALLS. LAST

PERMIT ISSUED IN ERROR BY DSD RES-0901101. ALL REPAIRSLISTED ON HOUSING VIOLATION LIST TO BE

COMPLETED ON THIS NEW ISSUED PERMI.

Contractor:

Occupancy: R1 Insp Area: 3 Activity Code: C1 GENERAL REPAIR/FIX-IT

Valuation: \$999.99 Fees Req: \$270.54 Fees Col: \$270.54 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901647

Parcel: 03002340160000 Applied: 02/17/2009 Issued: 02/17/2009 Finaled:

Site Address: 712 RIVERCREST DR # Units: 0.00 Sq Ft: 0

Location:

Description: HVAC CHANGE-OUT. SPLIT SYSTEM.

Contractor: DIAL ONE SERVICE EXPERTS

Activity Code: M1 HEATING/AIR CONDITION Occupancy: R1 Insp Area: 2

Fees Col: \$213.92 Bal Due: \$0.00 Valuation: \$9 801 00 Fees Req: \$213.92

Type: Building / Residential / Minor / Single Family Activity: RES-0901651

Parcel: 01602910300000 Applied: 02/17/2009 Issued: 02/17/2009 Finaled:

Site Address: 1209 NEVIS CT # Units: 0.00 Sq Ft: 0

Location:

Description: HVAC CHANGE-OUT. SPLIT SYSTEM.

Contractor: MC DONALD PLUMBING HEATING & AIR CONDITIONING INC

Occupancy: R1 Insp Area: 2 Activity Code: M1 HEATING/AIR CONDITION

Valuation: \$7,728.00 Fees Req: \$209.09 Fees Col: \$209.09 Bal Due: \$0.00

Type: Building / Residential / Minor / Half Plex Activity: RES-0901652

Parcel: 03105901000000 Applied: 02/17/2009 Issued: 02/17/2009 Finaled:

Site Address: 2 WINDUBEY CIR # Units: 0.00 Sq Ft: 0

Location:

Description: HVAC- SPLIT SYSTEM. CHANGE OUT

Activity Data Report 02/23/2009 Page 27 City of Sacramento, CA 08:59:34 AM

ISSUED between 02/15/2009 and 02/21/2009

Contractor: AIR CONTROL SERVICES INC

Activity Code: M1 HEATING/AIR CONDITION Occupancy: R3 Insp Area: 2

Valuation: \$9,676.00 Fees Req: \$213.87 Fees Col: \$213.87 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901654

Parcel: 05300860050000 Applied: 02/17/2009 Issued: 02/17/2009

Site Address: 7659 TEEKAY WAY # Units: 1.00 Sq Ft: 0

Location:

Description: SMUD Safety Inspection.

Contractor:

Occupancy: R3 Insp Area: 2 Activity Code: E11 SAFETY INSPECTION

Valuation: \$999.00 Fees Req: \$84.00 Fees Col: \$84.00 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901655

Parcel: 00501410040000 Applied: 02/17/2009 Issued: 02/17/2009

Site Address: 5330 MONALEE AVE # Units: 0.00 Sq Ft: 0

Location:

Description: REPLACE SEWER SERVICE. TRENCHLESS.

Contractor: TRENCHLESS COMPANY THE

Occupancy: R1 Insp Area: 1 Activity Code: P2 SEWER SERVICE

Valuation: \$3,643.00 Fees Req: \$91.46 Fees Col: \$91.46 Bal Due: \$0.00

Activity: RES-0901657 Type: Building / Residential / Minor / Single Family

Parcel: 04904300060000 Applied: 02/17/2009 Issued: 02/17/2009 Finaled:

Site Address: 7431 CROWNWEST WAY # Units: 0.00 0 Sq Ft:

Location: Description:

Contractor: AIR CONTROL SERVICES INC

Occupancy: R3 Insp Area: 2 Activity Code: M1 HEATING/AIR CONDITION

Valuation: \$5,696.00 Fees Req: \$204.28 Fees Col: \$204.28 Bal Due: \$0.00

Type: Building / Residential / Remodel / Single Family Activity: RES-0901658

Parcel: 01103300280000 Applied: 02/17/2009 Issued: 02/17/2009 Finaled:

Site Address: 5311 BROADWAY # Units: 0.00 Sq Ft: 0

Location:

Description: RELOCATE INTERIOR WALL WITHIN BATHROOM TO CONVERT 1/2 BATHTO FULL BATH- NO OTHER STRUCTURAL WORK

PROPOSED (PLUMBING ON SEPERATE PERMIT)

Contractor: PAHLER CONSTRUCTION

Occupancy: R3 Insp Area: 3 Activity Code: 11 INTERIOR REM-RES

Valuation: \$500.00 Fees Req: \$189.26 Fees Col: \$189.26 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901659

Parcel: 00803420030000 Applied: 02/17/2009 Issued: 02/17/2009 Finaled:

Site Address: 1430 52ND ST # Units: 0.00 Sq Ft: 0

Location:

Activity Data Report City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Description: HVAC CHANGE-OUT. PACKAGE UNIT. Contractor: BELL BROTHER'S HEATING AND AIR INC

Occupancy: R1 Insp Area: 1 Activity Code: M1 HEATING/AIR CONDITION

Valuation: \$8,500.00 Fees Req: \$211.40 Fees Col: \$211.40 Bal Due: \$0.00

Type: Building / Residential / Housing-Minor / Single Family Activity: RES-0901660

Parcel: 26301610090000 Applied: 02/17/2009 Issued: 02/17/2009 Finaled:

Site Address: 2645 GARY WAY # Units: 0.00 Sq Ft: 1.400

Location:

Description: PERMIT TO REPAIR ALL VIOLATION ON HOUSING VIOLATION LIST. BUILDING ADDITION TO BE A HOBBY ROOM PLANS

OK'D BY PLANNING. PERMIT FOR NEW HVAC ROOF TOP SYSTEM. ELECTRICAL INSPECT AND APPROVE HVAC AND

GARAGE ELECTRICAL.PLUMBING, DWV ADDED TO GARAGE FOR WASHER PERMIT AND EXPECT.

Contractor: A-TOMIC CONSTRUCTION & ELECTRIC

Occupancy: R3 Insp Area: 4 Activity Code: C4 HOUSING CASES

Valuation: \$10,000.00 Fees Req: \$716.00 Fees Col: \$716.00 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901663

Applied: 02/17/2009 Issued: 02/17/2009 Parcel: 01601920050000 Finaled:

Site Address: 971 SAGAMORE WAY # Units: 0.00 Sq Ft: 0

Location:

Description: WATER HEATER. GAS. Contractor: RISSE MECHANICAL

Occupancy: R1 Insp Area: 2 Activity Code: P6 WATER HEATER

Valuation: \$100.00 Fees Reg: \$84.04 Fees Col: \$84.04 Bal Due: \$0.00

Activity: RES-0901667 Type: Building / Residential / Addition / Single Family

Parcel: 20104900240000 Applied: 02/17/2009 Issued: 02/17/2009 Finaled:

Site Address: 201 BARNHART CIR # Units: 0.00 Sq Ft: 430

Location:

Description: NEW ALUMINUM PATIOCOVER 430 SQ.FT.

Contractor:

Occupancy: R3 Insp Area: 4 Activity Code: A1 ADD SQFT-EXISTING BLDG

Valuation: \$3.500.00 Fees Req: \$311.82 Fees Col: \$311.82 Bal Due: \$0.00

Activity: RES-0901668 Type: Building / Residential / Minor / Single Family

Parcel: 02702510050000 Issued: 02/17/2009 Applied: 02/17/2009 Finaled:

Site Address: 7720 35TH AVE # Units: 0.00 Sq Ft: 0

Location:

Description: SMUD SAFETY INSPECTION Contractor: H & H ELECTRIC INC

Activity Code: E11 SAFETY INSPECTION Occupancy: R3 Insp Area: 3

Valuation: \$0.00 Fees Req: \$84.00 Fees Col: \$84.00 Bal Due: \$0.00

Type: Building / Residential / Housing-Minor / Single Family Activity: RES-0901669

Parcel: 26502720010000 Applied: 02/17/2009 Issued: 02/17/2009 Finaled:

Page 28

Activity Data Report
City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Page 29

Site Address: 2840 JANETTE WAY #Units: 0.00 Sq Ft: 985

Location:

Description: 08-009127 --Obtain a building permit for the interior remodel and the re-roof. Replace missing HVAC unit. Building permit required.

Replace missing dead front on main electrical panel. Provide approved support for gas water heater in garage.

Contractor:

Occupancy: R3 Insp Area: 4 Activity Code: C4 HOUSING CASES

Valuation: \$5,000.00 Fees Req: \$350.50 Fees Col: \$350.50 Bal Due: \$0.00

Activity: RES-0901672 Type: Building / Residential / Minor / Duplex

 Parcel:
 01200520140000
 Applied:
 02/17/2009
 Issued:
 02/17/2009
 Finaled:
 02/17/2009

 Site Address:
 2730 21ST ST
 # Units:
 2.00
 Sq Ft:
 0

Location:

Description: REPLACE TREE DAMAGED WEATHERHEAD AT DUPLEX DROP.OCCUPIED WITHOUT POWER.

Contractor: GRIFFIN ELECTRIC INC

Occupancy: R3 Insp Area: 2 Activity Code: E1 SERVICE REPAIR

Valuation: \$500.00 Fees Req: \$84.20 Fees Col: \$84.20 Bal Due: \$0.00

Activity: RES-0901674 Type: Building / Residential / Minor / Single Family

 Site Address:
 2101 51ST AVE
 # Units:
 0.00
 Sq Ft:
 0

Location:

Description: C/O WINDOWS IN LIVING ROOM REPLACE SINKS AND FAUCETS IN BOTH BATHROOMS - NO STRUCTURAL WORK

Contractor:

Occupancy: R3 Insp Area: 2 Activity Code: I1 INTERIOR REM-RES

Valuation: \$900.00 Fees Req: \$84.50 Fees Col: \$84.50 Bal Due: \$0.00

Activity: RES-0901675 Type: Building / Residential / Minor / Half Plex

Site Address: 5994 GLORIA DR # Units: 2.00 Sq Ft: 0

Location:

Description: Electrical panel change out, both units, 5994 Gloria Dr & 1083 Lake Glenn. Duplex meter main, Over Head 100 amp service each.

Contractor: EMPIRE ELECTRIC COMPANY

Occupancy: R3 Insp Area: 2 Activity Code: E2 ELEC SERVICE CHANGE

 Valuation:
 \$1,200.00
 Fees Req:
 \$366.00
 Fees Col:
 \$366.00
 Bal Due:
 \$0.00

Activity: RES-0901676 Type: Building / Residential / Housing-Minor / Single Family

Site Address: 3310 62ND ST **# Units:** 0.00 **Sq Ft:** 1,395

Location:

Description: PERMIT FOR SMUD SAFETY INSPECTION.

Contractor:

Occupancy: R3 Insp Area: 3 Activity Code: C4 HOUSING CASES

Valuation: \$999.00 Fees Req: \$234.00 Fees Col: \$234.00 Bal Due: \$0.00

Activity: RES-0901677 Type: Building / Residential / Minor / Single Family

Activity Data Report Page 30 City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Parcel: 25100730230000 Applied: 02/17/2009 Issued: 02/17/2009 Finaled:

Site Address: 3820 DRY CREEK RD # Units: 1.00 Sq Ft: 0

Location:

Description: Electrical Panel Change out, 100 Over head service.

Contractor: SAM'S ELECTRIC

Activity Code: E2 ELEC SERVICE CHANGE Occupancy: R3 Insp Area: 4

Valuation: \$1,435.00 Fees Req: \$86.57 Fees Col: \$86.57 Bal Due: \$0.00

Activity: RES-0901678 Type: Building / Residential / Minor / Single Family

Parcel: 02702510300000 Applied: 02/17/2009 Issued: 02/17/2009 Finaled:

Site Address: 7709 36TH AVE # Units: 0.00 Sq Ft: 0

Location:

Description: HVAC CHANGE-OUT. ROOF UNIT. Contractor: HANLEY & SON'S HEAT & AIR INC

Activity Code: M1 HEATING/AIR CONDITION Occupancy: R1 Insp Area: 3

Valuation: \$4,500.00 Fees Req: \$201.80 Fees Col: \$201.80 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901679

Parcel: 01600810060000 Issued: 02/17/2009 Applied: 02/17/2009 Finaled:

Site Address: 1121 BROWNWYK DR # Units: 0.00 Sq Ft: O

Location:

Description: SEWER SERVICE

Contractor: BERKAN & CLARK HEATING & AIR

Occupancy: R1 Insp Area: 2 Activity Code: P2 SEWER SERVICE

Fees Req: \$93.68 Fees Col: \$93.68 Valuation: \$4,200.00 Bal Due: \$0.00

Activity: RES-0901680 Type: Building / Residential / Minor / Single Family

Parcel: 03111900590000 Applied: 02/17/2009 Issued: 02/17/2009 Finaled:

Site Address: 7745 RIVER VILLAGE DR # Units: 0.00 Sq Ft: 0

Location:

Description: HVAC CHANGE-OUT. SPLIT SYSTEM. Contractor: BERKAN & CLARK HEATING & AIR

Occupancy: R1 Insp Area: 2 Activity Code: M1 HEATING/AIR CONDITION

Fees Req: \$208.93 Fees Col: \$208.93 Valuation: \$7,336.00 Bal Due: \$0.00

Activity: RES-0901683 Type: Building / Residential / Housing-Minor / Single Family

Parcel: 05200940040000 Applied: 02/17/2009 Issued: 02/17/2009 Finaled:

Site Address: 7617 23RD ST # Units: 0.00 Sq Ft: 1,343

Location:

Description: PERMIT TO REPAIR ALL VIOLATIONS ON THE HOUSING VIOLATION LIST. BUILDING, TEAR OFF- REROOF, DRY ROT

REPAIR, REPAIR / REPLACE WINDOWS, RETURN GARAGE TO A CAR PORT, REPAIR WALL HEATERS. ELECTRICAL REPAIRS. PLUMBING DRAIN AT WASHER. PG&E, SMUD SAFETY INSPECTION. LEAD PAINT SURVEY. REPLACE

KITCHEN CABINETS, REPLACE SINK AND PLUMBING.

Contractor:

Occupancy: R3 Insp Area: 2 Activity Code: C4 HOUSING CASES

Valuation: \$11,000.00 Fees Req: \$730.20 Fees Col: \$730.20 Bal Due: \$0.00

Activity Data Report Page 31
City of Sacramento, CA

0

ISSUED between 02/15/2009 and 02/21/2009

Activity: RES-0901684 Type: Building / Residential / Addition / Single Family

Site Address: 6 FIG LEAF CT # Units: 0.00 Sq Ft: 117

Location:

Description: ATTACHEDNEW ALUMINUM PATIOCOVER 117 SQ.FT.

Contractor: COACHWORKS CONSTRUCTION

Occupancy: R3 Insp Area: 4 Activity Code: D3 PATIOCOVER

Valuation: \$2,000.00 Fees Req: \$248.02 Fees Col: \$248.02 Bal Due: \$0.00

Activity: RES-0901685 Type: Building / Residential / Minor / Single Family

 Parcel:
 04901250020000
 Applied:
 02/17/2009
 Issued:
 02/18/2009
 Finaled:

 Site Address:
 7554 SWEETFERN WAY
 # Units:
 0.00
 Sq Ft:

Location:

Description: CHANGE TUB TO SHOWER ONLY **Contractor:** HANLEY & SON'S HEAT & AIR INC

Occupancy: R3 Insp Area: 2 Activity Code: 11 INTERIOR REM-RES

Valuation: \$3,000.00 Fees Req: \$202.02 Fees Col: \$202.02 Bal Due: \$0.00

Activity: RES-0901692 Type: Building / Residential / Repair-Maintenance / Single Family

 Site Address:
 1700 U ST
 # Units:
 0.00
 Sq Ft:
 800

Location:

Description: FIRE DAMAGE: REPAIR SHEETROCK, FLOORING, WINDOWS(LIKE FOR LIKE), ELECTRICAL PLUGS/SWITCHES.

Contractor: STORY DESIGN AND CONSTRUCTION INC

Occupancy: R3 Insp Area: 1 Activity Code: C3 FIRE REPAIR

Valuation: \$20,000.00 Fees Req: \$664.04 Fees Col: \$664.04 Bal Due: \$0.00

Activity: RES-0901693 Type: Building / Residential / Minor / Single Family

Site Address: 740 WESTLITE CIR # Units: 0.00 Sq Ft: 0

Location:

Description: HVAC CHANGE-OUT. ROOF UNIT.

Contractor: GARICK AIR CONDITIONING SERVICE

Occupancy: R1 Insp Area: 2 Activity Code: M1 HEATING/AIR CONDITION

 Valuation:
 \$8,821.00
 Fees Req:
 \$211.53
 Fees Col:
 \$211.53
 Bal Due:
 \$0.00

Activity: RES-0901694 Type: Building / Residential / Minor / Single Family

Site Address: 7031 13TH ST **# Units:** 0.00 **Sq Ft:** 0

Location:

Description: HVAC CHANGE-OUT. SPLIT SYSTEM. **Contractor:** GARICK AIR CONDITIONING SERVICE

Occupancy: R1 Insp Area: 2 Activity Code: M1 HEATING/AIR CONDITION

Activity Data Report 02/23/2009 Page 32 City of Sacramento, CA 08:59:34 AM

ISSUED between 02/15/2009 and 02/21/2009

Valuation: \$12,127.00 Fees Req: \$220.85 Fees Col: \$220.85 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901695

Parcel: 01801120010000 Applied: 02/18/2009 Issued: 02/18/2009 Finaled:

Site Address: 2200 23RD AVE # Units: 0.00 Sq Ft: 0

Location:

Description: WATER HEATER. GAS.

Contractor: MC DONALD PLUMBING HEATING & AIR CONDITIONING INC

Occupancy: R1 Insp Area: 3 Activity Code: P6 WATER HEATER

Valuation: \$1,190.00 Fees Req: \$86.48 Fees Col: \$86.48 Bal Due: \$0.00

Activity: RES-0901697 Type: Building / Residential / Minor / Single Family

Parcel: 01300610120000 Applied: 02/18/2009 Issued: 02/19/2009 Finaled:

Site Address: 2190 MARSHALL WAY # Units: 0.00 Sq Ft:

Location:

Description: GAS LINE TO KITCHEN.

Contractor: J W HARRIS PLUMBING & ROOTER

Occupancy: R1 Insp Area: 3 Activity Code: P6 WATER HEATER

Valuation: \$450.00 Fees Req: \$84.18 Fees Col: \$84.18 Bal Due: \$0.00

Activity: RES-0901698 Type: Building / Residential / Minor / Single Family

Parcel: 03001910010000 Applied: 02/18/2009 Issued: 02/18/2009 Finaled:

Site Address: 6700 HAVENSIDE DR # Units: 0.00 Sq Ft:

Description: HVAC CHANGE-OUT. FURNACE ONLY.

Contractor: SERVICE CHAMPIONS

Insp Area: 2 Activity Code: M1 HEATING/AIR CONDITION Occupancy: R1

Valuation: \$4,508.00 Fees Req: \$201.80 Fees Col: \$201.80 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901699

Parcel: 03103300220000 Applied: 02/18/2009 Issued: 02/18/2009 Finaled:

Site Address: 17 HOPLAND CT # Units: 1.00 Sq Ft:

Location:

Description: Reroof, tear off, re-sheet, install 40 sq of 50 Lam. Dim. Comp.

Contractor: WEATHERTITE ROOFING CO

Occupancy: R3 Insp Area: 2 Activity Code: R1 REROOF

Valuation: \$18,000.00 Fees Req: \$235.00 Fees Col: \$235.00 Bal Due: \$0.00

Type: Building / Residential / Housing-Rental Program / Single Family Activity: RES-0901700

Parcel: 01200440170000 Applied: 02/18/2009 Issued: 02/18/2009 Finaled:

Site Address: 1845 CARAMAY WAY # Units: 0.00 Sq Ft: 1,046

Location:

Description: 08-029711 --- BRING WIRING ON BACK PATIOUP TO CODE, REWIRE.

Contractor: E S ELECTRICAL CONSTRUCTION

Activity Data Report Page 33
City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Occupancy: R3 Insp Area: 2 Activity Code: C4 HOUSING CASES

Valuation: \$999.00 **Fees Req:** \$84.40 **Fees Col:** \$84.40 **Bal Due:** \$0.00

Activity: RES-0901703 Type: Building / Residential / Minor / Single Family

Parcel: 01103900270000 Applied: 02/18/2009 Issued: 02/18/2009 Finaled:

Site Address: 14 GOVERNORS CT # Units: 0.00 Sq Ft: 0

Location:

Description: C/O HEATPUMP PACKAGE UNIT-LIKE FOR LIKE

Contractor: ALLEY & COMPANY INC

Occupancy: R3 Insp Area: 3 Activity Code: M2 HEATPUMP

Valuation: \$8,988.00 Fees Req: \$211.60 Fees Col: \$211.60 Bal Due: \$0.00

Activity: RES-0901704 Type: Building / Residential / Minor / Single Family

Site Address: 7339 MEADOWGATEDR #Units: 0.00 Sq Ft: 0

Location:

Description: SMUD SAFETY.

Contractor:

Occupancy: R1 Insp Area: 2 Activity Code: E11 SAFETY INSPECTION

Valuation: \$100.00 Fees Req: \$84.00 Fees Col: \$84.00 Bal Due: \$0.00

Activity: RES-0901705 Type: Building / Residential / Minor / Single Family

Site Address: 831 PRICE CT #Units: 0.00 Sq Ft: 0

Location:

Description: REROOF. TEAR-OFF. 30 YEAR COMP.

Contractor: DONAHOO JODY RFG

Occupancy: R1 Insp Area: 4 Activity Code: R1 REROOF

Valuation: \$6,000.00 Fees Req: \$205.00 Fees Col: \$205.00 Bal Due: \$0.00

Activity: RES-0901707 Type: Building / Residential / Minor / Single Family

Site Address: 3817 FELL ST # Units: 0.00 Sq Ft: 0

Location:

Description: REROOF. TEAR-OFF. 30 YEAR COMP.

Contractor: MITCHELL ROOFING

Occupancy: R1 Insp Area: 4 Activity Code: R1 REROOF

Valuation: \$3,000.00 Fees Req: \$197.70 Fees Col: \$197.70 Bal Due: \$0.00

Activity: RES-0901708 Type: Building / Residential / Minor / Single Family

Site Address: 2224 LEJANO WAY # Units: 0.00 Sq Ft: 0

Location:

Description: REROOF. TEAR-OFF. 30 YEAR COMP.

Activity Data Report Page 34
City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Contractor: AGUIRRE ROOFING

Occupancy: R1 Insp Area: 4 Activity Code: R1 REROOF

Valuation: \$9,700.00 Fees Req: \$214.85 Fees Col: \$214.85 Bal Due: \$0.00

Activity: RES-0901709 Type: Building / Residential / Minor / Single Family

Site Address: 5623 SPILMAN AVE #Units: 0.00 Sq Ft: 0

Location:

Description: WATER HEATER C/O

Contractor: BONNEY PLUMBING & ROOTER SERVICE

Occupancy: R3 Insp Area: 1 Activity Code: P6 WATER HEATER

Valuation: \$1,700.00 Fees Req: \$86.68 Fees Col: \$86.68 Bal Due: \$0.00

Activity: RES-0901710 Type: Building / Residential / Minor / Single Family

Site Address: 517 SAN MIGUEL WAY # Units: 0.00 Sq Ft: 850

Location:

Description: ELECTRICAL SERVICE CHANGE from 100 to 200 AMPS; REWIRE living, dining, nook & misc as needed, REPLACE/ADD

receptacles & switches as needed

Contractor:

Occupancy: R3 Insp Area: 1 Activity Code: E2 ELEC SERVICE CHANGE

Valuation: \$3,000.00 Fees Req: \$88.00 Fees Col: \$88.00 Bal Due: \$0.00

Activity: RES-0901711 Type: Building / Residential / Minor / Single Family

Site Address: 306 CHENNAULTCT # Units: 0.00 Sq Ft: 0

Location:

Description: REPLACE existing 100AMP electrical panel, INSTALL new weatherhead/riser

Contractor:

Occupancy: R3 Insp Area: 4 Activity Code: E2 ELEC SERVICE CHANGE

Valuation: \$1,500.00 **Fees Req:** \$86.00 **Fees Col:** \$86.00 **Bal Due:** \$0.00

Activity: RES-0901712 Type: Building / Residential / Minor / Duplex

 Parcel: 27501650070000
 Applied: 02/18/2009
 Issued: 02/18/2009
 Finaled: 02/18/2009

 Site Address: 1133 LOCHBRAE RD
 # Units: 0.00
 Sq Ft: 0

Location:

Description: REPAIR ELECTRICAL SERVICE - WEATHER HEAD AND RISER THAT WAS DAMAGED BY TREE

Contractor: ERA ELECTRIC

Occupancy: R3 Insp Area: 4 Activity Code: E1 SERVICE REPAIR

Valuation: \$1,000.00 Fees Req: \$120.04 Fees Col: \$120.04 Bal Due: \$0.00

Activity: RES-0901713 Type: Building / Residential / Minor / Single Family

 Parcel:
 01302110100000
 Applied:
 02/18/2009
 Issued:
 02/18/2009
 Finaled:
 02/20/2009

 Site Address:
 2678 5TH AVE
 # Units:
 0.00
 Sq Ft:
 0

Location:

/ Data Report Page 35

02/23/2009 08:59:34 AM

Activity Data Report City of Sacramento, CA ISSUED between 02/15/2009 and 02/21/2009

Description: RUN GAS LINE TO BBQ.

Contractor: BONNEY PLUMBING & ROOTER SERVICE

Occupancy: R1 Insp Area: 3 Activity Code: P5 GAS TEST/LINE REPAIR

Valuation: \$2,289.00 Fees Req: \$88.92 Fees Col: \$88.92 Bal Due: \$0.00

Activity: RES-0901715 Type: Building / Residential / Minor / Single Family

 Site Address: 3806 MODDISON AVE
 # Units: 0.00
 Sq Ft: 0

Location:

Description: TWO BATHROOMREMODELS.

Contractor: KITCHEN MART INC

Occupancy: R1 Insp Area: 1 Activity Code: C1 GENERAL REPAIR/FIX-IT

Valuation: \$25,000.00 Fees Req: \$586.22 Fees Col: \$586.22 Bal Due: \$0.00

Activity: RES-0901716 Type: Building / Residential / Minor / Single Family

Site Address: 15 ALVARESCT # Units: 0.00 Sq Ft: 0

Location:

Description: REMODEL KITCHEN C/O CABNETS -SAME LOCATIONNEW ELECTRICAL CIRCUITS AND NEW SINK -NO STRUCTURAL

WORK-SMOKE DETECTORS REQUIRED

Contractor: MR FLOORS

Occupancy: R3 Insp Area: 4 Activity Code: 11 INTERIOR REM-RES

Valuation: \$24,300.00 Fees Req: \$576.15 Fees Col: \$576.15 Bal Due: \$0.00

Activity: RES-0901718 Type: Building / Residential / Minor / Single Family

Parcel: 02302030030000 Applied: 02/18/2009 Issued: 02/18/2009 Finaled:

Site Address: 7900 25TH AVE #Units: 0.00 Sq Ft: 0

Location:

Description: UPGRADE PANEL. 200AMP.

Contractor:

Occupancy: R1 Insp Area: 3 Activity Code: E2 ELEC SERVICE CHANGE

 Valuation:
 \$800.00
 Fees Req:
 \$84.00
 Fees Col:
 \$84.00
 Bal Due:
 \$0.00

Activity: RES-0901721 Type: Building / Residential / Minor / Single Family

Site Address: 7624 PRESCOTT WAY # Units: 0.00 Sq Ft: 0

Location:

Description: REROOF. TEAR-OFF, RESHEET. 30 YEAR COMP.

Contractor: QUALITY FIRST HOME IMPROVMENTINC

Occupancy: R1 Insp Area: 2 Activity Code: R1 REROOF

 Valuation:
 \$17,554.00
 Fees Req:
 \$234.78
 Fees Col:
 \$234.78
 Bal Due:
 \$0.00

Activity: RES-0901722 Type: Building / Residential / Minor / Single Family

 Parcel: 22509900560000
 Applied: 02/18/2009
 Issued: 02/18/2009
 Finaled:

 Site Address:
 1180 RUDGER WAY
 # Units:
 0.00
 Sq Ft:
 0

Activity Data Report Page 36 City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Location:

Description: REROOF, TEAR-OFF, RESHEET, 30 YEAR COMP.

Contractor: QUALITY FIRST HOME IMPROVMENTING

Occupancy: R1 Activity Code: R1 REROOF

Valuation: \$14,893.00 Fees Req: \$227.45 Fees Col: \$227.45 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901723

Parcel: 03100820250000 Applied: 02/18/2009 Issued: 02/18/2009 Finaled:

Site Address: 1320 VALLEY BROOK AVE # Units: 0.00 Sq Ft: 0

Location:

Description: EAR OFF SHAKE AND RESHEET AND REROOF WITH

Contractor: QUALITY FIRST HOME IMPROVMENTING

Occupancy: R3 Activity Code: R1 REROOF Insp Area: 2

Valuation: \$22,557.00 Fees Req: \$247.28 Fees Col: \$247.28 Bal Due: \$0.00

Activity: RES-0901724 Type: Building / Residential / Repair-Maintenance / Single Family

Parcel: 25101940140000 Applied: 02/18/2009 Issued: 02/18/2009 Finaled:

Site Address: 1003 CONGRESS AVE # Units: 0.00 Sq Ft:

Location:

Description: Repair front exterior wall, replace 2 vinyl windows, lap siding, 1 electrical circuit due to car damage. Replace like for like.

Contractor: TUDOR CONSTRUCTION & RESTORATION CO

Occupancy: R3 Insp Area: 4 Activity Code: C1 GENERAL REPAIR/FIX-IT

Valuation: \$8,529.00 Fees Req: \$477.54 Fees Col: \$477.54 Bal Due: \$0.00

Type: Building / Residential / Housing-Minor / Single Family Activity: RES-0901725

Parcel: 26302240100000 Applied: 02/18/2009 Issued: 02/18/2009 Finaled:

Site Address: 355 EL CAMINO AVE 7 # Units: 0.00 Sq Ft:

Location:

Description: 08-100914 -- Provide approved type and installation of room heater which will maintain a temperature of 70 degrees three (3) feet

above the floor for all units. Area of electrical service and water heater unsafe for use, Electical and plumbing done without

permits.

Contractor:

Activity Code: C4 HOUSING CASES Occupancy: R2.1 Insp Area: 4

Valuation: \$5,000.00 Fees Req: \$409.90 Fees Col: \$409.90 Bal Due: \$0.00

Type: Building / Residential / Housing-Minor / Single Family Activity: RES-0901725

Parcel: 26302240100000 Applied: 02/18/2009 Issued: 02/18/2009 Finaled:

Site Address: 355 EL CAMINO AVE 7 # Units: 0.00 Sq Ft: 0

Location:

Description: 08-100914 -- Provide approved type and installation of room heater which will maintain a temperature of 70 degrees three (3) feet

above the floor for all units. Area of electrical service and water heater unsafe for use, Electical and plumbing done without

Contractor:

Occupancy: R2.1 Insp Area: 4 Activity Code: C4 HOUSING CASES

Valuation: \$5,000.00 Fees Req: \$409.90 Fees Col: \$409.90 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901727

Activity Data Report Page 37
City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Site Address: 1401 36TH ST **# Units:** 0.00 **Sq Ft:** 0

Location:

Description: INSTALL SOLAR SYSTEM WATER HEATER

Contractor: AZTEC SOLAR

Occupancy: R3 Insp Area: 1 Activity Code: P6 WATER HEATER

Valuation: \$6,395.00 Fees Req: \$99.20 Fees Col: \$99.20 Bal Due: \$0.00

Activity: RES-0901728 Type: Building / Residential / Minor / Single Family

 Parcel:
 03502630090000
 Applied:
 02/18/2009
 Issued:
 02/18/2009
 Finaled:
 02/19/2009

 Site Address:
 2187 57TH AVE
 # Units:
 0.00
 Sq Ft:
 0

Location:

Description: REPAIR-CHANGE FEEDER CONDUCTORS BETWEEN METER AND MAIN

Contractor: OMAR'S ELECTRIC WORKS

Occupancy: R3 Insp Area: 2 Activity Code: E1 SERVICE REPAIR

Valuation: \$500.00 Fees Req: \$84.20 Fees Col: \$84.20 Bal Due: \$0.00

Activity: RES-0901729 Type: Building / Residential / Minor / Single Family

Site Address: 6541 LONGRIDGE WAY # Units: 0.00 Sq Ft: 0

Location:

Description: WATER HEATER. GAS.

Contractor: BONNEY PLUMBING & ROOTER SERVICE

Occupancy: R1 Insp Area: 2 Activity Code: P6 WATER HEATER

Valuation: \$1,800.00 Fees Req: \$86.72 Fees Col: \$86.72 Bal Due: \$0.00

Activity: RES-0901731 Type: Building / Residential / Housing Dept Permit / Single Family

Parcel: 04903400460000 **Applied**: 02/18/2009 **Issued**: 02/18/2009 **Finaled**:

Site Address: 28 CREEKS EDGE WAY #Units: 0.00 Sq Ft: 1,200

Location:

Description: Repairs as per housing checklist to include; HVAC repairs, repair to electrical panel, drywall repairs and minor plumbing,

electrical, and minor building repairs.

Contractor:

Occupancy: R3 Insp Area: 2 Activity Code: C4 HOUSING CASES

Valuation: \$1,500.00 Fees Req: \$272.14 Fees Col: \$272.14 Bal Due: \$0.00

Activity: RES-0901732 Type: Building / Residential / Addition / Single Family

Parcel: 20109200140000 **Applied:** 02/18/2009 **Issued:** 02/18/2009 **Finaled:**

Site Address: 5659 AMNEST WAY **# Units:** 0.00 **Sq Ft:** 168

Location:

Description: NEW SOLID PATIOCOVER 168 SQ.FT.

Contractor: CREATIVE PATIOAWNINGS

Occupancy: R3 Insp Area: 4 Activity Code: D3 PATIOCOVER

Valuation: \$4,082.40 Fees Req: \$362.23 Fees Col: \$362.23 Bal Due: \$0.00

Activity Data Report 02/23/2009 City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Activity: RES-0901734 Type: Building / Residential / Minor / Single Family

Parcel: 01303540020000 Applied: 02/18/2009 Issued: 02/18/2009 Finaled:

Site Address: 3219 38TH ST # Units: 0.00 Sq Ft: 0

Location:

Description: MINOR PLUMBING, ELECTRICAL REPAIRS.

Contractor:

Occupancy: R1 Insp Area: 3 Activity Code: C1 GENERAL REPAIR/FIX-IT

Valuation: \$1,000.00 Fees Req: \$84.00 Fees Col: \$84.00 Bal Due: \$0.00

Type: Building / Residential / Demolition / Single Family Activity: RES-0901738

Parcel: 00800830040000 Applied: 02/18/2009 Issued: 02/18/2009 Finaled:

Site Address: 836 57TH ST # Units: 0.00 Sq Ft: 1,846

Location:

Description: INTERIOR DEMO OF EXISTING SFR: FIREPLACE, STAIRCASE, DOORS ELECTRICAL KNOB & TUBE. DRYROT REPAIR IN

Contractor:

Occupancy: R1 Insp Area: 1 Activity Code: 11 INTERIOR REM-RES

Valuation: \$1,500.00 Fees Req: \$194.00 Fees Col: \$194.00 Bal Due: \$0.00

Activity: RES-0901739 Type: Building / Residential / Minor / Single Family

Parcel: 11710500040000 Applied: 02/19/2009 Issued: 02/19/2009 Finaled:

Site Address: 5131 CALVINE RD # Units: 0.00 Sq Ft:

Location:

Description: WATER HEATER. GAS. Contractor: LOZANO MIKE JOHN

Activity Code: P6 WATER HEATER Occupancy: R1 Insp Area: 2

Valuation: \$610.00 Fees Req: \$84.24 Fees Col: \$84.24 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901741

Parcel: 01800820350000 Applied: 02/19/2009 Issued: 02/19/2009 Finaled:

Site Address: 2209 22ND AVE # Units: 0.00 Sq Ft: 0

Location:

Description: INSTALLTANKLESS WATER HEATER.

Contractor: YANCEY COMPANY

Occupancy: R1 Insp Area: 3 Activity Code: P6 WATER HEATER

Valuation: \$2,000.00 Fees Req: \$86.80 Fees Col: \$86.80 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901742

Parcel: 00400840200000 Applied: 02/19/2009 Issued: 02/19/2009 Finaled:

Site Address: 121 46TH ST # Units: 0.00 Sq Ft: 0

Location:

Description: REROOF. TEAR-OFF, RESHEET. 30 YEAR COMP.

Contractor: LEWIS DON

Occupancy: R1 Insp Area: 1 Activity Code: R1 REROOF

Valuation: \$5,700.00 Fees Req: \$204.85 Fees Col: \$204.85 Bal Due: \$0.00

Activity Data Report 02/23/2009 City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Type: Building / Residential / Minor / Single Family Activity: RES-0901743

Parcel: 02300910200000 Applied: 02/19/2009 Issued: 02/19/2009 Finaled:

Site Address: 4991 76TH ST # Units: 0.00 Sq Ft: 0

Location:

Description: REROOF. OVERLAY. 30 YEAR COMP. OVERLAY LAP SIDING IN FRONT.

Contractor: GRUBBS CONST

Activity Code: R1 REROOF Occupancy: R1 Insp Area: 3

Valuation: \$3,400.00 Fees Req: \$199.86 Fees Col: \$199.86 Bal Due: \$0.00

Activity: RES-0901748 Type: Building / Residential / Minor / Single Family

Parcel: 01901140150000 Applied: 02/19/2009 Issued: 02/19/2009 Finaled:

Site Address: 2505 PHYLLIS AVE # Units: 0.00 Sq Ft: 0

Location:

Description: HVAC CHANGE-OUT. ROOF UNIT.

Contractor: MC DONALD PLUMBING HEATING & AIR CONDITIONING INC

Activity Code: M1 HEATING/AIR CONDITION Occupancy: R1 Insp Area: 3

Valuation: \$9,562.00 Fees Req: \$213.82 Fees Col: \$213.82 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901749

Parcel: 03104900380000 Applied: 02/19/2009 Issued: 02/19/2009 Finaled:

Site Address: 9 RIO PORTO CT # Units: 0.00 Sq Ft: 0

Location:

Description: REROOF. TEAR-OFF, RESHEET. INSTALLLIGHT WEIGHT TILE.

Contractor: MONARCH ROOFING SERVICE

Activity Code: R1 REROOF Occupancy: R1 Insp Area: 2

Valuation: \$25,000.00 Fees Req: \$252.50 Fees Col: \$252.50 Bal Due: \$0.00

Activity: RES-0901754 Type: Building / Residential / Minor / Single Family

Parcel: 23705300290000 Applied: 02/19/2009 Issued: 02/19/2009 Finaled:

Site Address: 1028 ANDY CIR # Units: 0.00 Sq Ft: 0

Location:

Description: REROOF 2-STORY - T/O; RESHEET; INSTALL 26 SQ 30 YR COMP ON SFD & GAR

Contractor: F X ROOFING CO

Occupancy: R3 Insp Area: 4 Activity Code: R1 REROOF

Valuation: \$6,500.00 Fees Req: \$207.25 Fees Col: \$207.25 Bal Due: \$0.00

Activity: RES-0901761 Type: Building / Residential / Minor / Single Family

Parcel: 11701030190000 Issued: 02/19/2009 Applied: 02/19/2009 Finaled:

Site Address: 5931 HOLLYHURST WAY # Units: 0.00 Sq Ft: 0

Location:

Description: REPLACE SERVICE PANEL. Contractor: MURRAY'S ELECTRIC SERVICE

Occupancy: R1 Insp Area: 2 Activity Code: E10 ELEC EQUIPMENT INSTALL Valuation: \$1,600.00 Fees Req: \$86.64 Fees Col: \$86.64 Bal Due: \$0.00

Activity Data Report
City of Sacramento, CA

Page 40

ISSUED between 02/15/2009 and 02/21/2009

Activity: RES-0901763 Type: Building / Residential / Minor / Single Family

Site Address: 4821 D ST #Units: 0.00 Sq Ft: 0

Location:

Description: HVAC CHANGE-OUT, ROOF UNIT.

Contractor: ONE HOUR HEATING AND AIR CONDITIONING

Occupancy: R1 Insp Area: 1 Activity Code: M1 HEATING/AIR CONDITION

Valuation: \$8,000.00 Fees Req: \$209.20 Fees Col: \$209.20 Bal Due: \$0.00

Activity: RES-0901770 Type: Building / Residential / Minor / Single Family

 Parcel: 02002140060000
 Applied: 02/19/2009
 Issued: 02/19/2009
 Finaled: 02/20/2009

 Site Address:
 3620 20TH AVE
 # Units:
 1.00
 Sq Ft:
 0

Location:

Description: Electrical Service Change Out, O.H. 200 amp service.

Contractor: SELECTRIC

Occupancy: R3 Insp Area: 3 Activity Code: E2 ELEC SERVICE CHANGE

Valuation: \$1,200.00 Fees Req: \$86.48 Fees Col: \$86.48 Bal Due: \$0.00

Activity: RES-0901772 Type: Building / Residential / Minor / Single Family

Site Address: 1200 PEBBLEWOOD DR #Units: 1.00 Sq Ft: 0

Location:

Description: Reroof (Dry Rot Repair), Over-lay, Install 30 yr lam. dim comp.

Contractor:

Occupancy: R3 Insp Area: 4 Activity Code: R1 REROOF

Valuation: \$2,100.00 Fees Req: \$196.50 Fees Col: \$196.50 Bal Due: \$0.00

Activity: RES-0901773 Type: Building / Residential / Housing-Minor / Single Family

Parcel: 01401830170000 **Applied:** 02/19/2009 **Issued:** 02/19/2009 **Finaled:**

Site Address: 3987 8TH AVE # Units: 0.00 Sq Ft: 1,000

Location:

Description: REPAIRSAS PER HSG VIOLATIONS LIST.MINOR ELECTRICAL STRUCTURAL PLUMBING. WINDOW REPAIR HVAC.

Contractor: FRESH PAINTING

Occupancy: R3 Insp Area: 3 Activity Code: C4 HOUSING CASES

Valuation: \$10,000.00 Fees Req: \$527.00 Fees Col: \$527.00 Bal Due: \$0.00

Activity: RES-0901775 Type: Building / Residential / Minor / Single Family

 Parcel: 00802620020000
 Applied: 02/19/2009
 Issued: 02/19/2009
 Finaled:

 Site Address: 1356 42ND ST
 # Units: 0.00
 Sq Ft: 0

Location:

Description: REPLACE SEWER. TRENCHLESS. **Contractor:** ACE PLUMBING HEATING & AIR

Occupancy: R1 Insp Area: 1 Activity Code: P2 SEWER SERVICE

Valuation: \$5,100.00 Fees Req: \$96.04 Fees Col: \$96.04 Bal Due: \$0.00

Activity Data Report
City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Activity: RES-0901776 Type: Building / Residential / Minor / Single Family

Site Address: 724 SAN ANTONIO WAY #Units: 0.00 Sq Ft: 0

Location:

Description: WATER HEATER. GAS.

Contractor: BONNEY PLUMBING & ROOTER SERVICE

Occupancy: R1 Insp Area: 1 Activity Code: P6 WATER HEATER

Valuation: \$2,000.00 Fees Req: \$86.80 Fees Col: \$86.80 Bal Due: \$0.00

Activity: RES-0901778 Type: Building / Residential / Minor / Single Family

Site Address: 6242 OAKRIDGE WAY # Units: 0.00 Sq Ft: 0

Location:

Description: REPLACE DRAIN LINES UNDER HOUSE **Contractor:** ACE PLUMBING HEATING & AIR

Occupancy: R1 Insp Area: 2 Activity Code: P2 SEWER SERVICE

Valuation: \$6,495.00 Fees Req: \$98.60 Fees Col: \$98.60 Bal Due: \$0.00

Activity: RES-0901780 Type: Building / Residential / Minor / Single Family

Site Address: 2123 FLORIN RD **# Units:** 0.00 **Sq Ft:** 0

Location:

Description: REPLACE SEWER. TRENCHLESS. **Contractor:** ACE PLUMBING HEATING & AIR

Occupancy: R1 Insp Area: 2 Activity Code: P2 SEWER SERVICE

Valuation: \$3,180.00 Fees Req: \$91.27 Fees Col: \$91.27 Bal Due: \$0.00

Activity: RES-0901781 Type: Building / Residential / Minor / Single Family

Site Address: 2720 17TH ST **# Units:** 0.00 **Sq Ft:** 0

Location:

Description: UPGRADE PANEL.

Contractor:

Occupancy:R1Insp Area:2Activity Code:E10 ELEC EQUIPMENT INSTALLValuation:\$500.00Fees Req:\$84.00Fees Col:\$84.00Bal Due:\$0.00

Activity: RES-0901785 Type: Building / Residential / Minor / Single Family

 Parcel: 03600210160000
 Applied: 02/19/2009
 Issued: 02/19/2009
 Finaled:

Site Address: 2521 ENCINAL AVE # Units: 1.00 Sq Ft: 0

Location:

Description: SERVICE CHANGE TO 200 AMP.OPEN REROOF PERMIT #0606786 NEEDS A FINAL.

Contractor:

Occupancy: R3 Insp Area: 3 Activity Code: E2 ELEC SERVICE CHANGE

 Valuation:
 \$1,500.00
 Fees Req:
 \$86.00
 Fees Col:
 \$86.00
 Bal Due:
 \$0.00

Activity Data Report 02/23/2009 Page 42 City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Activity: RES-0901787 Type: Building / Residential / Minor / Single Family

Parcel: 02102610060000 Applied: 02/19/2009 Issued: 02/19/2009 Finaled:

Site Address: 4459 71ST ST # Units: 0.00 Sq Ft: 0

Location:

Description: HVAC CUT-IN, SPLIT SYSTEM. Contractor: IMPERIAL HEATING & COOLING

Occupancy: R1 Activity Code: M1 HEATING/AIR CONDITION Insp Area: 3

Valuation: \$4.800.00 Fees Req: \$202.42 Fees Col: \$202.42 Bal Due: \$0.00

Activity: RES-0901788 Type: Building / Residential / Minor / Single Family

Parcel: 01602030010000 Applied: 02/19/2009 Issued: 02/19/2009 Finaled:

Site Address: 904 PIEDMONT DR # Units: 0.00 Sq Ft: 0

Location:

Description: 2 BATHROOM REMODELS.REPLACE TREADS AT STAIRS. NEW HANDRAIL.

Contractor: GARRETT CONSTRUCTION

Occupancy: R1 Activity Code: C1 GENERAL REPAIR/FIX-IT Insp Area: 2

Valuation: \$20,000.00 Fees Req: \$524.04 Fees Col: \$524.04 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901790

Parcel: 29300200010000 Applied: 02/19/2009 Issued: 02/19/2009 Finaled:

Site Address: 216 E RANCH RD # Units: 0.00 Sq Ft: 0

Location:

Description: DRY ROT REPAIR. T-111 SIDING, FASCIA.

Contractor: WILLIAMS JAMES E & SON INC

Occupancy: R1 Insp Area: 1 Activity Code: C1 GENERAL REPAIR/FIX-IT

Bal Due: \$0.00 Valuation: \$1,800.00 Fees Req: \$122.86 Fees Col: \$122.86

Activity: RES-0901793 Type: Building / Residential / Minor / Single Family

Parcel: 27401310200000 Applied: 02/19/2009 Issued: 02/19/2009 Finaled: 02/19/2009 Site Address: 471 CLEVELAND AVE # Units: 0.00 Sq Ft:

Location:

Description: SMUD SAFETY.

Contractor:

Activity Code: E11 SAFETY INSPECTION Occupancy: R1 Insp Area: 4

Valuation: \$100.00 Fees Req: \$84.00 Fees Col: \$84 00 Bal Due: \$0.00

Type: Building / Residential / Remodel / Single Family Activity: RES-0901794

Parcel: 02401820060000 Applied: 02/19/2009 Issued: 02/19/2009 Finaled:

Site Address: 5900 HOLSTEIN WAY # Units: 1.00 Sq Ft: 2,000

Location:

Description: Remodel kitchen, & bathroom, & garage fire wall.

Contractor: D Design Build

Activity Code: I1 INTERIOR REM-RES Occupancy: R3 Insp Area: 2

Valuation: \$20,000.00 Fees Req: \$862.76 Fees Col: \$862.76 Bal Due: \$0.00

Activity Data Report 02/23/2009 City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Type: Building / Residential / Housing-Minor / Single Family Activity: RES-0901800

Parcel: 03601060290000 Applied: 02/19/2009 Issued: 02/19/2009 Finaled:

Site Address: 2429 51ST AVE # Units: 0.00 Sq Ft: 1,500

Location:

Description: REPAIRS AS PER HSG VIOLATIONS LIST [SMUD SAFETY INSPECTION]

Contractor:

Occupancy: R3 Insp Area: 3 Activity Code: C4 HOUSING CASES

Valuation: \$3.500.00 Fees Req: \$352.82 Fees Col: \$352.82 Bal Due: \$0.00

Activity: RES-0901804 Type: Building / Residential / Minor / Single Family

Parcel: 00400920020000 Applied: 02/19/2009 Issued: 02/20/2009 Finaled:

Site Address: 4754 A ST # Units: 0.00 Sq Ft: 0

Location:

Description: REROOF. TEAR-OFF. 50 YEAR COMP.

Contractor: ZIMMERMAN RE - ROOFING INC

Occupancy: R1 Activity Code: R1 REROOF Insp Area: 1

Bal Due: \$0.00 Valuation: \$5,080.00 Fees Req: \$204.54 Fees Col: \$204.54

Type: Building / Residential / Minor / Single Family Activity: RES-0901805

Parcel: 02902740040000 Applied: 02/19/2009 Issued: 02/20/2009 Finaled:

Site Address: 6648 LAKE PARK DR # Units: 0.00 Sq Ft: 0

Location:

Description: HVAC CHANGE-OUT. SPLIT SYSTEM.

Contractor: MC DONALD PLUMBING HEATING & AIR CONDITIONING INC

Occupancy: R1 Insp Area: 2 Activity Code: M1 HEATING/AIR CONDITION

Valuation: \$8,370.00 Fees Req: \$211.35 Fees Col: \$211.35 Bal Due: \$0.00

Activity: RES-0901806 Type: Building / Residential / Minor / Single Family

Parcel: 01302720050000 Applied: 02/19/2009 Issued: 02/20/2009 Finaled:

Site Address: 3300 CUTTER WAY # Units: 0.00 Sq Ft: 0

Location:

Description: HVAC CHANGE-OUT. SPLIT SYSTEM.

Contractor: MC DONALD PLUMBING HEATING & AIR CONDITIONING INC

Activity Code: M1 HEATING/AIR CONDITION Occupancy: R1 Insp Area: 3

Valuation: \$12,757.00 Fees Req: \$221.10 Fees Col: \$221 10 Bal Due: \$0.00

Type: Building / Residential / Remodel / Single Family Activity: RES-0901809

Parcel: 29300610250000 Applied: 02/19/2009 Issued: 02/19/2009 Finaled:

Site Address: 2619 LATHAM DR # Units: 1.00 Sq Ft: 200

Location:

Description: Interior bathroom remodel. Contractor: JIL DESIGN GROUP INC

Activity Code: I1 INTERIOR REM-RES Occupancy: R3 Insp Area: 1

Valuation: \$10,887.00 Fees Req: \$667.40 Fees Col: \$667.40 Bal Due: \$0.00

Activity Data Report 02/23/2009 City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Activity: RES-0901810 Type: Building / Residential / Minor / Single Family

Parcel: 26302110110000 Applied: 02/19/2009 Issued: 02/19/2009 Finaled:

Site Address: 64 BAY DR # Units: 1.00 Sq Ft: 0

Location:

Description: ELECTRICAL REPAIRS. BRACE KIT. RIGHT LINE CLIP. DEAD FRONT. SERVICE CHANGE TO 200 AMP IF NECESSARY.

Contractor: GEORGE TRANSILVANIANCONSTRUCTION

Occupancy: R1 Activity Code: E1 SERVICE REPAIR Insp Area: 4

Valuation: \$1.500.00 Fees Req: \$84.20 Fees Col: \$84.20 Bal Due: \$0.00

Activity: RES-0901811 Type: Building / Residential / Minor / Single Family

Parcel: 00501620160000 Applied: 02/19/2009 Issued: 02/19/2009 Finaled:

Site Address: 5732 CALLISTER AVE # Units: 0.00 Sq Ft: 0

Location:

Description: SEWER SERVICE. TRENCHLESS.

Contractor: ROONEY'S PLUMBING CO

Occupancy: R1 Activity Code: P2 SEWER SERVICE Insp Area: 1

Bal Due: \$0.00 Valuation: \$1,740.00 Fees Req: \$86.70 Fees Col: \$86.70

Type: Building / Residential / Minor / Single Family Activity: RES-0901812

Parcel: 01801210170000 Applied: 02/19/2009 Issued: 02/19/2009 Finaled:

Site Address: 4641 22ND ST # Units: 0.00 Sq Ft: 0

Location:

Description: REPLACE SEWER LINE. Contractor: ROONEY'S PLUMBING CO

Activity Code: P2 SEWER SERVICE Occupancy: R1 Insp Area: 3

Bal Due: \$0.00 Valuation: \$1,185.00 Fees Req: \$86.47 Fees Col: \$86.47

Activity: RES-0901813 Type: Building / Residential / Housing-Minor / Single Family

Parcel: 02700400300000 Applied: 02/19/2009 Issued: 02/19/2009 Finaled:

Site Address: 5621 66TH ST # Units: 0.00 Sq Ft:

Location:

Description: 08-008790--Expired permit res-0813629. To complete repairs from violations list.

Contractor:

Activity Code: C4 HOUSING CASES Occupancy: R3 Insp Area: 3

Valuation: \$999.00 Fees Req: \$234.50 Fees Col: \$234.50 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901814

Parcel: 22506000630000 Applied: 02/19/2009 Issued: 02/19/2009 Finaled: 02/20/2009 Site Address: 1358 GRENDEL WAY # Units: 0.00 Sq Ft:

Location:

Description: REPLACEMENT OF STOLEN CIRCUIT BREAKER.

Contractor:

Activity Code: C1 GENERAL REPAIR/FIX-IT Occupancy: R3 Insp Area: 4

Valuation: \$100.00 Fees Req: \$84.00 Fees Col: \$84.00 Bal Due: \$0.00

Activity Data Report City of Sacramento, CA

Units: 0.00

Sq Ft:

0

ISSUED between 02/15/2009 and 02/21/2009

Activity: RES-0901814 Type: Building / Residential / Minor / Single Family

Parcel: 22506000630000 Applied: 02/19/2009 Issued: 02/19/2009 Finaled: 02/20/2009 Site Address: 1358 GRENDEL WAY

Location:

Description: REPLACEMENT OF STOLEN CIRCUIT BREAKER.

Contractor:

Activity Code: C1 GENERAL REPAIR/FIX-IT Occupancy: R3 Insp Area: 4

Valuation: \$100.00 Fees Req: \$84.00 Fees Col: \$84.00 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901815

Parcel: 01501230450000 Applied: 02/20/2009 Issued: 02/20/2009 Finaled:

Site Address: 5025 9TH AVE # Units: 0.00 Sq Ft: 0

Location:

Description: HVAC CUT-IN. ROOF UNIT.

Contractor: CALIFORNIA ENERGY CONSULTANTSERVICES

Occupancy: R1 Insp Area: 3 Activity Code: M1 HEATING/AIR CONDITION

Valuation: \$7,488.00 Fees Req: \$209.00 Fees Col: \$209.00 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901817

Parcel: 01301810390000 Applied: 02/20/2009 Issued: 02/20/2009 Finaled:

Site Address: 2232 8TH AVE # Units: 0.00 Sq Ft: 0

Location:

Description: HVAC CHANGE-OUT. ROOF UNIT.

Contractor: ONE HOUR HEATING AND AIR CONDITIONING

Occupancy: R1 Insp Area: 2 Activity Code: M1 HEATING/AIR CONDITION

Valuation: \$12,360.00 Fees Req: \$220.94 Fees Col: \$220.94 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901821

Parcel: 07800410100000 Applied: 02/20/2009 Issued: 02/20/2009 Finaled:

Site Address: 125 WATERGLENCIR # Units: 0.00 Sq Ft: 0

Location:

Description: HVAC CHANGE-OUT. SPLIT SYSTEM.

Contractor: PACIFIC HEAT & AIR INC

Activity Code: M1 HEATING/AIR CONDITION Occupancy: R1 Insp Area: 1

Valuation: \$1,900.00 Fees Req: \$194.76 Fees Col: \$194.76 Bal Due: \$0.00

Activity: RES-0901822 Type: Building / Residential / Minor / Single Family

Parcel: 11800710150000 Applied: 02/20/2009 Issued: 02/20/2009 Finaled:

Site Address: 7607 PRESCOTT WAY # Units: 0.00 Sq Ft: 0

Location:

Description: PANEL CHANGE OUT TO 125 AMP

Contractor: EMARD'S ELECTRICAL HOME TECHNICIANS INC

Activity Code: E2 ELEC SERVICE CHANGE Occupancy: R3 Insp Area: 2

Valuation: \$2,876.00 Fees Req: \$89.15 Fees Col: \$89.15 Bal Due: \$0.00

Activity Data Report
City of Sacramento, CA

Page 46

ISSUED between 02/15/2009 and 02/21/2009

Activity: RES-0901823 Type: Building / Residential / Minor / Single Family

Site Address: 2383 BEAUMONT ST #Units: 0.00 Sq Ft: 0

Location:

Description: REPLACE SEWER SERVICE.

Contractor: BONNEY PLUMBING & ROOTER SERVICE

Occupancy: R1 Insp Area: 4 Activity Code: P2 SEWER SERVICE

Valuation: \$7,725.00 Fees Req: \$101.09 Fees Col: \$101.09 Bal Due: \$0.00

Activity: RES-0901826 Type: Building / Residential / Housing-Minor / Single Family

Site Address: 3433 6TH AVE **# Units:** 0.00 **Sq Ft:** 888

Location:

Description: PERMIT TO REPAIR ALL VIOLATIONS LISTED ON THE HOUSING VIOLATIONS LIST. INSTALL SMOKE DECTORS

ACCORDING TO DIRECTIOS. REPAIR REAR SIDING. WATERPROOF, LAPPING. ELECTRIC REPAIRS IN BEDROOM AREAS. WALL HEATERS NEED TO BE INSPECTED AND PERMITTED. WATER HEATER NEEDS TPR PIPE EXTENDED TO

EXTERIOR, REPAIR WATER HEATER VENTILATION PIPE IN ACCORDANCE TO CODE SPECIFICATIONS, VALVE NEEDED

ON COLD WATER SIDE.

Contractor:

Occupancy: R3 Insp Area: 3 Activity Code: C4 HOUSING CASES

Valuation: \$1,000.00 Fees Req: \$270.14 Fees Col: \$270.14 Bal Due: \$0.00

Activity: RES-0901828 Type: Building / Residential / Minor / Single Family

 Site Address:
 3119 PERRYMAN WAY
 # Units:
 0.00
 Sq Ft:
 0

Location:

Description: CHNGE PANEL UPGRADE TO 125 AMP

Contractor: EMARD'S ELECTRICAL HOME TECHNICIANS INC

Occupancy: R3 Insp Area: 3 Activity Code: E2 ELEC SERVICE CHANGE

Valuation: \$2,876.00 Fees Req: \$89.15 Fees Col: \$89.15 Bal Due: \$0.00

Activity: RES-0901829 Type: Building / Residential / Minor / Duplex

Site Address: 959 FREMONT WAY # Units: 0.00 Sq Ft: 0

Location:

Description: HVAC CHANGE-OUT. GROUND UNIT.

Contractor: PERFECTION HOME SYSTEMS INC

Occupancy: R1 Insp Area: 2 Activity Code: M1 HEATING/AIR CONDITION

Valuation: \$8,137.00 Fees Req: \$211.25 Fees Col: \$211.25 Bal Due: \$0.00

Activity: RES-0901831 Type: Building / Residential / Minor / Duplex

 Parcel:
 03100700740000
 Applied:
 02/20/2009
 Issued:
 02/20/2009
 Finaled:

Site Address: 132 FOUNTAINOAKS CIR #Units: 0.00 Sq Ft: 0

Location:

Description: DUPLEX UNITS 147-149. T/O 1 STORY 40 SQ'S 50 YR COMP. IN PROGRESS INSPECTION REQUIRED

Activity Data Report Page 47
City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Contractor: R & R ENTERPRISES

Occupancy: R3 Insp Area: 2 Activity Code: R1 REROOF

Valuation: \$8,400.00 Fees Req: \$212.20 Fees Col: \$212.20 Bal Due: \$0.00

Activity: RES-0901832 Type: Building / Residential / Minor / Single Family

Site Address: 8053 LA RIVIERA DR #Units: 1.00 Sq Ft: 0

Location:

Description: Gas Tankless Water Heater change Out. Subject to field inspection.

Contractor:

Occupancy: R3 Insp Area: 1 Activity Code: P6 WATER HEATER

Valuation: \$999.00 Fees Req: \$84.00 Fees Col: \$84.00 Bal Due: \$0.00

Activity: RES-0901835 Type: Building / Residential / Remodel / Single Family

 Parcel:
 00702310060000
 Applied:
 02/20/2009
 Issued:
 02/20/2009
 Finaled:

 Site Address:
 1334 SANTA YNEZ WAY
 # Units:
 1.00
 Sq Ft:

Location:

Description: Bathroom remodel.

Contractor: KITCHEN MART INC

Occupancy: Insp Area: 1 Activity Code:

Valuation: \$9,270.00 Fees Req: \$632.96 Fees Col: \$632.96 Bal Due: \$0.00

Activity: RES-0901837 Type: Building / Residential / Minor / Duplex

 Parcel:
 03100700740000
 Applied:
 02/20/2009
 Issued:
 02/20/2009
 Finaled:

 Site Address:
 132 FOUNTAINOAKS CIR
 # Units:
 0.00
 Sq Ft:
 0

Location:

Description: DUPLEX UNITS 139,141. T/O 1 STORY 32 SQ'S 50 YR COMP. IN PROGRESS INSPECTION REQUIRED

Contractor: R & R ENTERPRISES

Occupancy: R3 Insp Area: 2 Activity Code: R1 REROOF

Valuation: \$6,720.00 Fees Req: \$207.36 Fees Col: \$207.36 Bal Due: \$0.00

Activity: RES-0901839 Type: Building / Residential / Minor / Duplex

 Parcel:
 03100700740000
 Applied:
 02/20/2009
 Issued:
 02/20/2009
 Finaled:

 Site Address:
 132 FOUNTAINOAKS CIR
 # Units:
 0.00
 Sq Ft:
 0

Location:

Description: DUPLEX UNITS D-10,D-20. T/O 1 STORY 40 SQ'S 50 YR COMP. IN PROGRESS INSPECTION REQUIRED

Contractor: R & R ENTERPRISES

Occupancy: R3 Insp Area: 2 Activity Code: R1 REROOF

Valuation: \$8,400.00 Fees Req: \$212.20 Fees Col: \$212.20 Bal Due: \$0.00

Activity: RES-0901840 Type: Building / Residential / Minor / Duplex

Parcel: 03100700740000 Applied: 02/20/2009 Issued: 02/20/2009 Finaled:

Site Address: 132 FOUNTAINOAKS CIR #Units: 0.00 Sq Ft: 0

Location:

Activity Data Report
City of Sacramento, CA
ISSUED between 02/15/2009 and 02/21/2009

Page 48

Description: DUPLEX UNITS D-30,D-40. T/O 1 STORY 40 SQ'S 50 YR COMP. IN PROGRESS INSPECTION REQUIRED

Contractor: R & R ENTERPRISES

Occupancy: R3 Insp Area: 2 Activity Code: R1 REROOF

Valuation: \$8,400.00 Fees Req: \$212.20 Fees Col: \$212.20 Bal Due: \$0.00

Activity: RES-0901841 Type: Building / Residential / Minor / Single Family

Site Address: 5111 CARMEN WAY #Units: 0.00 Sq Ft: 0

Location:

Description: REROOF. TEAR-OFF. 30 YEAR COMP.

Contractor: CURTIS ROOFING INC

Occupancy: R1 Insp Area: 3 Activity Code: R1 REROOF

Valuation: \$8,700.00 Fees Req: \$212.35 Fees Col: \$212.35 Bal Due: \$0.00

Activity: RES-0901842 Type: Building / Residential / Minor / Duplex

Site Address: 132 FOUNTAINOAKS CIR #Units: 0.00 Sq Ft: 0

Location:

Description: DUPLEX UNITS D-50,D-60. T/O 1 STORY 32 SQ'S 50 YR COMP. IN PROGRESS INSPECTION REQUIRED

Contractor: R & R ENTERPRISES

Occupancy: R3 Insp Area: 2 Activity Code: R1 REROOF

Valuation: \$6,720.00 Fees Req: \$207.36 Fees Col: \$207.36 Bal Due: \$0.00

Activity: RES-0901843 Type: Building / Residential / Minor / Single Family

Site Address: 710 HARTNELL PL #Units: 0.00 Sq Ft: 0

Location:

Description: HVAC CHANGE-OUT. SPLIT SYSTEM. CONDENSOR ONLY.

Contractor: A & P HEATING AND COOLING INC

Occupancy: R1 Insp Area: 1 Activity Code: M1 HEATING/AIR CONDITION

Valuation: \$2,600.00 Fees Req: \$197.04 Fees Col: \$197.04 Bal Due: \$0.00

Activity: RES-0901845 Type: Building / Residential / Minor / Single Family

Site Address: 2948 43RD ST **# Units**: 0.00 **Sq Ft**: 0

Location:

Description: REPLACE SEWER SERVICE.

Contractor: G-L PLUMBING

Occupancy: R1 Insp Area: 3 Activity Code: P2 SEWER SERVICE

Valuation: \$2,200.00 Fees Reg: \$88.88 Fees Col: \$88.88 Bal Due: \$0.00

Activity: RES-0901847 Type: Building / Residential / Minor / Single Family

 Site Address: 4255 65TH ST
 # Units: 0.00
 Sq Ft:
 0

Activity Data Report
City of Sacramento, CA
ISSUED between 02/15/2009 and 02/21/2009

Page 49

Location:

Description: CHANGE OUT. SPLIT SYSTEM. HVAC

Contractor: BRONCO HEATING & AIR

Occupancy: R3 Insp Area: 3 Activity Code: M1 HEATING/AIR CONDITION

Valuation: \$9,590.00 Fees Req: \$213.84 Fees Col: \$213.84 Bal Due: \$0.00

Activity: RES-0901849 Type: Building / Residential / Minor / Single Family

 Site Address:
 1904 28TH ST
 # Units:
 0.00
 Sq Ft:
 0

Location: Description:

Contractor: AIR COMPANY

Occupancy: R3 Insp Area: 1 Activity Code: M1 HEATING/AIR CONDITION

Valuation: \$8,185.00 Fees Req: \$211.27 Fees Col: \$211.27 Bal Due: \$0.00

Activity: RES-0901850 Type: Building / Residential / Housing-Minor / Single Family

Site Address: 6305 GLENHILLS WAY # Units: 0.00 Sq Ft: 1,300

Location:

Description: 08-025823 --- PROVIDE LABELS ON ALL CIRCUTS. REAR PATIOCOVER--PROVIDE LOAD-SUPPORT AT ALL POST. ALL

REPAIRS PER VIOLATIONS LIST. WATER HEATER REPAIRS PROVIDE SERVICE DISCONNECT. REMOVE ALL

UNAPPROVED WIRING.

Contractor:

Occupancy: R3 Insp Area: 3 Activity Code: C4 HOUSING CASES

Valuation: \$999.00 Fees Req: \$84.50 Fees Col: \$84.50 Bal Due: \$0.00

Activity: RES-0901851 Type: Building / Residential / Minor / Single Family

Site Address: 3916 FELL ST # Units: 0.00 Sq Ft: 0

Location:

Description: GAS FURNACE CHANGE OUT

Contractor: KLEENAIR HEATING AND AIR CONDITIONING

Occupancy: R3 Insp Area: 4 Activity Code: M3 FURNACE

Valuation: \$1,750.00 Fees Req: \$86.70 Fees Col: \$86.70 Bal Due: \$0.00

Activity: RES-0901852 Type: Building / Residential / Minor / Single Family

Site Address: 3824 14TH AVE #Units: 0.00 Sq Ft: 0

Location:

Description: UPGRADE PANEL. 100AMP. REWIRE HOUSE.

Contractor: KY'S HOME IMPROVEMENT COMPANY

Occupancy:R1Insp Area:3Activity Code:E10 ELEC EQUIPMENT INSTALLValuation:\$9,000.00Fees Req:\$103.60Fees Col:\$103.60Bal Due:\$0.00

Activity: RES-0901854 Type: Building / Residential / Minor / Single Family

Activity Data Report 02/23/2009 Page 50 City of Sacramento, CA

ISSUED between 02/15/2009 and 02/21/2009

Parcel: 11902000770000 Applied: 02/20/2009 Issued: 02/20/2009 Finaled:

Site Address: 2 MEADOWSTONE CT # Units: 0.00 Sq Ft: 0

Location:

Description: REROOF. TEAR-OFF, RESHEET. 30 YEAR COMP.

Contractor: AVI'S DISCOUNT ROOFING

Occupancy: R1 Insp Area: 2 Activity Code: R1 REROOF

Valuation: \$5,000.00 Fees Req: \$202.50 Fees Col: \$202.50 Bal Due: \$0.00

Activity: RES-0901855 Type: Building / Residential / Minor / Single Family

Parcel: 29503100070000 Applied: 02/20/2009 Issued: 02/20/2009 Finaled:

Site Address: 1222 COMMONS DR # Units: 0.00 Sq Ft: 0

Location:

Description: HVAC PACKAGE ROOF MOUNT CHANGE OUT

Contractor: DUNBAR AIR CONDITIONING HEATING AND REFRIGERATION SERVICE

Activity Code: M1 HEATING/AIR CONDITION Occupancy: R2.3 Insp Area: 1

Valuation: \$7,200.00 Fees Req: \$208.88 Fees Col: \$208.88 Bal Due: \$0.00

Type: Building / Residential / Remodel / Single Family Activity: RES-0901861

Parcel: 01201030070000 Issued: 02/20/2009 Applied: 02/20/2009 Finaled:

Site Address: 2780 RIVERSIDE BLVD # Units: 1 00 Sq Ft: 1,100

Location:

Description: Remodel due to damage, replace cabinets, counters, appliances, minor electrical repair, replace flooring, repair damage in roof,

paint interior. All work subject to field inspection.

Contractor: MID - STATEBUILDERS INC

Occupancy: R3 Insp Area: 2 Activity Code: C3 FIRE REPAIR

Valuation: \$48,000.00 Fees Col: \$1,327.96 Fees Req: \$1,327.96 Bal Due: \$0.00

Type: Building / Residential / Minor / Single Family Activity: RES-0901862

Parcel: 00903020240000 Applied: 02/20/2009 Issued: 02/20/2009 Finaled:

Site Address: 2601 MARTY WAY # Units: 1.00 Sq Ft: 0

Location:

Description: C/O GAS WALL HEATER. INSPECTION OF STARTER PLATE REQUIRED. SMOKE DETECTORS REQUIRED.

Contractor: MC DONALD PLUMBING HEATING & AIR CONDITIONING INC

Occupancy: R3 Insp Area: 2 Activity Code: M3 FURNACE

Valuation: \$2,500.00 Fees Req: \$89.00 Fees Col: \$89.00 Bal Due: \$0.00

Activity: RES-0901868 Type: Building / Residential / Minor / Single Family

Applied: 02/20/2009 Issued: 02/20/2009 Parcel: 29300200050000 Finaled:

Site Address: 307 E RANCH RD # Units: 0.00 Sq Ft: 0

Location:

Description: HVAC CHANGE-OUT. ROOF UNIT. Contractor: AMERICAN ENERGY SAVERS

Occupancy: R1 Activity Code: M1 HEATING/AIR CONDITION Insp Area: 1

Valuation: \$5,340.00 Fees Req: \$204.67 Fees Col: \$204.67 Bal Due: \$0.00

Activity Data Report
City of Sacramento, CA

Page 51

ISSUED between 02/15/2009 and 02/21/2009

Activity: RES-0901875 Type: Building / Residential / Housing-Minor / Single Family

Site Address: 5049 9TH AVE **# Units:** 0.00 **Sq Ft:** 1,100

Location:

Description: PERMIT TO HAVE WORK FINALED EXPIRED PERMIT # RES-081537. PERMIT TO COMPLETE FINAL, PER HOUSING

VIOLATION LIST.

Contractor:

Occupancy: R3 Insp Area: 3 Activity Code: C4 HOUSING CASES

Valuation: \$999.99 Fees Req: \$270.14 Fees Col: \$270.14 Bal Due: \$0.00

Activity: SIG-0815612 Type: Building / Sign / 1-5 / NA

 Parcel:
 01402230030000
 Applied:
 11/19/2008
 Issued:
 02/20/2009
 Finaled:

 Site Address:
 4545 9TH AVE
 # Units:
 0.00
 Sq Ft:

Location:

Description: 1 sign; s/f, attached non-illuminated, copy; Child & Family Institute

Contractor:

Occupancy: Insp Area: 3 Activity Code:

Valuation: \$480.00 Fees Req: \$425.83 Fees Col: \$425.83 Bal Due: \$0.00

Activity: SIG-0901008 Type: Building / Sign / 1-5 / NA

 Parcel:
 03700810250000
 Applied:
 01/29/2009
 Issued:
 02/18/2009
 Finaled:

 Site Address:
 6048 STOCKTON BLVD C
 # Units:
 0.00
 Sq Ft:

Location:

Description: 1 sign, s/f, attached illuminated channel letters, copy Happy Happy

Contractor: ALLIED SIGNS

Occupancy: Insp Area: 3 Activity Code:

Valuation: \$1,400.00 Fees Req: \$389.48 Fees Col: \$389.48 Bal Due: \$0.00

Activity: SIG-0901110 Type: Building / Sign / 1-5 / NA

 Parcel:
 23701400490000
 Applied:
 01/30/2009
 Issued:
 02/20/2009
 Finaled:

 Site Address:
 4220 MAY ST
 # Units:
 0.00
 Sq Ft:

Location:

Description: 1 sign; d/f, detached monument, illuminated sign, copy; Mt Moriah AOH Church of God ---NOTE: EXISTING SIGN TO BE

REMOVED COMPLETELY--Contractor: B - LINE CONSTRUCTION INC

Occupancy: Insp Area: 4 Activity Code:

Valuation: \$1,100.00 Fees Req: \$459.36 Fees Col: \$459.36 Bal Due: \$0.00

Activity: SIG-0901562 Type: Building / Sign / 1-5 / NA

 Parcel: 22510100120000
 Applied: 02/12/2009
 Issued: 02/18/2009
 Finaled: 02/18/2009

 Site Address: 2460 W EL CAMINO AVE
 # Units: 0.00
 Sq Ft:

Location:

Description: 5 signs: 4 signs, s/f, attached illuminated channel letters, copy; Logo & Carl's Jr: 1 sign. d/f, reface existing detached monument

sign, copy; Logo & Carl's Jr ---All directional signs max 4 sq ft w/out advertizing are excempt from permit, but needs electrical

permit for lighting.---

Contractor: NATIONAL SIGN & MARKETING CORPORATION

Occupancy: Insp Area: 4 Activity Code:

Activity Data Report City of Sacramento, CA ISSUED between 02/15/2009 and 02/21/2009

Page 52

 Valuation:
 \$2,783.00
 Fees Req:
 \$439.55
 Fees Col:
 \$439.55
 Bal Due:
 \$0.00